

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised June 10, 2003

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-36463
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Shelley 35 State
8. Well Number 007
9. OGRID Number 023230
10. Pool name or Wildcat Skaggs; Drinkard (57000)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☐ Gas Well ☐ Other ☐ P&A

2. Name of Operator
Tom Brown, Inc.

3. Address of Operator
P O Box 2608, Midland, TX 79702

4. Well Location
Unit Letter P : 660 feet from the South line and 990 feet from the East line
Section 35 Township 19S Range 37E NMPM County Lea

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3594

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1/2/04 Drill 7-7/8" hole to TD @ 7220' TOOH for logs. RU wireline & logged well.

1/3/04 Finish logging well. Notified OCD of PA intent.
Set plug from 7215 to 7115 w/ 40 sx Super H
Set plug from 5400 to 5300 w/ 40 sx Super H
Set plug from 2800 to 2700 w/ 55 sx Class C

1/4/04 Set plug from 1555 to 1430 w/ 60 sx Class C
Re-Set plug from 2557 to 1450 w/ 60 sx Class C
Set plug from 400 to 300 w/ 35 sx cmt
Set plug from 90 to surface w/ 30 sx cmt
Cut off wellhead and install dry hole marker
Clean Pits
Release Rig @ 16:00 CST

Approved as to plugging of the Well Bore.
Liability under bond is retained until
surface restoration is completed.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Diane Kuykendall TITLE Operations Asst / Tech DATE 1/12/04

Type or print name Diane Kuykendall E-mail address: dkuykendall@tombrown.com Telephone No. 432-688-9773

(This space for State use)

APPROVED BY Harry W. Wink TITLE OC FIELD REPRESENTATIVE II / STAFF MANAGER DATE JAN 15 2004
Conditions of approval, if any: