

Office

Energy, Minerals and Natural Resources

June 19, 2008

District I

1625 N French Dr., Hobbs, NM 87240

District II

1301 W. Grand Ave., Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S St Francis Dr., Santa Fe, NM

87505

RECEIVED

OIL CONSERVATION DIVISION

NOV 02 2009 1220 South St. Francis Dr.

HOBBSCOCD Santa Fe, NM 87505

WELL API NO.

30-025-31425

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name:
EUNICE MONUMENT SOUTH UNIT

8. Well Number

#625

9. OGRID Number

005380

10. Pool name or Wildcat

EUNICE MONUMENT; GRAYBURG-SAN ANDRES

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator

XT0 Energy, Inc.

3. Address of Operator

200 N. Loraine, Ste. 800 Midland, TX 79701

4. Well Location

Unit Letter T : 2630' feet from the South line and 10' feet from the West lineSection 4 Township 21S Range 36E NMPM County Lea

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
 TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
 PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
 DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
 COMMENCE DRILLING OPNS. ☐ P AND A ☐
 CASING/CEMENT JOB ☐

This Approval of Temporary
Abandonment Expires 11-3-2014OTHER: Temporary Abandon ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

10/09/09 MIRU PU. RU Wood Group spooler. ND WH & NU BOP. POOH w/tbg & LD TD1750 sub pmp. RD. RU Entech WL RIH w/4.6" OD gauge ring & WL dwn to 3,630'. POOH w/WL & LD gauge ring. RIH w/5-1/2" CIBP, WL & set @ 3,625'. POOH w/WL & LD setting tool. RIH w/4" x 33' cmt dump bailer & dump 20' of cmt on top of CIBP. POOH w/WL & LD dump bailer. RD.

10/12/09 RIH w/116 jts of 2-7/8" J-55 prod tbg & tag 3,612'. RU pmp trk & circ w/65 bbls of pkr fluid. POOH LD w/ttl 119 jts of 2-7/8" J-55 tbg. ND BOP & NU WH. RDMO PU. Call OCD for witness of MIT. Well is TA'd. MIT Chart Attached.

Spud Date:

10/08/09

Rig Release Date:

10/12/09

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

*Kristy Ward*TITLE Regulatory AnalystDATE 10/14/2009

kristy_ward@xtoenergy.com

Type or print name Kristy WardE-mail address: PHONE 432.620.6740

For State Use Only

APPROVED BY

Tony W. Hill

DISTRICT 1 SUPERVISOR

TITLE

DATE

NOV 03 2009

Conditions of Approval (if any)

