

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources
RECEIVED
OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505
NOV 05 2009
HOBBSOCD

Form C-103
June 19, 2008

WELL API NO. 30-025-03494
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. E-392
7. Lease Name or Unit Agreement Name State KT
8. Well Number 24-1
9. OGRID Number 264953
10. Pool name or Wildcat Eumont Yates 7 Rivers Queen
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3,637' KB 3,627' GL

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input checked="" type="checkbox"/>	
2. Name of Operator Herman L. Loeb LLC	
3. Address of Operator P O Box 838 Lawrenceville, IL 62439	
4. Well Location Unit Letter J : 2310 feet from the south line and 1800 feet from the east line Section 24 Township 21S Range 35E NMPM County Lea	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3,637' KB 3,627' GL	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐

OTHER: Temporarily abandon ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. POH w/ rods & tbg, RIH w/ 4 3/4" bit & csg scraper, tag btm @ 3850'. Clean out w/ bailer to 3892'. 9/08-09/9
2. Set CIBP @ 3830', spot 4 sk of cement on plug w/ dump bailer. Set CIBP @ 3490'. 9/14/09
3. Load csg w/ 2% KCl water w/ biocide, pressure test csg to 550# for 40 min w/ no loss in pressure. Test recorded on chart and submitted to NM OCD.

This Approval of Temporary
Abandonment Expires 11-6-2014

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE Petroleum Engineer

DATE 11/02/09

Type or print name G. A. Payne

E-mail address: gapayne@sigecon.net

PHONE: 812.453.0385

For State Use Only

APPROVED BY:

TITLE

DISTRICT 1 SUPERVISOR

DATE

NOV 06 2009

Conditions of Approval (if any):

