

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB No. 1004-0135
Expires November 30, 2000

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well
☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator
John H. Hendrix Corporation

3a. Address
P. O. Box 3040 Midland TX 79702-3040

3b. Phone No. (include area code)
(432)684-6631

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
Unit J, 1650' FSL & 1980' FEL, Section 15, T19S, R32E

5. Lease Serial No.
NM 025497

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.
Jennings "A" Federal #4

9. API Well No.
30-025-27940

10. Field and Pool, or Exploratory Area
Lusk, Bone Spring, East

11. County or Parish, State
Lea County, NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/ Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other <u>P&A Lusk,</u>
	<input type="checkbox"/> Change Plans	<input checked="" type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	<u>Delaware North</u>
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

12/16/03 Set RBP @ 9250'. Set packer at 6035'.
12/17/03 Squeezed perms. 6521 - 6567' w/ 100 sx. Class "C" neat cement. Obtained 3000 psig surface squeeze.
12/19/03 Drld. out cement 6250 - 6630'. Test squeezed to 1000 psig for 30 mins. No leak off. Washed sand fr. RBP at 9250'.
12/20/03 POH w/ RBP.
12/24/03 Ran 2-7/8" tbg. & rods to 9995'.

Well is permanentaly abandoned in the Lusk, Delaware, North Pool. Well is now a Lusk, Bone Spring, East producer.

ACCEPTED FOR RECORD

JAN 12 2004

14. I hereby certify that the foregoing is true and correct
Name (Printed/Typed)

Ronnie H. Westbrook

Title
Vice President

Signature

Date
01/05/2004

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on reverse)

GW