Form 3160-5 (April 2004)

D-HOB WECEIVED

UNITED STATES
DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

NOV 1 13 2009

5 Lease Senal No

LC 031670B

SUNDRY NOTICES AND REPORTS ON WOBSOCD

6	If Indian, Allottee or Tribe Name

abandoned well. Use Form 3160-3 (APD) for such	proposals.
SUBMIT IN TRIPLICATE- Other instructions on re-	
1 Type of Well Gas Well ✓ Other	NMNM 716411 8 Well Name and No
2 Name of Operator ConocoPhillips Company 4TTN: Donna Williams	SEMU # 71 9 API Well No
3a Address 3b Phone No (inc	clude area code) 30-025-07797
P.O. Box 51810 Widland, Texas 79710-1810 432-688-6884 4 Location of Well (Footage, Sec., T, R. M., or Survey Description)	10. Field and Pool, or Exploratory Area Skaggs Drinkard
Unit O 660' FSL & 1830' FEL, Section 18, T-20-S, R-38-E	11 County or Parish, State Lea, New Mexico
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NAT	FURE OF NOTICE, REPORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION
Acidize Deepen Notice of Intent Alter Casing Fracture Treat Casing Repair New Construct Change Plans Final Abandonment Notice Convert to Injection Deepen Fracture Treat New Construct Plug and Aband Plug Back	
13. Describe Proposed or Completed Operation (clearly state all pertinent details, including If the proposal is to deepen directionally or recomplete horizontally, give subsurface lot Attach the Bond under which the work will be performed or provide the Bond No on following completion of the involved operations. If the operation results in a multiple of testing has been completed. Final Abandonment Notices shall be filed only after all recompleted determined that the site is ready for final inspection.) 9/22/09 Sqz 200sxs cmt below pkr @ 6603' 9/23/09 Drill cmt from 6980' to 7266' clean out to CIBP @ 7850' 10/9/09 Circ hole w/ MLF spot 25sxs cmt @ 7850' 10/12/09 Set CIBP @ 7266' Spot 90sxs cmt @ 7266' tag plug @ 6711' 10/13/09 Spot 25sxs cmt @ 5887'-5733' 10/13/09 Perf @ 5370' No injection Rate Spot 25sxs cmt @ 5420' tag plug @ 10/14/09 Perf @ 2877' No injection Rate Spot 30sxs cmt @ 2620' tag plug @ 10/14/09 Perf @ 2570' No injection Rate Spot 30sxs cmt @ 2927' tag plug @ 10/15/09Perf @ 1550' Sqz 40sxs cmt @ 1550' tag plug 1421' 10/15/09 Perf @ 314' Pump 100sxs cmt from314' to surface out of 9 5/8"cs Install Dry Hole Marker	eations and measured and true vertical depths of all pertinent markers and zones file with BLM/BIA. Required subsequent reports shall be filed within 30 days completion or recompletion in a new interval, a Form 3160-4 shall be filed once quirements, including reclamation, have been completed, and the operator has ACCEPTED FOR RECORD 2757; 2925 @ 2757; 2925 @ 2430; 2620 g leave 7 " full of cmt
Accepted as to plugging of the well bore. Liability under bond is retained until Surface restoration is completed.	BURZAU OF LAND MANAGEMENT CARLSBAD FIELD OFFICE
14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)	
1	e Area Manager, P&A Basic Energy Services 432-530-0907
Signature Dat	e 10/29/2009
. THIS SPACE FOR FEDERAL OF	
Approved by Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon Title 18 USC Section 1001 and Title 43 USC Section 1212, make it a crime for any personant states any false; fictitious or fraudulent statements or representations as to any matter with	Office Date NOV 2 0 7009 Office on knowingly and willfully to make to any department or agency of the United