	OL A INCITACE
	JB. 11/23/2009 pctober 13, 2009
District 1	WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 District II District II	30-025-28613
District II 1301 W. Grand Ave., Artesia, No. 120 CONSERVATION DIVISION District III 220 South St. Francis Dr.	5. Indicate Type of Lease STATE X FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505 HOBBSOCO	004762
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	State 27
PROPOSALS.) 1. Type of Well: Oil Well X Gas Well Other	8. Well Number 3
2. Name of Operator	9. OGRID Number
CrownQuest Operating, LLC	213190 10. Pool name or Wildcat
3. Address of Operator 303 Veterans Airpark Lane, STE 5100, PO Box 53310, Midland, TX 79710	TULK ABO TULK PENN
4. Well Location	
Unit Letter A 990 feet from the North line and 1300 feet from the East line	
Section 36 27 Township 138 / 45 Range 33E 32 E NMPM County Lea	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4317' KB	
The state of the s	as a control entering metabolistic statement and proceedings to the control of th
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBS	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	
TEMPORARILY ABANDON	
PULL OR ALTER CASING	JOB []
OTHER: V Locati	on in mode for OCD increasion after DOA
OTHER: OTHER: X Locati	on is ready for OCD inspection after P&A
X All pits have been remediated in compliance with OCD rules and the terms of the Opera	tor's pit permit and closure plan.
 X All pits have been remediated in compliance with OCD rules and the terms of the Opera X Rat hole and cellar have been filled and leveled. Cathodic protection holes have been pro 	tor's pit permit and closure plan. operly abandoned.
 X All pits have been remediated in compliance with OCD rules and the terms of the Opera X Rat hole and cellar have been filled and leveled. Cathodic protection holes have been pro X A steel marker at least 4" in diameter and at least 4' above ground level has been set in c 	tor's pit permit and closure plan. operly abandoned. oncrete. It shows the
X All pits have been remediated in compliance with OCD rules and the terms of the Opera X Rat hole and cellar have been filled and leveled. Cathodic protection holes have been pro X A steel marker at least 4" in diameter and at least 4' above ground level has been set in COPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER	tor's pit permit and closure plan. operly abandoned. oncrete. It shows the
 X All pits have been remediated in compliance with OCD rules and the terms of the Opera X Rat hole and cellar have been filled and leveled. Cathodic protection holes have been pro X A steel marker at least 4" in diameter and at least 4' above ground level has been set in c 	tor's pit permit and closure plan. operly abandoned. oncrete. It shows the
X All pits have been remediated in compliance with OCD rules and the terms of the Opera X Rat hole and cellar have been filled and leveled. Cathodic protection holes have been pro X A steel marker at least 4" in diameter and at least 4' above ground level has been set in COPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS EXPERMANENTLY STAMPED ON THE MARKER'S SURFACE.	tor's pit permit and closure plan. operly abandoned. oncrete. It shows the QUARTER LOCATION OR BEEN WELDED OR
X All pits have been remediated in compliance with OCD rules and the terms of the Opera X Rat hole and cellar have been filled and leveled. Cathodic protection holes have been pro X A steel marker at least 4" in diameter and at least 4' above ground level has been set in COPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS ESPERMANENTLY STAMPED ON THE MARKER'S SURFACE. X The location has been leveled as nearly as possible to original ground contour and has be other production equipment.	tor's pit permit and closure plan. operly abandoned. oncrete. It shows the QUARTER LOCATION OR BEEN WELDED OR ten cleared of all junk, trash, flow lines and
X All pits have been remediated in compliance with OCD rules and the terms of the Opera X Rat hole and cellar have been filled and leveled. Cathodic protection holes have been pro X A steel marker at least 4" in diameter and at least 4" above ground level has been set in COPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS EXPERMANENTLY STAMPED ON THE MARKER'S SURFACE. X The location has been leveled as nearly as possible to original ground contour and has be other production equipment. X Anchors, dead men, tie downs and risers have been cut off at least two feet below ground.	tor's pit permit and closure plan. operly abandoned. oncrete. It shows the QUARTER LOCATION OR BEEN WELDED OR een cleared of all junk, trash, flow lines and
X All pits have been remediated in compliance with OCD rules and the terms of the Opera X Rat hole and cellar have been filled and leveled. Cathodic protection holes have been pro X A steel marker at least 4" in diameter and at least 4" above ground level has been set in COPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS EXPERMANENTLY STAMPED ON THE MARKER'S SURFACE. X The location has been leveled as nearly as possible to original ground contour and has be other production equipment. X Anchors, dead men, tie downs and risers have been cut off at least two feet below ground X If this is a one-well lease or last remaining well on lease, the battery and pit location(s) in the state of the st	tor's pit permit and closure plan. operly abandoned. oncrete. It shows the QUARTER LOCATION OR BEEN WELDED OR een cleared of all junk, trash, flow lines and I level. ave been remediated in compliance with
X All pits have been remediated in compliance with OCD rules and the terms of the Opera X Rat hole and cellar have been filled and leveled. Cathodic protection holes have been pro X A steel marker at least 4" in diameter and at least 4' above ground level has been set in COPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS EXPERMANENTLY STAMPED ON THE MARKER'S SURFACE. X The location has been leveled as nearly as possible to original ground contour and has be other production equipment. X Anchors, dead men, tie downs and risers have been cut off at least two feet below ground X If this is a one-well lease or last remaining well on lease, the battery and pit location(s) if OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production lease and well location.	tor's pit permit and closure plan. operly abandoned. oncrete. It shows the QUARTER LOCATION OR BEEN WELDED OR een cleared of all junk, trash, flow lines and il level. ave been remediated in compliance with ction equipment and junk have been removed
X All pits have been remediated in compliance with OCD rules and the terms of the Opera X Rat hole and cellar have been filled and leveled. Cathodic protection holes have been pro X A steel marker at least 4" in diameter and at least 4' above ground level has been set in a OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS ESPERMANENTLY STAMPED ON THE MARKER'S SURFACE. X The location has been leveled as nearly as possible to original ground contour and has be other production equipment. X Anchors, dead men, tie downs and risers have been cut off at least two feet below ground X If this is a one-well lease or last remaining well on lease, the battery and pit location(s) FOCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production lease and well location. X All metal bolts and other materials have been removed. Portable bases have been removed.	tor's pit permit and closure plan. operly abandoned. oncrete. It shows the QUARTER LOCATION OR BEEN WELDED OR een cleared of all junk, trash, flow lines and il level. ave been remediated in compliance with ction equipment and junk have been removed
X All pits have been remediated in compliance with OCD rules and the terms of the Opera X Rat hole and cellar have been filled and leveled. Cathodic protection holes have been pro X A steel marker at least 4" in diameter and at least 4' above ground level has been set in COPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS EXPERMANENTLY STAMPED ON THE MARKER'S SURFACE. X The location has been leveled as nearly as possible to original ground contour and has be other production equipment. X Anchors, dead men, tie downs and risers have been cut off at least two feet below ground X If this is a one-well lease or last remaining well on lease, the battery and pit location(s) if OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production lease and well location.	tor's pit permit and closure plan. operly abandoned. oncrete. It shows the QUARTER LOCATION OR BEEN WELDED OR een cleared of all junk, trash, flow lines and il level. ave been remediated in compliance with ction equipment and junk have been removed
X All pits have been remediated in compliance with OCD rules and the terms of the Opera X Rat hole and cellar have been filled and leveled. Cathodic protection holes have been pro X A steel marker at least 4" in diameter and at least 4' above ground level has been set in COPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS ESPERMANENTLY STAMPED ON THE MARKER'S SURFACE. X The location has been leveled as nearly as possible to original ground contour and has be other production equipment. X Anchors, dead men, tie downs and risers have been cut off at least two feet below ground X If this is a one-well lease or last remaining well on lease, the battery and pit location(s) Proceed to CCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production lease and well location. X All metal bolts and other materials have been removed. Portable bases have been removed to be removed.) X All other environmental concerns have been addressed as per OCD rules. X Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC.	tor's pit permit and closure plan. operly abandoned. oncrete. It shows the QUARTER LOCATION OR BEEN WELDED OR een cleared of all junk, trash, flow lines and I level. ave been remediated in compliance with ction equipment and junk have been removed d. (Poured onsite concrete bases do not have
X All pits have been remediated in compliance with OCD rules and the terms of the Opera X Rat hole and cellar have been filled and leveled. Cathodic protection holes have been pro X A steel marker at least 4" in diameter and at least 4" above ground level has been set in COPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS ESPERMANENTLY STAMPED ON THE MARKER'S SURFACE. X The location has been leveled as nearly as possible to original ground contour and has be other production equipment. X Anchors, dead men, tie downs and risers have been cut off at least two feet below ground X If this is a one-well lease or last remaining well on lease, the battery and pit location(s) Proceed to CCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production lease and well location. X All metal bolts and other materials have been removed. Portable bases have been removed to be removed.) X All other environmental concerns have been addressed as per OCD rules. X Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. A retrieved flow lines and pipelines.	tor's pit permit and closure plan. operly abandoned. oncrete. It shows the QUARTER LOCATION OR BEEN WELDED OR een cleared of all junk, trash, flow lines and I level. ave been remediated in compliance with ction equipment and junk have been removed d. (Poured onsite concrete bases do not have
X All pits have been remediated in compliance with OCD rules and the terms of the Opera X Rat hole and cellar have been filled and leveled. Cathodic protection holes have been pro X A steel marker at least 4" in diameter and at least 4' above ground level has been set in a OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS EXEMPLED ON THE MARKER'S SURFACE. X The location has been leveled as nearly as possible to original ground contour and has be other production equipment. X Anchors, dead men, tie downs and risers have been cut off at least two feet below ground X If this is a one-well lease or last remaining well on lease, the battery and pit location(s) POCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production lease and well location. X All metal bolts and other materials have been removed. Portable bases have been removed be removed.) X All other environmental concerns have been addressed as per OCD rules. X Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. A retrieved flow lines and pipelines. X I hereby certify that the information above is true and complete to the best of my knowled.	tor's pit permit and closure plan. operly abandoned. oncrete. It shows the QUARTER LOCATION OR EEN WELDED OR een cleared of all junk, trash, flow lines and d level. ave been remediated in compliance with ction equipment and junk have been removed d. (Poured onsite concrete bases do not have All fluids have been removed from non- dge and belief.
X All pits have been remediated in compliance with OCD rules and the terms of the Opera X Rat hole and cellar have been filled and leveled. Cathodic protection holes have been pro X A steel marker at least 4" in diameter and at least 4" above ground level has been set in COPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS ESPERMANENTLY STAMPED ON THE MARKER'S SURFACE. X The location has been leveled as nearly as possible to original ground contour and has be other production equipment. X Anchors, dead men, tie downs and risers have been cut off at least two feet below ground X If this is a one-well lease or last remaining well on lease, the battery and pit location(s) Proceed to CCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production lease and well location. X All metal bolts and other materials have been removed. Portable bases have been removed to be removed.) X All other environmental concerns have been addressed as per OCD rules. X Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. A retrieved flow lines and pipelines.	tor's pit permit and closure plan. operly abandoned. oncrete. It shows the QUARTER LOCATION OR EEN WELDED OR een cleared of all junk, trash, flow lines and d level. ave been remediated in compliance with ction equipment and junk have been removed d. (Poured onsite concrete bases do not have All fluids have been removed from non- dge and belief.
X All pits have been remediated in compliance with OCD rules and the terms of the Opera X Rat hole and cellar have been filled and leveled. Cathodic protection holes have been pro X A steel marker at least 4" in diameter and at least 4' above ground level has been set in a OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS EXEMPLED ON THE MARKER'S SURFACE. X The location has been leveled as nearly as possible to original ground contour and has be other production equipment. X Anchors, dead men, tie downs and risers have been cut off at least two feet below ground X If this is a one-well lease or last remaining well on lease, the battery and pit location(s) POCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production lease and well location. X All metal bolts and other materials have been removed. Portable bases have been removed be removed.) X All other environmental concerns have been addressed as per OCD rules. X Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. A retrieved flow lines and pipelines. X I hereby certify that the information above is true and complete to the best of my knowled.	tor's pit permit and closure plan. operly abandoned. oncrete. It shows the QUARTER LOCATION OR BEEN WELDED OR een cleared of all junk, trash, flow lines and I level. ave been remediated in compliance with ction equipment and junk have been removed d. (Poured onsite concrete bases do not have all fluids have been removed from non- dge and belief. dule an inspection.
X All pits have been remediated in compliance with OCD rules and the terms of the Opera X Rat hole and cellar have been filled and leveled. Cathodic protection holes have been pro X A steel marker at least 4" in diameter and at least 4 above ground level has been set in a OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS EPERMANENTLY STAMPED ON THE MARKER'S SURFACE. X The location has been leveled as nearly as possible to original ground contour and has beother production equipment. X Anchors, dead men, tie downs and risers have been cut off at least two feet below ground X If this is a one-well lease or last remaining well on lease, the battery and pit location(s) in OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production lease and well location. X All metal bolts and other materials have been removed. Portable bases have been removed to be removed.) X All other environmental concerns have been addressed as per OCD rules. X Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. A retrieved flow lines and pipelines. X I hereby certify that the information above is true and complete to the best of my knowled. SIGNATURE TITLE Manager of Special Project Type or print name Don Rogers. E-mail address: drogers@crownque.	tor's pit permit and closure plan. operly abandoned. oncrete. It shows the QUARTER LOCATION OR BEEN WELDED OR een cleared of all junk, trash, flow lines and I level. ave been remediated in compliance with ction equipment and junk have been removed d. (Poured onsite concrete bases do not have all fluids have been removed from non- dge and belief. dule an inspection. DATE 11 19 09
X All pits have been remediated in compliance with OCD rules and the terms of the Opera X Rat hole and cellar have been filled and leveled. Cathodic protection holes have been pro X A steel marker at least 4" in diameter and at least 4" above ground level has been set in COPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS ESPERMANENTLY STAMPED ON THE MARKER'S SURFACE. X The location has been leveled as nearly as possible to original ground contour and has be other production equipment. X Anchors, dead men, tie downs and risers have been cut off at least two feet below ground X If this is a one-well lease or last remaining well on lease, the battery and pit location(s) in COCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production lease and well location. X All metal bolts and other materials have been removed. Portable bases have been removed to be removed.) X All other environmental concerns have been addressed as per OCD rules. X Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. A retrieved flow lines and pipelines. X I hereby certify that the information above is true and complete to the best of my knowled. Hereby certify that the information above is true and complete to the best of my knowled. TITLE Manager of Special Project. Type or print name Don Rogers E-mail address: drogers@crownque.	tor's pit permit and closure plan. operly abandoned. oncrete. It shows the QUARTER LOCATION OR BEEN WELDED OR een cleared of all junk, trash, flow lines and d level. ave been remediated in compliance with ction equipment and junk have been removed d. (Poured onsite concrete bases do not have All fluids have been removed from non- dge and belief. dule an inspection. DATE 11 19 09 est.com PHONE: 432 818 0300
X All pits have been remediated in compliance with OCD rules and the terms of the Opera X Rat hole and cellar have been filled and leveled. Cathodic protection holes have been pro X A steel marker at least 4" in diameter and at least 4 above ground level has been set in a OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS EPERMANENTLY STAMPED ON THE MARKER'S SURFACE. X The location has been leveled as nearly as possible to original ground contour and has beother production equipment. X Anchors, dead men, tie downs and risers have been cut off at least two feet below ground X If this is a one-well lease or last remaining well on lease, the battery and pit location(s) in OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production lease and well location. X All metal bolts and other materials have been removed. Portable bases have been removed to be removed.) X All other environmental concerns have been addressed as per OCD rules. X Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. A retrieved flow lines and pipelines. X I hereby certify that the information above is true and complete to the best of my knowled. SIGNATURE TITLE Manager of Special Project Type or print name Don Rogers. E-mail address: drogers@crownque.	tor's pit permit and closure plan. operly abandoned. oncrete. It shows the QUARTER LOCATION OR BEEN WELDED OR een cleared of all junk, trash, flow lines and I level. ave been remediated in compliance with ction equipment and junk have been removed d. (Poured onsite concrete bases do not have All fluids have been removed from non- dge and belief. dule an inspection. DATE 11 19