Submit 1 Copy To Appropriate District Office District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Ave., Artesia, NM 88210 District III 1000 Rio Brazos Rd., Aztec, NM 87410 District IV  Santa Fe, NM 87505	WELL API NO. 30-025-22395  5. Indicate Type of Lease STATE X FEE   6. State Oil & Gas Lease No.
District IV 1220 S. St. Francis Dr., Santa Fe, NM NOV 20 2009	K 1318
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)  1. Type of Well: Oil Well X Gas Well  Other	<ul> <li>7. Lease Name or Unit Agreement Name</li> <li>State 5</li> <li>8. Well Number 2</li> </ul>
2. Name of Operator	9. OGRID Number
CrownQuest Operating, LLC  3. Address of Operator  303 Veterans Airpark Lane, STE 5100, PO Box 53310, Midland, TX 79710	213190 10. Pool name or Wildcat Baum Upper PENN
4. Well Location	
Unit Letter B 660 feet from the North line and 1980 feet from the East line	
Section 5 / Township 14S Range 33E NMP  11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   TEMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRILL OR ALTER CASING   MULTIPLE COMPL   CASING/CEMENT DOWNHOLE COMMINGLE	LING OPNS. P AND A
OTHER: OTHER: X Locati	on is ready for OCD inspection after P&A
OTHER: X Location X All pits have been remediated in compliance with OCD rules and the terms of the Opera X Rat hole and cellar have been filled and leveled. Cathodic protection holes have been prox A steel marker at least 4" in diameter and at least 4" above ground level has been set in COPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS I	tor's pit permit and closure plan. operly abandoned. oncrete. It shows the
X All pits have been remediated in compliance with OCD rules and the terms of the Opera X Rat hole and cellar have been filled and leveled. Cathodic protection holes have been pro X A steel marker at least 4" in diameter and at least 4" above ground level has been set in COPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS I PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	tor's pit permit and closure plan. operly abandoned. concrete. It shows the QUARTER LOCATION OR BEEN WELDED OR
X All pits have been remediated in compliance with OCD rules and the terms of the Opera X Rat hole and cellar have been filled and leveled. Cathodic protection holes have been pro X A steel marker at least 4" in diameter and at least 4" above ground level has been set in COPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS I PERMANENTLY STAMPED ON THE MARKER'S SURFACE.  X The location has been leveled as nearly as possible to original ground contour and has beother production equipment. X Anchors, dead men, tie downs and risers have been cut off at least two feet below ground X If this is a one-well lease or last remaining well on lease, the battery and pit location(s) hoch occurred the operator's pit permit and closure plan. All flow lines, production lease and well location.	tor's pit permit and closure plan. operly abandoned. oncrete. It shows the  QUARTER LOCATION OR BEEN WELDED OR  een cleared of all junk, trash, flow lines and I level. ave been remediated in compliance with ction equipment and junk have been removed
X All pits have been remediated in compliance with OCD rules and the terms of the Opera X Rat hole and cellar have been filled and leveled. Cathodic protection holes have been pro X A steel marker at least 4" in diameter and at least 4" above ground level has been set in COPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS I PERMANENTLY STAMPED ON THE MARKER'S SURFACE.  X The location has been leveled as nearly as possible to original ground contour and has be other production equipment. X Anchors, dead men, tie downs and risers have been cut off at least two feet below ground X If this is a one-well lease or last remaining well on lease, the battery and pit location(s) he OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production lease and well location. X All metal bolts and other materials have been removed. Portable bases have been removed to be removed.)	tor's pit permit and closure plan. operly abandoned. oncrete. It shows the  QUARTER LOCATION OR BEEN WELDED OR  een cleared of all junk, trash, flow lines and I level. ave been remediated in compliance with ction equipment and junk have been removed
X All pits have been remediated in compliance with OCD rules and the terms of the Opera X Rat hole and cellar have been filled and leveled. Cathodic protection holes have been pro X A steel marker at least 4" in diameter and at least 4' above ground level has been set in COPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS I PERMANENTLY STAMPED ON THE MARKER'S SURFACE.  X The location has been leveled as nearly as possible to original ground contour and has be other production equipment. X Anchors, dead men, tie downs and risers have been cut off at least two feet below ground X If this is a one-well lease or last remaining well on lease, the battery and pit location(s) he OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production lease and well location. X All metal bolts and other materials have been removed. Portable bases have been removed to be removed.) X All other environmental concerns have been addressed as per OCD rules. X Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. A	tor's pit permit and closure plan. Operly abandoned. Oncrete. It shows the  QUARTER LOCATION OR BEEN WELDED OR  Den cleared of all junk, trash, flow lines and d level. The average been remediated in compliance with control equipment and junk have been removed d. (Poured onsite concrete bases do not have
X All pits have been remediated in compliance with OCD rules and the terms of the Opera X Rat hole and cellar have been filled and leveled. Cathodic protection holes have been pro X A steel marker at least 4" in diameter and at least 4' above ground level has been set in COPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS I PERMANENTLY STAMPED ON THE MARKER'S SURFACE.  X The location has been leveled as nearly as possible to original ground contour and has be other production equipment. X Anchors, dead men, tie downs and risers have been cut off at least two feet below ground X If this is a one-well lease or last remaining well on lease, the battery and pit location(s) he OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production lease and well location. X All metal bolts and other materials have been removed. Portable bases have been removed to be removed.) X All other environmental concerns have been addressed as per OCD rules. X Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. A retrieved flow lines and pipelines.	tor's pit permit and closure plan. operly abandoned. concrete. It shows the  QUARTER LOCATION OR BEEN WELDED OR  een cleared of all junk, trash, flow lines and I level. ave been remediated in compliance with ction equipment and junk have been removed d. (Poured onsite concrete bases do not have
X All pits have been remediated in compliance with OCD rules and the terms of the Opera X Rat hole and cellar have been filled and leveled. Cathodic protection holes have been pro X A steel marker at least 4" in diameter and at least 4' above ground level has been set in COPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS I PERMANENTLY STAMPED ON THE MARKER'S SURFACE.  X The location has been leveled as nearly as possible to original ground contour and has be other production equipment.  X Anchors, dead men, tie downs and risers have been cut off at least two feet below ground X If this is a one-well lease or last remaining well on lease, the battery and pit location(s) he OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production lease and well location.  X All metal bolts and other materials have been removed. Portable bases have been removed to be removed.)  X All other environmental concerns have been addressed as per OCD rules.  X Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. A retrieved flow lines and pipelines.  X I hereby certify that the information above is true and complete to the best of my knowless.	tor's pit permit and closure plan. operly abandoned. concrete. It shows the  QUARTER LOCATION OR BEEN WELDED OR  een cleared of all junk, trash, flow lines and I level. ave been remediated in compliance with ction equipment and junk have been removed d. (Poured onsite concrete bases do not have all fluids have been removed from non- dge and belief.
X All pits have been remediated in compliance with OCD rules and the terms of the Opera X Rat hole and cellar have been filled and leveled. Cathodic protection holes have been pro X A steel marker at least 4" in diameter and at least 4' above ground level has been set in COPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS I PERMANENTLY STAMPED ON THE MARKER'S SURFACE.  X The location has been leveled as nearly as possible to original ground contour and has be other production equipment. X Anchors, dead men, tie downs and risers have been cut off at least two feet below ground X If this is a one-well lease or last remaining well on lease, the battery and pit location(s) he OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production lease and well location. X All metal bolts and other materials have been removed. Portable bases have been removed to be removed.) X All other environmental concerns have been addressed as per OCD rules. X Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. A retrieved flow lines and pipelines.	tor's pit permit and closure plan. Operly abandoned. Oncrete. It shows the  QUARTER LOCATION OR BEEN WELDED OR  The cleared of all junk, trash, flow lines and all level. The ave been remediated in compliance with cition equipment and junk have been removed and. (Poured onsite concrete bases do not have all fluids have been removed from non-dige and belief.  dule an inspection.
X All pits have been remediated in compliance with OCD rules and the terms of the Opera X Rat hole and cellar have been filled and leveled. Cathodic protection holes have been pro X A steel marker at least 4" in diameter and at least 4' above ground level has been set in a OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS PERMANENTLY STAMPED ON THE MARKER'S SURFACE.  X The location has been leveled as nearly as possible to original ground contour and has beother production equipment. X Anchors, dead men, tie downs and risers have been cut off at least two feet below ground X If this is a one-well lease or last remaining well on lease, the battery and pit location(s) in OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production lease and well location. X All metal bolts and other materials have been removed. Portable bases have been removed to be removed.) X All other environmental concerns have been addressed as per OCD rules. X Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. A retrieved flow lines and pipelines. X I hereby certify that the information above is true and complete to the best of my knowled.	tor's pit permit and closure plan. Operly abandoned. Oncrete. It shows the  QUARTER LOCATION OR BEEN WELDED OR  The cleared of all junk, trash, flow lines and all level. The average been remediated in compliance with cition equipment and junk have been removed and. (Poured onsite concrete bases do not have all fluids have been removed from non-dige and belief.  DATE 11 19 07