District II 1301 W Grand District III 1000 Rio Braz District IV 1220 S. St Fra	ancis Dr , Santa	ia, NM 88 NM 874 Fe, NM 8	<b>ULU</b> 1 7505	IVED 4 2009 SOCD	y Mineral Dil Conso 1220 Sou Santa	ervation 1th St. Fra Fe, NM 8	tural Reso Division ancis Dr. 87505	ources S		Form C-101 June 16, 2008 Priate District Office MENDED REPORT
	ATION FC			DRILL,	NE-END	1 BK, D1	5151 151 <b>\</b> ,			
120021		1 (	Operator Name a		AL			147179	<sup>2</sup> OGRID Numbe	r
			P.O Box 1	8496					<sup>3</sup> API Number	
<sup>3</sup> Proper	ty Code		ahoma City, OK	73154-0496	<sup>5</sup> Property N	Vame		30 -025- 364	475 <sup>6</sup> We	
-	24402				Boyce 1					5
			oposed Pool 1 , Permo-Upper F	Penn				<sup>10</sup> Propo	osed Pool 2	
<sup>7</sup> Surface	Location		,							
UL or lot no B		wnship 16S	Range 35E	Lot Idn	Feet fro 330		North/South North	Feet from the 1650'	East/West line East	County Lea
<sup>8</sup> Proposed I	Bottom Hole	Locatio	n If Different	From Surfa	ice			1		· · · · · · · · · · · · · · · · · · ·
UL or lot no	Section To	wnship	Range	Lot Idn	Feet fio	m the N	orth/South line	Feet from the	East/West line	County
	ıl Well İnfo	ormatic						14	15.0	
	Type Code P		<sup>12</sup> Well Type Cod O	e	<sup>13</sup> Cable F			<sup>14</sup> Lease Type Code P	- Gio	und Level Elevation 3991' GR
	ultiple		<sup>17</sup> Proposed Dept	h	<sup>18</sup> For			<sup>19</sup> Contractor TBD		<sup>20</sup> Spud Date Pending
]	N	1	PBTD 11,365'	<u> </u>	Permo-Uj					
<sup>21</sup> Propose	ed Casing a	and Ce	ment Progi	am	εx	15710	٩۵			
Hole St			g Size	Casing we			ngDepth	Sacks of Ce	ement	Estimated TOC
17 1/2	2,37		3/8"	48			49'	450 s?		0'
11"			//8"	32			<u>200'</u> ,800'	<u>1150 s</u> 880 sz		<u>0'</u> 3900'
7 7/8	5	5	/2''	17 &	20#	11	,800	000 3/	13	
<sup>22</sup> Describe th Describe the	ne proposed pro blowout preven	gram If t tion progr	his application am, if any. Use	is to DEEPEN additional she	or PLUG B/	\CK, give th ary	e data on the	present productive z	one and proposed	new productive zone
							C-102 and C-	144(CLEZ) pit perm	iit	
Please find ou	ir work procedu		inplete this wear	to the reality	opper i enn,	ninoed st		r (ceee) pri porm		
							******	A Stoome Dunn	n Annraval	l
						Permit	Expires to Unless	2 Venrs Fron Deilling Und	derway	L
						Da	ac attes:	Plegb	ack	
								1 and 1		
			given above is t	true and compl	ete to the			CONSERVA		NON
best of my kn	lowledge and be	elief.		. /	1			CONSERVA		
Signature		$\square$			1	Approved	by	21/	/	
		Bry	n /	luip	1			May		
Printed name	Bryan Arrant			·		Title	PETROLI	ETH ENGINE	<b>11</b>	
Title Senior Regulatory Compliance Specialist				Approval	Date DEC	1 5 2009 <sup>1</sup>	Expiration Date			
E-mail Addre	ess bryan arran	t@chk co	m					<u> </u>		
			Phone (405)	035-2782	<u></u>	Condition	s of Approval	Attached		
Date 12/11/	20009		Filone (405)		_	Condition	s or Approval			

District I					State of	Nev	ew Mexico Forr				n C-102	
1625 N. French Dr., Hobbs, NM 88240				A CONT	Mainerals & Natural Resources Department				Revised October 15,2009		15,2009	
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> 1301 W Grand Avenue, Artesia, NM 88210 OIL CONSERVATION DIVISION						Subr	mit one a	opy to app	ropriate			
	venue, Artes	ad, 14141 002.10				V / \ I		IN	040			
District III DEC 1 4 2009 1220 South St. Francis Dr. /										Unice		
District IV	KO., AZIEC, N		)BR2(				M 87505		ſ		NDED R	
1220 S. St. Francis	e Dr. Sonto			JUU	Cantar	С, Т	101 07 000		i			
	s Di., Gailta	•							۸ <del>-</del> -			
······						ACR	EAGE DEDIC					
	API Numbe	r		² Pool Co	xde			<sup>3</sup> Pool Na	ame			
30-025-3647	5		5984	7	ć	Том	Townsend; Permo-Upper Penn.					
<sup>4</sup> Property (	Code				<sup>5</sup> Property Name					<sup>6</sup> Well Number		
24402		Boyce 15								5		
<sup>7</sup> OGRID I	No.				<sup>8</sup> Operator Name						<sup>e</sup> Elevation	
147179		Chesapeal	ke Operat	ing, Inc.						3991' (	GR	
					<sup>10</sup> Sur	face	Location			I		
UL or lot no.	Section	Township	Range	Lot Id	-to ty illustration	om the		Feet from the	Eas	t/West line		County
В	15	16S	35E		330'		North	1650'	East		Lea	
	<sup>11</sup> Bottom Hole Location If Different From Surface											
UL or lot no Section Township		Range	Lotid				Feet from the	Eas	t/West line		County	
<sup>12</sup> Dedicated Acres	s <sup>13</sup> Joint o	r Infill 14 Co	onsolidation	Code 15 (	Order No				L		•••••	
40	1											

No allowable will be assigned to this completion until all interests have been consolidated or a non-standard unit has been approved by the division.

16	1	<u> </u>		
		330' FNL		<sup>17</sup> OPERATOR CERTIFICATION
		ш <b>ј</b>		I hereby certify that the information contained herein is true and complete to the
		330	1650' FEL	best of my knowledge and belief and that this organization either owns a
		.,		working interest or unleased minoral interest in the land including the proposed
				bottom hole location or has a right to drill this well at this location pursuant to
			· -	a contract with an owner of such a mineral or working interest, or to a
				voluntary pooling agreement or a compulsory poolypg order heretofore entered
				by the division
			ŀ	12/11/2000
				Mey king 12/11/2009
				Sgnature Date
				Bryan Arrant
				Printed Name
				<sup>18</sup> SURVEYOR CERTIFICATION
				I hereby certify that the well location shown on this plat was
				plotted from field notes of actual surveys made by me or under
				my supervision, and that the same is true and correct to the
				best of my belief
				Date of Survey
				Signature and Seal of Professional Surveyor
				Please Refer to Original Plat
				Certificate Number



#### Boyce #5-15 Permo-Penn and Wolfcamp Recompletion Lea County, NM

# **Current Wellbore Information**

#### TD: 11,800' PBTD: 11,365'

Casing	م الم الم الم الم الم الم الم الم الم ال	⊵_Weight	Grade	Depth Set	TOC
Surface	13-3/8"	48#	H-40	449'	Surface
Intermediate	8-5/8"	32#	J-55	4,200'	Surface
Production	5-1/2"	17# & 20#	L-80	11,800'	3,900'

Perfs	Top Perf	Bottom Perf.	Status	SPF	Total Holes
Atoka	11,450'	11,460'	Abandoned	4	40
Atoka	11,498'	11,508'	Abandoned	4	40
Atoka	11,630'	11,640'	Abandoned	4	40

OIH	Size	Location
DV tool	NA	7,988'
CIBP w/ 35' cement	5-1/2"	11,365'

# GL: 3,991' KB: 15' KB Height: 4,006'

### Procedure

Hold Pre-Job Safety Assessment (PJSA) meeting prior to beginning work each morning and as required for specific operations.

- 1. Prep location. Check anchors and clean area for workover.
- 2. Rack and tally work string consisting of 11,365' (379 joints) of 2-7/8, 6.5#, L-80 tubing.
- 3. MIRU workover rig. ND WH. NU BOP.
- 4. RU wireline unit. RIH w/ bit and scraper to 11,365'. POH.
- 5. Test casing to 7,000# for 15 minutes to test casing integrity.
- 6. RU loggers and log from 11,000' to 3,800'. Run CBL, CCL, and GR. RDMO loggers.
- Install lubricator. MU Select Fire Perforating Guns loaded w/ 28 shots @ 4 spf w/ 60 degree phasing (23 g minimum charges) and RIH. Correlate to the log ran in Step #6 and perforate the Permo-Penn as follows:

Formation	Interval	SPF	Total Shots
Permo-Penn	10,830'	4 spf	4
Permo-Penn	10,816'	4 spf	4
Permo-Penn	10,812'	4 spf	4
Permo-Penn	10,808'	4 spf	4
Permo-Penn	10,768'	4 spf	4
Permo-Penn	10,766'	4 spf	4
Permo-Penn	10,758'	4 spf	4
Total	72'		/28 /

POOH w/ tubing and perforating guns and verify all shots fired. RDMO Wireline.

.

- 8. RD Lubricator and install frac valve. RU Treating Company and pump a total of 5,000 gallons of 15% NEFE acid dropping 42 perf balls throughout the job. Flush acid to bottom perf w/ 2% KCL. SI and wait 1 hour. See attached acid procedure.
- 9. RIH w/ bit to PBTD @ 11,365' to clear perfs.
- RU frac service and frac the Permo-Penn perfs 10,758' 10,830' (28 holes). Frac per attached procedure. (5-1/2", 17# & 20#, L-80, Internal Yield = 7,740 psi) Record ISIP-5-10-15 min pressures.
- 11. RU Lubricator. RU wireline and RIH and set CBP @ +/-10,458'. POH.
- 12. MU Select Fire Perforating Guns loaded w/ 8 shots @ 4 spf w/ 60 degree phasing (23 g minimum charges) and RIH. Correlate to the log ran in Step #6 and perforate the Wolfcamp as follows:

Formation	Interval	SPF	Total Shots
Wolfcamp	10,148'	4 spf	4
Wolfcamp	10,146'	4 spf	4
Total	2'		8

POOH w/ tubing and perforating guns and verify all shots fired. RDMO Wireline.

- 13. RD Lubricator and RIH w/ packer and tubing and pump a total of 5,000 gallons of 15% NEFE acid. SI and wait 1 hour. See attached acid procedure. Swab well to determine productivity and if a larger acid job is necessary. RD swab. Release packer and POH w/ tubing and packer.
- 14. PU bit, drill collars and workstring and DO CBP @ +/- 10,458' and clean out to PBTD @ 11,365'. Circulate hole clean. TOH.
- 15. TIH with production tubing and SN. Set seat nipple at 10,880' (below perfs).
- 16. ND BOP. NU WH. TIH with pump and rods. Fill tubing and space out pump accordingly. Verify pump action. Place well on test.
- 17. RDMO workover rig. Clean location.

# **Contacts**

Production Foreman Steve Serna Office: 575-391-1462 Cell: 575-390-9053 Asset Manager Kim Henderson Office: 405-935-8583 Cell: 405-312-1840