Submit 1 Copy To Appropriate District Office	State of New Mexico	Form C-103
District Ener	gy, Minerals and Natural Resources	October 13, 2009
1625 N. French Dr., Hobbs, NM		WELL API NO. 30-025-04879
1301 W. Grand Ave., Artesia, NM 88210 OTE CONSERVATION DIVISION		5. Indicate Type of Lease
District III DEC 22 2009 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410 South St. Francis Dr.		STATE X FEE
District IV 1220 S St. Francis Dr., Santa Fe, NM	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		7. Lease Name or Unit Agreement Name Pech State
PROPOSALS) 1. Type of Well: Oil Well X Gas Well		8. Well Number 1
2. Name of Operator Chesapeake Operating, Inc.		9. OGRID Number / 147179
3. Address of Operator P.O. Box 18496 Oklahoma City, OK 73154-0496		10. Pool name or WildcatEunice; Seven Rivers-Queen, South
4. Well Location		
Unit Letter L : 1650' feet from the South line and 990' feet from the West line		
Section 32	Township 21S Range 36E	NMPM CountyLea
11. Elevation <i>(Show whether DR, RKB, RT, GR, etc.)</i> 3631' GR		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
		RK 🗌 ALTERING CASING 🗌
TEMPORARILY ABANDON 🔲 CHANGE PLANS 🔲 COMMENCE DRILLING OPNS 🗌 P AND A 🛛 🕅		
		IT JOB
OTHER.	OTHER [.]	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.		
Please find the work performed in the plug & abandonment of this well from 12/16/09 through 12/18/09.		
12/16/09: MIRU PU. POOH w/ rods & pump. NDWH & NUBOP. SISD.		
12/17/09: POOH w/tbg. RIH, Pump 100 sxs of cmt 3742'-2649'. POOH, RIH & tag plug @ 2587'. Circ brine & plugging mud. POOH,		
RIH w/WL & perf @ 1750'. Set pkr 1360'. Sqz 40 sxs cmt 1750' to 1550'. SISD.		
12/18/09: Release pkr. POOH, RIH & tag plug @ 1613'. Perf @ 1582'. Load hole, set pkr @ 1175'. Sqz 40 sxs cmt 1582'-1482'. WOC. Release pkr, POOH. Tag plug @ 1430'. Perf @ 400'. NDBOP. Set pkr @ 30'. Circ 100 sxs cmt 400' to surface. RDMO. Well P&A'd on 12/18/09. Turn well over to production for final clean up.		
	Liabil	wed for plugging of well bore only. ity under bond is retained pending receipt
	of C-1	03 (Subsequent Report of Well Plugging) may be found at OCD Web Page under
	Form	www.emnfd.state.nm.us/ocd.
Spud Date:	Rig Release Date:	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNATURE /// TITLE Senior Regulatory Compl. Sp. DATE 12/21/2009		
Type or print name Bryan Arrant E-mail address: bryan.arrant@chk.com PHONE: (405)935-3782		
		RVISOR DEC 2 3 2009
APPROVED BY: Conditions of Approval (if any):	TITLE	DATE
V		