1)11/4	OF TO PELEKE
Submit I Copy To Appropriate District Office District I Energy, Minerals and Natural Resources	12/22/2006 Form C-103
Office District I Energy, Minerals and Natural Resources	WELL API NO. October 13, 2009
1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Ave., Artesia, NM 88240 CONSERVATION DIVISION	30-025-28807 /
District III 1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 8700 2U ZUU9 Santa Fe NM 87505	STATE X FEE
District IV 1220 S. St. Francis Dr., Santa Fe, NMBBSOCD 87505	6. State Oil & Gas Lease No. K 1318
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	State 5
PROPOSALS.) 1. Type of Well: Oil Well X Gas Well Other	8. Well Number 3
2. Name of Operator	9. OGRID Number
CrownQuest Operating, LLC	213190
3. Address of Operator 303 Veterans Airpark Lane, STE 5100, PO Box 53310, Midland, TX 79710	10. Pool name or Wildcat Baum Upper Penn
4. Well Location	
Unit Letter A990 feet from the North line and 660feet from the East line	
Section 5 Township 14S Range 33E NMP	M County Lea
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4248 GR	
The state of the s	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	
TEMPORARILY ABANDON	
PULL OR ALTER CASING	
DOWNHOLE COMMINGLE	
OTHER: OTHER: X Locati	on is ready for OCD inspection after P&A
 X All pits have been remediated in compliance with OCD rules and the terms of the Opera X Rat hole and cellar have been filled and leveled. Cathodic protection holes have been pro 	tor's pit permit and closure plan. operly abandoned.
X All pits have been remediated in compliance with OCD rules and the terms of the Opera	tor's pit permit and closure plan. operly abandoned.
X All pits have been remediated in compliance with OCD rules and the terms of the Operat X Rat hole and cellar have been filled and leveled. Cathodic protection holes have been pro X A steel marker at least 4" in diameter and at least 4' above ground level has been set in complex of the Operator Name, Lease Name, Well number, Api number, Quarter	tor's pit permit and closure plan. operly abandoned. oncrete. It shows the
X All pits have been remediated in compliance with OCD rules and the terms of the Operat X Rat hole and cellar have been filled and leveled. Cathodic protection holes have been pro X A steel marker at least 4" in diameter and at least 4' above ground level has been set in complex of the operation of the Operat X A steel marker at least 4" in diameter and at least 4' above ground level has been set in complex of the Operat X A steel marker at least 4" in diameter and at least 4' above ground level has been set in complex of the Operat X A steel marker at least 4" in diameter and at least 4' above ground level has been set in complex of the Operat X A steel marker at least 4" in diameter and at least 4' above ground level has been set in complex of the Operat X A steel marker at least 4" in diameter and at least 4' above ground level has been set in complex of the Operat X A steel marker at least 4" in diameter and at least 4' above ground level has been set in complex of the Operat X A steel marker at least 4" in diameter and at least 4' above ground level has been set in complex of the Operat X A steel marker at least 4" in diameter and at least 4' above ground level has been set in complex of the Operat X A steel marker at least 4" in diameter and at least 4' above ground level has been set in complex of the Operat X A steel marker at least 4" in diameter and at least 4' above ground level has been set in complex of the Operat X A steel marker at least 4" above ground level has been set in complex of the Operat X A steel marker at least 4" above ground level has been set in complex of the Operat X A steel marker at least 4" above ground level has been set in complex of the Operat X A steel marker at least 4" above ground level has been set in complex of the Operat X A steel marker at least 4" above ground level has been set in complex of the Operat X A steel marker at least 4" above ground level has been set in complex of the Operat X A steel marker at least 4" above ground level has been set in complex of the	tor's pit permit and closure plan. operly abandoned. oncrete. It shows the
X All pits have been remediated in compliance with OCD rules and the terms of the Operat X Rat hole and cellar have been filled and leveled. Cathodic protection holes have been pro X A steel marker at least 4" in diameter and at least 4' above ground level has been set in COPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS E PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	tor's pit permit and closure plan. operly abandoned. oncrete. It shows the QUARTER LOCATION OR BEEN WELDED OR
X All pits have been remediated in compliance with OCD rules and the terms of the Operat X Rat hole and cellar have been filled and leveled. Cathodic protection holes have been pro X A steel marker at least 4" in diameter and at least 4' above ground level has been set in COPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER, UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS E PERMANENTLY STAMPED ON THE MARKER'S SURFACE. X The location has been leveled as nearly as possible to original ground contour and has been	tor's pit permit and closure plan. operly abandoned. oncrete. It shows the QUARTER LOCATION OR BEEN WELDED OR
X All pits have been remediated in compliance with OCD rules and the terms of the Operat X Rat hole and cellar have been filled and leveled. Cathodic protection holes have been pro X A steel marker at least 4" in diameter and at least 4" above ground level has been set in COPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS E PERMANENTLY STAMPED ON THE MARKER'S SURFACE. X The location has been leveled as nearly as possible to original ground contour and has be other production equipment. X Anchors, dead men, tie downs and risers have been cut off at least two feet below ground.	tor's pit permit and closure plan. operly abandoned. oncrete. It shows the QUARTER LOCATION OR BEEN WELDED OR een cleared of all junk, trash, flow lines and
X All pits have been remediated in compliance with OCD rules and the terms of the Operat X Rat hole and cellar have been filled and leveled. Cathodic protection holes have been prox A steel marker at least 4" in diameter and at least 4" above ground level has been set in a OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS E PERMANENTLY STAMPED ON THE MARKER'S SURFACE. X The location has been leveled as nearly as possible to original ground contour and has be other production equipment. X Anchors, dead men, tie downs and risers have been cut off at least two feet below ground X If this is a one-well lease or last remaining well on lease, the battery and pit location(s) has been set in a contract of the contract of	tor's pit permit and closure plan. operly abandoned. oncrete. It shows the QUARTER LOCATION OR EEN WELDED OR een cleared of all junk, trash, flow lines and il level. ave been remediated in compliance with
X All pits have been remediated in compliance with OCD rules and the terms of the Operat X Rat hole and cellar have been filled and leveled. Cathodic protection holes have been prox A steel marker at least 4" in diameter and at least 4' above ground level has been set in a OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS E PERMANENTLY STAMPED ON THE MARKER'S SURFACE. X The location has been leveled as nearly as possible to original ground contour and has be other production equipment. X Anchors, dead men, tie downs and risers have been cut off at least two feet below ground X If this is a one-well lease or last remaining well on lease, the battery and pit location(s) hoce OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, produ	tor's pit permit and closure plan. operly abandoned. oncrete. It shows the QUARTER LOCATION OR EEN WELDED OR een cleared of all junk, trash, flow lines and il level. ave been remediated in compliance with
X All pits have been remediated in compliance with OCD rules and the terms of the Operator X Rat hole and cellar have been filled and leveled. Cathodic protection holes have been proximal X A steel marker at least 4" in diameter and at least 4' above ground level has been set in a OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS E PERMANENTLY STAMPED ON THE MARKER'S SURFACE. X The location has been leveled as nearly as possible to original ground contour and has beother production equipment. X Anchors, dead men, tie downs and risers have been cut off at least two feet below ground X If this is a one-well lease or last remaining well on lease, the battery and pit location(s) hocD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production lease and well location. X All metal bolts and other materials have been removed. Portable bases have been removed.	tor's pit permit and closure plan. operly abandoned. oncrete. It shows the QUARTER LOCATION OR EEN WELDED OR een cleared of all junk, trash, flow lines and it level. ave been remediated in compliance with ction equipment and junk have been removed
X All pits have been remediated in compliance with OCD rules and the terms of the Operator X Rat hole and cellar have been filled and leveled. Cathodic protection holes have been proximal X A steel marker at least 4" in diameter and at least 4' above ground level has been set in a OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS E PERMANENTLY STAMPED ON THE MARKER'S SURFACE. X The location has been leveled as nearly as possible to original ground contour and has beother production equipment. X Anchors, dead men, tie downs and risers have been cut off at least two feet below ground X If this is a one-well lease or last remaining well on lease, the battery and pit location(s) h OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production lease and well location. X All metal bolts and other materials have been removed. Portable bases have been removed to be removed.)	tor's pit permit and closure plan. operly abandoned. oncrete. It shows the QUARTER LOCATION OR EEN WELDED OR een cleared of all junk, trash, flow lines and it level. ave been remediated in compliance with ction equipment and junk have been removed
X All pits have been remediated in compliance with OCD rules and the terms of the Operat X Rat hole and cellar have been filled and leveled. Cathodic protection holes have been prox X A steel marker at least 4" in diameter and at least 4' above ground level has been set in a OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS E PERMANENTLY STAMPED ON THE MARKER'S SURFACE. X The location has been leveled as nearly as possible to original ground contour and has be other production equipment. X Anchors, dead men, tie downs and risers have been cut off at least two feet below ground X If this is a one-well lease or last remaining well on lease, the battery and pit location(s) h OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, produ from lease and well location. X All metal bolts and other materials have been removed. Portable bases have been removed to be removed.) X All other environmental concerns have been addressed as per OCD rules.	tor's pit permit and closure plan. operly abandoned. oncrete. It shows the QUARTER LOCATION OR EEN WELDED OR een cleared of all junk, trash, flow lines and it level. ave been remediated in compliance with ction equipment and junk have been removed d. (Poured onsite concrete bases do not have
X All pits have been remediated in compliance with OCD rules and the terms of the Opera X Rat hole and cellar have been filled and leveled. Cathodic protection holes have been pro X A steel marker at least 4" in diameter and at least 4" above ground level has been set in COPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS EPERMANENTLY STAMPED ON THE MARKER'S SURFACE. X The location has been leveled as nearly as possible to original ground contour and has be other production equipment. X Anchors, dead men, tie downs and risers have been cut off at least two feet below ground X If this is a one-well lease or last remaining well on lease, the battery and pit location(s) h OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, produfrom lease and well location. X All metal bolts and other materials have been removed. Portable bases have been removed to be removed.) X All other environmental concerns have been addressed as per OCD rules. X Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. A retrieved flow lines and pipelines.	tor's pit permit and closure plan. operly abandoned. oncrete. It shows the QUARTER LOCATION OR EEN WELDED OR een cleared of all junk, trash, flow lines and il level. ave been remediated in compliance with ction equipment and junk have been removed d. (Poured onsite concrete bases do not have
X All pits have been remediated in compliance with OCD rules and the terms of the Operator X Rat hole and cellar have been filled and leveled. Cathodic protection holes have been prox X A steel marker at least 4" in diameter and at least 4' above ground level has been set in a COPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS EPERMANENTLY STAMPED ON THE MARKER'S SURFACE. X The location has been leveled as nearly as possible to original ground contour and has be other production equipment. X Anchors, dead men, tie downs and risers have been cut off at least two feet below ground X If this is a one-well lease or last remaining well on lease, the battery and pit location(s) he OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production lease and well location. X All metal bolts and other materials have been removed. Portable bases have been removed to be removed.) X All other environmental concerns have been addressed as per OCD rules. X Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All recommendations are removed.	tor's pit permit and closure plan. operly abandoned. oncrete. It shows the QUARTER LOCATION OR EEN WELDED OR een cleared of all junk, trash, flow lines and il level. ave been remediated in compliance with ction equipment and junk have been removed d. (Poured onsite concrete bases do not have
X All pits have been remediated in compliance with OCD rules and the terms of the Opera X Rat hole and cellar have been filled and leveled. Cathodic protection holes have been pro X A steel marker at least 4" in diameter and at least 4" above ground level has been set in COPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS EPERMANENTLY STAMPED ON THE MARKER'S SURFACE. X The location has been leveled as nearly as possible to original ground contour and has be other production equipment. X Anchors, dead men, tie downs and risers have been cut off at least two feet below ground X If this is a one-well lease or last remaining well on lease, the battery and pit location(s) h OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, produfrom lease and well location. X All metal bolts and other materials have been removed. Portable bases have been removed to be removed.) X All other environmental concerns have been addressed as per OCD rules. X Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. A retrieved flow lines and pipelines.	tor's pit permit and closure plan. operly abandoned. oncrete. It shows the QUARTER LOCATION OR EEEN WELDED OR een cleared of all junk, trash, flow lines and it level. ave been remediated in compliance with ction equipment and junk have been removed d. (Poured onsite concrete bases do not have all fluids have been removed from non- dge and belief.
X All pits have been remediated in compliance with OCD rules and the terms of the Operator Rat hole and cellar have been filled and leveled. Cathodic protection holes have been prox A steel marker at least 4" in diameter and at least 4' above ground level has been set in a OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS EPERMANENTLY STAMPED ON THE MARKER'S SURFACE. X The location has been leveled as nearly as possible to original ground contour and has beother production equipment. X Anchors, dead men, tie downs and risers have been cut off at least two feet below ground If this is a one-well lease or last remaining well on lease, the battery and pit location(s) he OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production lease and well location. X All metal bolts and other materials have been removed. Portable bases have been removed to be removed.) X All other environmental concerns have been addressed as per OCD rules. X Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. A retrieved flow lines and pipelines. X I hereby certify that the information above is true and complete to the best of my knowless.	tor's pit permit and closure plan. operly abandoned. oncrete. It shows the QUARTER LOCATION OR EEN WELDED OR een cleared of all junk, trash, flow lines and it level. ave been remediated in compliance with ction equipment and junk have been removed d. (Poured onsite concrete bases do not have all fluids have been removed from non- dge and belief. dule an inspection.
X All pits have been remediated in compliance with OCD rules and the terms of the Operat X Rat hole and cellar have been filled and leveled. Cathodic protection holes have been prox X A steel marker at least 4" in diameter and at least 4 above ground level has been set in a OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS E PERMANENTLY STAMPED ON THE MARKER'S SURFACE. X The location has been leveled as nearly as possible to original ground contour and has beother production equipment. X Anchors, dead men, tie downs and risers have been cut off at least two feet below ground X If this is a one-well lease or last remaining well on lease, the battery and pit location(s) hood of rules and the terms of the Operator's pit permit and closure plan. All flow lines, production lease and well location. X All metal botts and other materials have been removed. Portable bases have been removed to be removed.) X All other environmental concerns have been addressed as per OCD rules. X Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. A retrieved flow lines and pipelines. X I hereby certify that the information above is true and complete to the best of my knowled When all work has been completed, return this form to the appropriate District office to sche SIGNATURE TITLE Manager of Special Projects. Title Manager of Special Projects.	tor's pit permit and closure plan. operly abandoned. oncrete. It shows the QUARTER LOCATION OR EEN WELDED OR een cleared of all junk, trash, flow lines and if level. ave been remediated in compliance with ction equipment and junk have been removed d. (Poured onsite concrete bases do not have all fluids have been removed from non- dge and belief. dule an inspection. DATE 11 1909
X All pits have been remediated in compliance with OCD rules and the terms of the Operat Rat hole and cellar have been filled and leveled. Cathodic protection holes have been prox A steel marker at least 4" in diameter and at least 4' above ground level has been set in complete to the best of my knowled When all work has been completed, return this form to the appropriate District office to sches Signature. X All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production lease and well location. X All metal bolts and other materials have been addressed as per OCD rules. X Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. A retrieved flow lines and pipelines. X I hereby certify that the information above is true and complete to the best of my knowled. Signature TITLE Manager of Special Projects.	tor's pit permit and closure plan. operly abandoned. oncrete. It shows the QUARTER LOCATION OR EEN WELDED OR een cleared of all junk, trash, flow lines and if level. ave been remediated in compliance with ction equipment and junk have been removed d. (Poured onsite concrete bases do not have all fluids have been removed from non- dge and belief. dule an inspection. DATE 11 1909
X All pits have been remediated in compliance with OCD rules and the terms of the Operat X Rat hole and cellar have been filled and leveled. Cathodic protection holes have been prox X A steel marker at least 4" in diameter and at least 4 above ground level has been set in a OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS E PERMANENTLY STAMPED ON THE MARKER'S SURFACE. X The location has been leveled as nearly as possible to original ground contour and has beother production equipment. X Anchors, dead men, tie downs and risers have been cut off at least two feet below ground X If this is a one-well lease or last remaining well on lease, the battery and pit location(s) hood of rules and the terms of the Operator's pit permit and closure plan. All flow lines, production lease and well location. X All metal botts and other materials have been removed. Portable bases have been removed to be removed.) X All other environmental concerns have been addressed as per OCD rules. X Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. A retrieved flow lines and pipelines. X I hereby certify that the information above is true and complete to the best of my knowled When all work has been completed, return this form to the appropriate District office to sche SIGNATURE TITLE Manager of Special Projects. Title Manager of Special Projects.	tor's pit permit and closure plan. operly abandoned. oncrete. It shows the QUARTER LOCATION OR EEN WELDED OR een cleared of all junk, trash, flow lines and if level. ave been remediated in compliance with ction equipment and junk have been removed d. (Poured onsite concrete bases do not have all fluids have been removed from non- dge and belief. dule an inspection. DATE 11 1909