•					,	,		
		TED CTATES	COD-MOR	378 <b>5</b>	CODE			
Form 3160-5 (September 2001)	UNITED STATES DEPARTMENT OF THE INTE				FORM APPROVED OMB NO 1004-0135			
ć	BUREAU OF	LAND MANAGEME	NT			January 31, 2004		
SUNDRY NOTICES AND REPORTS ON WELLS DEC 2 2 2009					5 Lease Serial No			
,	Do not use this form for	proposals to drill o	or to re-enter ARRS	SOCO	<u>M – 0766</u> 6. If Indian, Allott	ee or Tribe Name		
al	bandoned well. Use For	m 3160-3 (APD) for	such proposals.	VVV				
SL	JBMIT IN TRIPLICATE -	Other instructions	on reverse side	<u></u>	7 If Unit or CA/A	Agreement, Name and/or No		
1 Type of Well		/						
X Oil Well Gas Well Other						8 Well Name and No CARLSON FEDERAL #4		
2 Name of Operator								
CIMAREX ENERGY CO. OF COLORADO       ATIN:       ZENO FARRIS         3a Address       3b Phone No. (include area					9. API Well No			
600 N. MARIENE	EID		432.571.7800			30-025-29373 10. Field and Pool, or Exploratory Area		
	tage. Sec, T, R, M, or Survey			LANGLIE MATTIX;				
UNIT LETTER P	/			7 RIVERS - C	N - GRAYBURG			
990' FSL & 990	1				11 County or Parish, State			
SEC. 23, T-25S					LEA COUNTY	<u></u> <u></u>		
12.	CHECK APPROPRIATE	BOX(ES) TO IND	ICATE NATURE OF	NOTICE, REF	PORT, OR OTHE	R DATA		
TYPE OF SUBMISSION			TY	PE OF ACTION	l			
X Notice	of Intent	Acidize	Deepen	Productio	on (Start/Resume)	Water Shut-Off		
		Alter Casing	Fracture Treat	Reclamat	ion	Well Integrity		
Subsequent Report			New Construction	Recomple		Other		
		Change Plans	Plug and Abandon		rily Abandon			
Final A	Abandonment Notice							
		Convert to Injectio	Plug Back	Water Du	sposal			
following complet testing has been of determined that the COMPLY WITH THE AUTHORIT 1) TAG EXIS 2) CIRC. WE 3) MIX X PU 4) MIX X PU 5) MIX X PU 6) MIX X PU 7) MIX X PU 8) MIX & PU	Inder which the work will be perion of the involved operations ompleted Final Abandonment e final site is ready for final inspe- ALL CIMAREX X GOVERN Y TO SHUT DOWN UNSAFT STING 5-1/2" CIBP + O ELL W/ PXA MUD. MP A 25 SX. OMT. PLUX MP A 10 SX. OMT. PLUX MP A 10 SX. OMT. SURI & CUT OFF WELLHEAD 3 RECLAMATION PROCI	If the operation results in Notices shall be filed on cetton) <b>MENT ENVIRONMENT</b> <b>COPERATIONS</b> . <b>MT.</b> (0 +/-2,855'; <b>G</b> (2,625'-2,425 <b>G</b> (2,625'-2,625'-2,625 <b>G</b> (2,215'-2,015 <b>G</b> (2,535'-335' (9-1) <b>F</b> . <b>PLUG</b> (6,63'-3' <b>' ' ' ' ' ' ' ' ' '</b>	n a multiple completion or r ly after all requirements, in AL X SAFETY REGULA MIX X FUMP A 25 S ' (T/7-RIVERS) . ' (DV TOOL X T/YATE ' (B/SALT) . T/SALT) ; WOC X TAG 5/8" CSG.SHOE) . STEEL PLATE ON CAS SEI	recompletion in a cluding reclamati ITIONS. ANY EX. OMT. PLU S). TOP OF OMI SINGS & SET E ATTA(	new interval, a Form on, have been comp CONE ON THE JUJ IG @ 2,855'-2, '. PLUG.	n 3160-4 shall be filed once leted, and the operator ha B LOCATION HAS 655'.		
14 I hereby certify that Name (Printed/Typed	the foregoing is true and correct		Title					
DAVID A.			AGENT					
1 Ja	A. 2	Q	Date 12/14/0	<sup>9</sup> ADD				
		SySPACE FOR FED	ERAL OR STATE OF	FICEUSE	<u>NUVEU</u>			
Approved by	- FALI	//5	Call Tiller DIGT	1. SULEN	VISON Date	DEC 2 3 2009		
Conditions of approval	if any are attached. Approval	of this notice does not w			<u>-2   2009  </u>	2009		
certify that the applican	t holds legal or equitable title to applicant to conduct operations t	those rights in the sub-	lect lease	/\$/ Dusti	n Winkler			
			e for any person knowingly	BURLAHINEL	NP.MANAGEMEN	nt or agency of the limited		
States any false, fictitiou	1001, and Title 43 U S.C Sections or fraudulent statements or rep	presentations as to any ma	atter within its jurisdiction.	CARLSBAL	J FIELD OFFICE	Stricy of the onited		

,

÷.

----



Cimares Energy Company of Colorado NM-0766: Carlson Federal #4 API: 30-025-29373 Lea County, New Mexico

RE: Plugging and Abandonment Requirements, Conditions of Approval

- 1. OK (Perfs)
- 2. OK
- 3. OK (7 Rivers)
- 4. WOC and tag Otherwise OK (DV Tool/Yates)
- 5. WOC and tag Otherwise OK (BOS)
- Optional Combine steps 1, 3-5 into one solid plug to run from +/-2855' (based on tag) to 2015'.
  WOC and tag at 2015 or shallower. If combined, complete step 2 before continuing.
  OK (TOS)
- 7. WOC and tag Otherwise OK (Casing shoe)
- 8. OK
- 9. Verify that all annuluses have cement to surface and fill in as required Otherwise OK.
- 10. Submit a subsequent report to the BLM.

H2S equipment should be on site since there is the potential for H2S.

See attached standard COAs.

DHW 122109

## BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

## Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90<sup>th</sup> day provide this office, prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.

3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.

4. <u>Mud Requirement</u>: Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.

5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. In lieu of a cement plug in a cased hole, a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Any plug that requires a tag will have a minimum WOC time of 4 hours.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C" for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). **The BLM is to be notified when the wellhead is cut off to verify that cement is to surface in the casing and all annuluses.** The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement. The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).

7. <u>Subsequent Plugging Reporting</u>: Within 30 days after plugging work is completed, file one original and five copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date well was plugged.</u>

8. <u>Trash</u>: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation procedure.

DHW 112309



## United States Department of the Interior

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 E Greene St Carlsbad. New Mexico 88220-6292 www blm.gov/nm



In Reply Refer To: 1310

2.

## **Interim Reclamation Procedures**

**Reclamation Objective:** Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses.

Interim reclamation consists of minimizing the footprint of disturbance by reclaiming all portions of the well site not needed for production operations. The portions of the cleared well site not needed for operational and safety purposes are recontoured to a final or intermediate contour that blends with the surrounding topography as much as possible. Sufficient level area remains for setup of a workover rig and to park equipment. Topsoil is respread over areas not needed for all-weather operations. Production facilities should be clustered to maximize the opportunity for interim reclamation. In order to inspect and operate the well or complete workover operations, it may be necessary to drive, park, and operate on restored, interim vegetation within the previously disturbed area. This is generally acceptable provided damage is repaired and reclaimed following use.

To reduce final reclamation costs; maintain healthy, biologically active topsoil; and to minimize habitat, visual, and forage loss during the life of the well, all salvaged topsoil should be spread over the area of interim reclamation, rather than stockpiled.

The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of Öperations must include adequate measures for stabilization and reclamation of disturbed lands. Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD process as per Onshore Oil and Gas Order No. 1.

For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). Interim reclamation is to be completed within 6 months of well completion.

If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with interim reclamation as per approved APD or Sundry Notice. If you have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.

5. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos

Supervisory Environmental Protection Specialist 575-234-5909, 575-361-2648 (Cell)

Terry Gregston Environmental Protection Specialist 575-234-5958

Bobby Ballard Environmental Protection Specialist 575-234-2230

Randy Rust Environmental Protection Specialist 575-234-5943

Linda Denniston Environmental Protection Specialist 575-234-5974

Jennifer Van Curen Environmental Protection Specialist. 575-234-5905

Justin Frye Environmental Protection Specialist 575-234-5922 Cody Layton Natural Resource Specialist 575-234-5959

Trishia Bad Bear Natural Resource Specialist 575-393-3612

Todd Suter Surface Protection Specialist 575-234-5987

Doug Hoag Civil Engineering Technician 575-234-5979