
State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE OIL CONSERVATION DIVISION WELL API NO. RECEIVE 20 South St. Francis Dr. Shita Fe, NM 87505 DISTRICT I 1625 N. French Dr., Hobbs, NM 88240 30-025-37409 5 Indicate Type of Lease DISTRICT II DEC 2 4 2009 FEE STATE X 1301 W Grand Ave, Artesia, NM 88210 6. State Oil & Gas Lease No DISTRICT III 1000 Rio Brazos Rd, Aztec, NM 87410 7. Lease Name or Unit Agreement Name SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A North Hobbs (G/SA) Unit DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.) Section 29 8. Well No. 1. Type of Well: 635 Oil Well Gas Well Injector 9. OGRID No 157984 2. Name of Operator Occidental Permian Ltd. 10. Pool name or Wildcat Hobbs (G/SA) 3. Address of Operator HCR 1 Box 90 Denver City, Tx 79323 4. Well Location Feet From The Line Feet From The South 1240 East Unit Letter 1665 NMPM Range County Section 29 Township 18-S 38-E Lea 11. Elevation (Show whether DF, RKB, RT GR, etc.) 3646' GR Pit or Below-grade Tank Application or Closure Distance from nearest fresh water well Distance from nearest surface water Depth of Ground Water Pit Type ____ Below-Grade Tank: Volume bbls: Construction Material Pit Liner Thickness Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 12. NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: ALTERING CASING PLUG AND ABANDON REMEDIAL WORK PERFORM REMEDIAL WORK CHANGE PLANS COMMENCE DRILLING OPNS **PLUG & ABANDONMENT** TEMPORARILY ABANDON CASING TEST AND CEMENT JOB PULL OR ALTER CASING Multiple Completion OTHER. OTHER: 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 1. RUPU & RU. Kill well 2. ND wellhead/NU BOP. 3. POOH w/tubing and injection packer. 4. RU wireline and dump bail 1-1/2 sacks of cement on CIBP @4247. Tag cement @4233'. RD wireline. 5. RIH w/straddle acid packers set @4156 & 4212'. RU HES & acid treat well w/1378 gals of treated water & 637 gal of 15% PAD acid in 4 stages. POOH w/straddle acid packers. 6. RIH w/CIBP set @4215'. 7. RIH w/5-1/2" Arrowset packer set on 122 jts of 2-7/8" Duoline tubing. Packer set @4050' 8. ND BOP/NU wellhead. 9. Test casing to 680# for 30 minutes and chart for the NMOCD. RUPU 11/06/09 RDPU 11/11/09 10. RDPU & RU. Clean location. I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be closed according to NMOCD guidelines or an (attached) alternative OCD-approved , a general permit plan SIGNATURE TITLE DATE Administrative Associate 12/23/2009 TYPE OR PRINT NAME TELEPHONE NO. 806-592-6280 Mendy Johnson E-mail address: Mendy johnson@oxy.com For State Use Only DEC 3 1 2009 TITLE DISTRICT 1 SUPERVISOR APPROVED BY CONDITIONS OF APPROVAL IF ANY:



The state of the s