

Submit 3 Copies To Appropriate District Office
JAN 05 2010
HOBBS
5 N. French Dr., Hobbs, NM 87240
1 W. Grand Ave., Artesia, NM 88210
0 Rio Brazos Rd., Aztec, NM 87410
0 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources
CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
May 27, 2004

WELL API NO. 30-005-20832
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. LG-2464
7. Lease Name or Unit Agreement Name: LOVELESS LQ STATE
8. Well Number 007
9. OGRID Number 14 31 99
10. Pool name or Wildcat TOMAHAWK (SAN ANDRES)

SUNDRY NOTICES AND REPORTS ON WELLS
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.

Type of Well:
Oil Well ☒ Gas Well ☐ Other ☐
Name of Operator
ENERVEST OPERATING, L.L.C. ATTN: B. HELFRICH
Address of Operator
1001 FANNIN ST., STE 800 HOUSTON, TEXAS 77002
Well Location

RECEIVED
DEC 30 2009
NMOCD ARTESIA

Unit Letter M 330 feet from the SOUTH line and 990 feet from the WEST line
Section 36 Township 07S Range 31E NMPM County CHAVES

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
4,388' - GR

Below-grade Tank Application ☐ or Closure ☒
Type S EEL Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____
Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material * NONE WITHIN 1,000'

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

FORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERED CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDON ☐
REPAIR / ALTER CASING ☐	MULTIPLE COMPLETION ☐	CASING TEST AND CEMENT JOB ☐	
OTHER: ☐		OTHER: ☐	

Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

9.5# brine w/ 12.5# salt gel per bbl

- 1.) TAG EXISTING CIBP X CMT @ +/- 3,830'; CIRC WELL W/ PXA MUD.
- 2.) MIX X PUMP A 25 SXS CMT PLUG @ 3,300' - 3,050' (B/SALT) Tag Plug @ 2300'. SQZ 25 SXS CMT WOC TAG.
- 3.) CUT X PULL 4-1/2" CSG @ +/- 1,720'.
- 4.) MIX X PUMP A 40 SXS CMT PLUG @ 1,770' (4-1/2" CSG STUB X 8-5/8" CSG SHOE); WOC X TAG TOP OF CMT PLUG
- 5.) MIX X PUMP A 40 SXS CMT PLUG @ 1,540' (T/SALT); WOC X TAG PLUG
- 6.) MIX X CIRC. TO SURF A 20 SXS CMT PLUG @ 63' - 3'.
- 7.) LOG OUT X CUT OFF WELLHEAD 3' B.G.L.; INSTALL DRY HOLE MARKER.

Approval checked providing work is complete by 3/04/10

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☒ , a general permit ☐ or an (attached) alternative OCD-approved plan ☐

(NATURAL) Leslie White TITLE AGENT DATE 12/29/09
E-mail address: LESLIE@THEMCDANIELCOMPANY.COM
Telephone No. 972-392-9335

State Use Only
APPROVED BY Mark Brown TITLE 1/04/10
Conditions of Approval, if any 1/5/2010

