

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised May 08, 2003

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-36186
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No. No
7. Lease Name or Unit Agreement Name Gladys
8. Well Number 1
9. OGRID Number 218878
10. Pool name or Wildcat Wildcat, Penn

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other	
2. Name of Operator Miller, Dyer & Co. LLC	
3. Address of Operator 508 West Wall #700, Midland, TX 79701	
4. Well Location Unit Letter J : 1980 feet from the South line and 1980 feet from the East line Section 33 Township 12S Range 38E NMPM Lea County	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3822 GR	


12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS <input type="checkbox"/> PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: <input type="checkbox"/>

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Contacted NMDC on 4/14/03 and recieved verbal instructions as to P & A Procedure.

1. Spot 35 sx plug @ 9,800' - 9,700'
2. Spot 35 sx plug @ 9,200' - 9,116'
3. Spot 35 sx plug @ 7,280' - 7,180'
4. Spot 35 sx plug @ 6,022' - 5,922'
5. Spot 35 sx plug @ 4,607' - 4,507', waited 2 hours and tagged @ 4,998'
- 6 Spot 35 sx plug @ 2,338' - 2,238'
7. Spot 35 sx plug @ 500' - 400', waited 2 hours and tagged @ 400'
8. Set 60' Surface plug and Move off rig
9. Prep to set marker and level location

Approved as to plugging of the Well Bore.
Liability under bond is retained until
surface restoration is completed.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. W. Mulloy TITLE Agent DATE 6/5/03

Type or print name J. W. Mulloy Telephone No. (432) 687-0323

(This space for State use)

APPROVED BY Hayes W. Wink FIELD REPRESENTATIVE II/STAFF MANAGER
Conditions of approval, if any: DATE JUN 17 2003