Submit 1 Copy To Appropriate District	State of New Mexico	Form C-103
Office Energy District I	y, Minerals and Natural Resources	October 13, 2009
THE RESERVE OF THE PARTY OF THE		WELL API NO.
District II 1301 W Grand Ave Artesia, NM 88210 OIL	CONSERVATION DISSELLA	30-025-38090 30- 025-38090
1301 W Grand Ave, Artesia, NM 88210 District III 1000 Rio Brazos Rd, Aztec, NM 87410 District IV	1220 South St. Francis Dran of the state of	STATE FEE
1000 Rio Brazos Rd , Aztec, NM 87410	Santa Fe, NM 87505 JAN 0 7 20	6 State Oil & Gas Lease No.
District IV 1220 S St. Francis Dr, Santa Fe, NM 87505	HOBBSOL	V-5491
07303		
SUNDRY NOTICES AND I		7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR		Willie State Unit
PROPOSALS.)		8. Well Number
1. Type of Well: Oil Well Gas Well	Other P&A	6
2. Name of Operator		9. OGRID Number
Yates Petroleum Corporation		025575
3. Address of Operator		10. Pool name or Wildcat
105 South Fourth Street, Artesia, NM 8821	0	Eight Mile Draw; Morrow (Gas)
4. Well Location		· · · · · · · · · · · · · · · · · · ·
Unit Letter K : 1980	feet from the South line and	1980 feet from the West line
Section 25 Townshi	p 11S Range 34E	NMPM Lea County
	tion (Show whether DR, RKB; RT, GR, etc.)	
	4146' GR	
12. Check Appropriat	e Box to Indicate Nature of Notice,	Report or Other Data
	<i>1.6</i> € 1	** :
NOTICE OF INTENTION		SEQUENT REPORT OF:
· —	ID ABANDON 🔲 REMEDIAL WOR	
TEMPORARILY ABANDON CHANGE	i i	LLING OPNS : P AND A
PULL OR ALTER CASING MULTIPL	E COMPL , 🔲 - , CASING/CEMENT	「JOB , □
DOWNHOLE COMMINGLE		•
OTHER:	□ OTHER	П
OTHER 13. Describe proposed or completed operat	OTHER	d give pertinent dates, including estimated date
13. Describe proposed or completed operat	ions. (Clearly state all pertinent details, and	I give pertinent dates, including estimated date appletions: Attach wellbore diagram of
13. Describe proposed or completed operat		
13. Describe proposed or completed operat of starting any proposed work). SEE R proposed completion or recompletion.	ions. (Clearly state all pertinent details, and ULE 19.15.7.14 NMAC. For Multiple Cor	npletions: Attach wellbore diagram of
13. Describe proposed or completed operat of starting any proposed work). SEE R proposed completion or recompletion. 12/15/09 Dumped 50' of cement on top of flow	ions. (Clearly state all pertinent details, and ULE 19.15.7.14 NMAC. For Multiple Corthuru plug. Set CIBP @ 10,000' w/35' cem	npletions: Attach wellbore diagram of
 13. Describe proposed or completed operate of starting any proposed work). SEE R proposed completion or recompletion. 12/15/09 Dumped 50' of cement on top of flow 7557-70' (26), 7580-84' (8) & 7592-9 	ions. (Clearly state all pertinent details, and ULE 19.15.7.14 NMAC. For Multiple Corthru plug. Set CIBP @ 10,000' w/35' cem 4' (4).	ent. Perforated Lower Yeso 7544-48' (8),
 13. Describe proposed or completed operate of starting any proposed work). SEE R proposed completion or recompletion. 12/15/09 Dumped 50' of cement on top of flow 7557-70' (26), 7580-84' (8) & 7592-9 12/16/09 Acidized w/2750 gal 15% NEFE & 90 	thru plug. Set CIBP @ 10,000' w/35' cem 4' (4).	ent. Perforated Lower Yeso 7544-48' (8),
 13. Describe proposed or completed operation of starting any proposed work). SEE R proposed completion or recompletion. 12/15/09 Dumped 50' of cement on top of flow 7557-70' (26), 7580-84' (8) & 7592-9 12/16/09 Acidized w/2750 gal 15% NEFE & 90 12/22/09 Circulated hole w/mud. Spotted 25 sx 	thru plug. Set CIBP @ 10,000' w/35' cem 4' (4). balls. Recompletion unsuccessful. Prep to plug @ 9200'.	ent. Perforated Lower Yeso 7544-48' (8), p plug & abandon.
13. Describe proposed or completed operation of starting any proposed work). SEE R proposed completion or recompletion. 12/15/09 Dumped 50' of cement on top of flow 7557-70' (26), 7580-84' (8) & 7592-912/16/09 Acidized w/2750 gal 15% NEFE & 9012/22/09 Circulated hole w/mud. Spotted 25 sx 12/23/09 thru 12/27/09 Tagged plug @ 9002'.	thru plug. Set CIBP @ 10,000' w/35' cem 4' (4). balls. Recompletion unsuccessful. Prep to plug @ 9200'. Pumped 100' plug from 7550-7450'. WOO	ent. Perforated Lower Yeso 7544-48' (8), p plug & abandon.
13. Describe proposed or completed operation of starting any proposed work). SEE R proposed completion or recompletion. 12/15/09 Dumped 50' of cement on top of flow 7557-70' (26), 7580-84' (8) & 7592-9 12/16/09 Acidized w/2750 gal 15% NEFE & 90 12/22/09 Circulated hole w/mud. Spotted 25 sx 12/23/09 thru 12/27/09 Tagged plug @ 9002'. 12/28/09 Spotted 25 sx plug @ 6300'. WOC 3	thru plug. Set CIBP @ 10,000' w/35' cem 4' (4). balls. Recompletion unsuccessful. Prep to plug @ 9200'. Pumped 100' plug from 7550-7450'. WOChrs. Tagged @ 4090'.	ent. Perforated Lower Yeso 7544-48' (8), o plug & abandon. C 3 hrs. Tagged @ 7352'.
13. Describe proposed or completed operation of starting any proposed work). SEE R proposed completion or recompletion. 12/15/09 Dumped 50' of cement on top of flow 7557-70' (26), 7580-84' (8) & 7592-9 12/16/09 Acidized w/2750 gal 15% NEFE & 90 12/22/09 Circulated hole w/mud. Spotted 25 sx 12/23/09 thru 12/27/09 Tagged plug @ 9002'. 12/28/09 Spotted 25 sx plug @ 6300'. WOC 3 12/29/09 Perforated squeeze holes @ 2000'. Spotted 25 sx plug @ 2000'.	thru plug. Set CIBP @ 10,000' w/35' cem 4' (4). balls. Recompletion unsuccessful. Prep to plug @ 9200'. Pumped 100' plug from 7550-7450'. WOChrs. Tagged @ 4090'.	ent. Perforated Lower Yeso 7544-48' (8), o plug & abandon. C 3 hrs. Tagged @ 7352'. WOC 3 hrs. Tagged @ 1860'. Perforated @
13. Describe proposed or completed operation of starting any proposed work). SEE R proposed completion or recompletion. 12/15/09 Dumped 50' of cement on top of flow 7557-70' (26), 7580-84' (8) & 7592-9 12/16/09 Acidized w/2750 gal 15% NEFE & 90 12/22/09 Circulated hole w/mud. Spotted 25 sx 12/23/09 thru 12/27/09 Tagged plug @ 9002'. 12/28/09 Spotted 25 sx plug @ 6300'. WOC 3 12/29/09 Perforated squeeze holes @ 2000'. Sp 483'. Spotted 25 sx plug. Tagged @	thru plug. Set CIBP @ 10,000' w/35' cem 4' (4). balls. Recompletion unsuccessful. Prep to plug @ 9200'. Pumped 100' plug from 7550-7450'. WOC hrs. Tagged @ 4090'. botted 30 sx plug 50' inside & 50' outside.	ent. Perforated Lower Yeso 7544-48' (8), o plug & abandon. C 3 hrs. Tagged @ 7352'. WOC 3 hrs. Tagged @ 1860'. Perforated @ t to surface.
13. Describe proposed or completed operation of starting any proposed work). SEE R proposed completion or recompletion. 12/15/09 Dumped 50' of cement on top of flow 7557-70' (26), 7580-84' (8) & 7592-9 12/16/09 Acidized w/2750 gal 15% NEFE & 90 12/22/09 Circulated hole w/mud. Spotted 25 sx 12/23/09 thru 12/27/09 Tagged plug @ 9002'. 12/28/09 Spotted 25 sx plug @ 6300'. WOC 3 12/29/09 Perforated squeeze holes @ 2000'. Sp 483'. Spotted 25 sx plug. Tagged @	thru plug. Set CIBP @ 10,000' w/35' cem 4' (4). balls. Recompletion unsuccessful. Prep to plug @ 9200'. Pumped 100' plug from 7550-7450'. WOC hrs. Tagged @ 4090'. cotted 30 sx plug 50' inside & 50' outside. 221'. Perforated @ 60'. Circulated cemen arker, cleaned location. WELL IS PLUGO	ent. Perforated Lower Yeso 7544-48' (8), po plug & abandon. C.3 hrs. Tagged @ 7352'. WOC 3 hrs. Tagged @ 1860'. Perforated @ t to surface. GED & ABANDONED.
13. Describe proposed or completed operation of starting any proposed work). SEE R proposed completion or recompletion. 12/15/09 Dumped 50' of cement on top of flow 7557-70' (26), 7580-84' (8) & 7592-9 12/16/09 Acidized w/2750 gal 15% NEFE & 90 12/22/09 Circulated hole w/mud. Spotted 25 sx 12/23/09 thru 12/27/09 Tagged plug @ 9002'. 12/28/09 Spotted 25 sx plug @ 6300'. WOC 3 12/29/09 Perforated squeeze holes @ 2000'. Sp 483'. Spotted 25 sx plug. Tagged @	thru plug. Set CIBP @ 10,000' w/35' cem 4' (4). balls. Recompletion unsuccessful. Prep to plug @ 9200'. Pumped 100' plug from 7550-7450'. WOC hrs. Tagged @ 4090'. botted 30 sx plug 50' inside & 50' outside. 221'. Perforated @ 60'. Circulated cemen arker, cleaned location. WELL IS PLUGO	ent. Perforated Lower Yeso 7544-48' (8), o plug & abandon. C 3 hrs. Tagged @ 7352'. WOC 3 hrs. Tagged @ 1860'. Perforated @ t to surface. GED & ABANDONED. Piproved for plugging or well bore only. Capture to good to retained pending receipt
13. Describe proposed or completed operation of starting any proposed work). SEE R proposed completion or recompletion. 12/15/09 Dumped 50' of cement on top of flow 7557-70' (26), 7580-84' (8) & 7592-9 12/16/09 Acidized w/2750 gal 15% NEFE & 90 12/22/09 Circulated hole w/mud. Spotted 25 sx 12/23/09 thru 12/27/09 Tagged plug @ 9002'. 12/28/09 Spotted 25 sx plug @ 6300'. WOC 3 12/29/09 Perforated squeeze holes @ 2000'. Sp 483'. Spotted 25 sx plug. Tagged @	thru plug. Set CIBP @ 10,000' w/35' cem 4' (4). balls. Recompletion unsuccessful. Prep to plug @ 9200'. Pumped 100' plug from 7550-7450'. WOChrs. Tagged @ 4090'. botted 30 sx plug 50' inside & 50' outside. 221'. Perforated @ 60'. Circulated cemen arker, cleaned location. WELL IS PLUGO	ent. Perforated Lower Yeso 7544-48' (8), popling & abandon. C.3 hrs. Tagged @ 7352'. WOC 3 hrs. Tagged @ 1860'. Perforated @ t to surface. GED & ABANDONED. piproved for plugging of well bore only. facility under bond is retained pending receipt for this cache acquirent Report of Well Plugging)
13. Describe proposed or completed operate of starting any proposed work). SEE R proposed completion or recompletion. 12/15/09 Dumped 50' of cement on top of flow 7557-70' (26), 7580-84' (8) & 7592-9 (12/16/09) Acidized w/2750 gal 15% NEFE & 90 (12/22/09) Circulated hole w/mud. Spotted 25 sx (12/23/09) thru (12/27/09) Tagged plug @ 9002'. 12/28/09 Spotted 25 sx plug @ 6300'. WOC 3 (12/29/09) Perforated squeeze holes @ 2000'. Sp 483'. Spotted 25 sx plug. Tagged @ 1/03/10 Cut off wellhead, installed dry hole may see the see that the starting any proposed work).	thru plug. Set CIBP @ 10,000' w/35' cem 4' (4). balls. Recompletion unsuccessful. Prep to plug @ 9200'. Pumped 100' plug from 7550-7450'. WOChrs. Tagged @ 4090'. botted 30 sx plug 50' inside & 50' outside. 221'. Perforated @ 60'. Circulated cemen arker, cleaned location.	ent. Perforated Lower Yeso 7544-48' (8), popling & abandon. C 3 hrs. Tagged @ 7352'. WOC 3 hrs. Tagged @ 1860'. Perforated @ to surface. GED & ABANDONED. pproved for plugging or well bore only. fability under bond is retained pending receipt for 103 (Subsequent Report of Well Plugging) fisch in the found at OCD Web Page under
13. Describe proposed or completed operation of starting any proposed work). SEE R proposed completion or recompletion. 12/15/09 Dumped 50' of cement on top of flow 7557-70' (26), 7580-84' (8) & 7592-9 12/16/09 Acidized w/2750 gal 15% NEFE & 90 12/22/09 Circulated hole w/mud. Spotted 25 sx 12/23/09 thru 12/27/09 Tagged plug @ 9002'. 12/28/09 Spotted 25 sx plug @ 6300'. WOC 3 12/29/09 Perforated squeeze holes @ 2000'. Sp 483'. Spotted 25 sx plug. Tagged @	thru plug. Set CIBP @ 10,000' w/35' cem 4' (4). balls. Recompletion unsuccessful. Prep to plug @ 9200'. Pumped 100' plug from 7550-7450'. WOChrs. Tagged @ 4090'. botted 30 sx plug 50' inside & 50' outside. 221'. Perforated @ 60'. Circulated cemen arker, cleaned location.	ent. Perforated Lower Yeso 7544-48' (8), popling & abandon. C.3 hrs. Tagged @ 7352'. WOC 3 hrs. Tagged @ 1860'. Perforated @ t to surface. GED & ABANDONED. piproved for plugging of well bore only. facility under bond is retained pending receipt for this cache acquirent Report of Well Plugging)
13. Describe proposed or completed operate of starting any proposed work). SEE R proposed completion or recompletion. 12/15/09 Dumped 50' of cement on top of flow 7557-70' (26), 7580-84' (8) & 7592-9 (12/16/09) Acidized w/2750 gal 15% NEFE & 90 (12/22/09) Circulated hole w/mud. Spotted 25 sx (12/23/09) thru (12/27/09) Tagged plug @ 9002'. 12/28/09 Spotted 25 sx plug @ 6300'. WOC 3 (12/29/09) Perforated squeeze holes @ 2000'. Sp 483'. Spotted 25 sx plug. Tagged @ 1/03/10 Cut off wellhead, installed dry hole may see the see that the starting any proposed work).	thru plug. Set CIBP @ 10,000' w/35' cem 4' (4). balls. Recompletion unsuccessful. Prep to plug @ 9200'. Pumped 100' plug from 7550-7450'. WOChrs. Tagged @ 4090'. botted 30 sx plug 50' inside & 50' outside. 221'. Perforated @ 60'. Circulated cemen arker, cleaned location.	ent. Perforated Lower Yeso 7544-48' (8), popling & abandon. C 3 hrs. Tagged @ 7352'. WOC 3 hrs. Tagged @ 1860'. Perforated @ to surface. GED & ABANDONED. pproved for plugging or well bore only. fability under bond is retained pending receipt for 103 (Subsequent Report of Well Plugging) fisch in the found at OCD Web Page under
13. Describe proposed or completed operat of starting any proposed work). SEE R proposed completion or recompletion. 12/15/09 Dumped 50' of cement on top of flow 7557-70' (26), 7580-84' (8) & 7592-9 12/16/09 Acidized w/2750 gal 15% NEFE & 90 12/22/09 Circulated hole w/mud. Spotted 25 sx 12/23/09 thru 12/27/09 Tagged plug @ 9002'. 12/28/09 Spotted 25 sx plug @ 6300'. WOC 3 12/29/09 Perforated squeeze holes @ 2000'. Sp 483'. Spotted 25 sx plug. Tagged @ 1/03/10 Cut off wellhead, installed dry hole masses and the starting any proposed work).	thru plug. Set CIBP @ 10,000' w/35' cem 4' (4). balls. Recompletion unsuccessful. Prep to plug @ 9200'. Pumped 100' plug from 7550-7450'. WOC hrs. Tagged @ 4090'. botted 30 sx plug 50' inside & 50' outside. 221'. Perforated @ 60'. Circulated cemen arker, cleaned location. Rig Release Date:	ent. Perforated Lower Yeso 7544-48' (8), o plug & abandon. C 3 hrs. Tagged @ 7352'. WOC 3 hrs. Tagged @ 1860'. Perforated @ t to surface. GED & ABANDONED. pproved for plugging of well bore only. iability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) high may be found at OCD Web Page under orms; www.emnrd.state.nm.us/ocd.
13. Describe proposed or completed operate of starting any proposed work). SEE R proposed completion or recompletion. 12/15/09 Dumped 50' of cement on top of flow 7557-70' (26), 7580-84' (8) & 7592-9 (12/16/09) Acidized w/2750 gal 15% NEFE & 90 (12/22/09) Circulated hole w/mud. Spotted 25 sx (12/23/09) thru (12/27/09) Tagged plug @ 9002'. 12/28/09 Spotted 25 sx plug @ 6300'. WOC 3 (12/29/09) Perforated squeeze holes @ 2000'. Sp 483'. Spotted 25 sx plug. Tagged @ 1/03/10 Cut off wellhead, installed dry hole may see the see that the starting any proposed work).	thru plug. Set CIBP @ 10,000' w/35' cem 4' (4). balls. Recompletion unsuccessful. Prep to plug @ 9200'. Pumped 100' plug from 7550-7450'. WOC hrs. Tagged @ 4090'. botted 30 sx plug 50' inside & 50' outside. 221'. Perforated @ 60'. Circulated cemen arker, cleaned location. Rig Release Date:	ent. Perforated Lower Yeso 7544-48' (8), o plug & abandon. C 3 hrs. Tagged @ 7352'. WOC 3 hrs. Tagged @ 1860'. Perforated @ t to surface. GED & ABANDONED. pproved for plugging of well bore only. iability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) high may be found at OCD Web Page under orms; www.emnrd.state.nm.us/ocd.
13. Describe proposed or completed operat of starting any proposed work). SEE R proposed completion or recompletion. 12/15/09 Dumped 50' of cement on top of flow 7557-70' (26), 7580-84' (8) & 7592-9 12/16/09 Acidized w/2750 gal 15% NEFE & 90 12/22/09 Circulated hole w/mud. Spotted 25 sx 12/23/09 thru 12/27/09 Tagged plug @ 9002'. 12/28/09 Spotted 25 sx plug @ 6300'. WOC 3 12/29/09 Perforated squeeze holes @ 2000'. Sp 483'. Spotted 25 sx plug. Tagged @ 1/03/10 Cut off wellhead, installed dry hole masses and the starting any proposed work).	thru plug. Set CIBP @ 10,000' w/35' cem 4' (4). balls. Recompletion unsuccessful. Prep to plug @ 9200'. Pumped 100' plug from 7550-7450'. WOC hrs. Tagged @ 4090'. botted 30 sx plug 50' inside & 50' outside. 221'. Perforated @ 60'. Circulated cemen arker, cleaned location. Rig Release Date:	ent. Perforated Lower Yeso 7544-48' (8), o plug & abandon. C 3 hrs. Tagged @ 7352'. WOC 3 hrs. Tagged @ 1860'. Perforated @ t to surface. GED & ABANDONED. pproved for plugging of well bore only. iability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) high may be found at OCD Web Page under orms; www.emnrd.state.nm.us/ocd.
13. Describe proposed or completed operat of starting any proposed work). SEE R proposed completion or recompletion. 12/15/09 Dumped 50' of cement on top of flow 7557-70' (26), 7580-84' (8) & 7592-9 12/16/09 Acidized w/2750 gal 15% NEFE & 90 12/22/09 Circulated hole w/mud. Spotted 25 sx 12/23/09 thru 12/27/09 Tagged plug @ 9002'. 12/28/09 Spotted 25 sx plug @ 6300'. WOC 3 12/29/09 Perforated squeeze holes @ 2000'. Sp 483'. Spotted 25 sx plug. Tagged @ 1/03/10 Cut off wellhead, installed dry hole masses and the starting any proposed work).	thru plug. Set CIBP @ 10,000' w/35' cem 4' (4). balls. Recompletion unsuccessful. Prep to plug @ 9200'. Pumped 100' plug from 7550-7450'. WOChrs. Tagged @ 4090'. botted 30 sx plug 50' inside & 50' outside. 221'. Perforated @ 60'. Circulated cemen arker, cleaned location. WELL IS PLUGO Rig Release Date:	ent. Perforated Lower Yeso 7544-48' (8), o plug & abandon. C 3 hrs. Tagged @ 7352'. WOC 3 hrs. Tagged @ 1860'. Perforated @ t to surface. GED & ABANDONED. pproved for plugging of well bore only. iability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) high may be found at OCD Web Page under orms; www.emnrd.state.nm.us/ocd.
13. Describe proposed or completed operate of starting any proposed work). SEE R proposed completion or recompletion. 12/15/09 Dumped 50' of cement on top of flow 7557-70' (26), 7580-84' (8) & 7592-9 12/16/09 Acidized w/2750 gal 15% NEFE & 90 12/22/09 Circulated hole w/mud. Spotted 25 sx 12/23/09 thru 12/27/09 Tagged plug @ 9002'. 12/28/09 Spotted 25 sx plug @ 6300'. WOC 3 12/29/09 Perforated squeeze holes @ 2000'. Sp 483'. Spotted 25 sx plug. Tagged @ 1/03/10 Cut off wellhead, installed dry hole may specific that the information above is true. Spud Date:	thru plug. Set CIBP @ 10,000' w/35' cem 4' (4). balls. Recompletion unsuccessful. Prep to plug @ 9200'. Pumped 100' plug from 7550-7450'. WOChrs. Tagged @ 4090'. botted 30 sx plug 50' inside & 50' outside. 221'. Perforated @ 60'. Circulated cemen arker, cleaned location. WELL IS PLUGO Rig Release Date:	ent. Perforated Lower Yeso 7544-48' (8), o plug & abandon. C 3 hrs. Tagged @ 7352'. WOC 3 hrs. Tagged @ 1860'. Perforated @ t to surface. GED & ABANDONED. pipioved for plugging of well bore only. fability under bond is retained pending receipt (C-103 (Subsequent Report of Well Plugging)) flich may be found at OCD Web Page under orms; www.emmrd.state.nm. us/ocd. e- and belief. DATE 1/05/10
13. Describe proposed or completed operat of starting any proposed work). SEE R proposed completion or recompletion. 12/15/09 Dumped 50' of cement on top of flow 7557-70' (26), 7580-84' (8) & 7592-9 12/16/09 Acidized w/2750 gal 15% NEFE & 90 12/22/09 Circulated hole w/mud. Spotted 25 sx 12/23/09 thru 12/27/09 Tagged plug @ 9002'. 12/28/09 Spotted 25 sx plug @ 6300'. WOC 3 12/29/09 Perforated squeeze holes @ 2000'. Sp 483'. Spotted 25 sx plug. Tagged @ 1/03/10 Cut off wellhead, installed dry hole may be supported by the struck of the struck o	thru plug. Set CIBP @ 10,000' w/35' cem 4' (4). balls. Recompletion unsuccessful. Prep to plug @ 9200'. Pumped 100' plug from 7550-7450'. WOChrs. Tagged @ 4090'. botted 30 sx plug 50' inside & 50' outside. 221'. Perforated @ 60'. Circulated cemen arker, cleaned location. WELL IS PLUGO Rig Release Date:	ent. Perforated Lower Yeso 7544-48' (8), o plug & abandon. C 3 hrs. Tagged @ 7352'. WOC 3 hrs. Tagged @ 1860'. Perforated @ t to surface. GED & ABANDONED. pipioved for plugging of well bore only. fability under bond is retained pending receipt (C-103 (Subsequent Report of Well Plugging)) flich may be found at OCD Web Page under orms; www.emmrd.state.nm. us/ocd. e- and belief. DATE 1/05/10
13. Describe proposed or completed operate of starting any proposed work). SEE R proposed completion or recompletion. 12/15/09 Dumped 50' of cement on top of flow 7557-70' (26), 7580-84' (8) & 7592-9 12/16/09 Acidized w/2750 gal 15% NEFE & 90 12/22/09 Circulated hole w/mud. Spotted 25 sx 12/23/09 thru 12/27/09 Tagged plug @ 9002'. 12/28/09 Spotted 25 sx plug @ 6300'. WOC 3 12/29/09 Perforated squeeze holes @ 2000'. Sp 483'. Spotted 25 sx plug. Tagged @ 1/03/10 Cut off wellhead, installed dry hole may specific that the information above is true. Spud Date:	thru plug. Set CIBP @ 10,000' w/35' cem 4' (4). balls. Recompletion unsuccessful. Prep to plug @ 9200'. Pumped 100' plug from 7550-7450'. WOC hrs. Tagged @ 4090'. botted 30 sx plug 50' inside & 50' outside. 221'. Perforated @ 60'. Circulated cemen arker, cleaned location. WELL IS PLUGO Rig Release Date: Rig Release Date: TITLE Regulatory Compliance E-mail address: abarton@yatespetroleu.	ent. Perforated Lower Yeso 7544-48' (8), o plug & abandon. C3 hrs. Tagged @ 7352'. WOC 3 hrs. Tagged @ 1860'. Perforated @ t to surface. GED & ABANDONED. pproved for plugging of well bore only. fiability under bond is retained pending receipt in C103 (Subsequent Report of Well Plugging) frich may be found at OCD Web Page under forms; will wiemerd state.nm. us/ocd. e and belief. e Technician DATE 1/05/10
13. Describe proposed or completed operat of starting any proposed work). SEE R proposed completion or recompletion. 12/15/09 Dumped 50' of cement on top of flow 7557-70' (26), 7580-84' (8) & 7592-9 12/16/09 Acidized w/2750 gal 15% NEFE & 90 12/22/09 Circulated hole w/mud. Spotted 25 sx 12/23/09 thru 12/27/09 Tagged plug @ 9002'. 12/28/09 Spotted 25 sx plug @ 6300'. WOC 3 12/29/09 Perforated squeeze holes @ 2000'. Sp. 483'. Spotted 25 sx plug. Tagged @ 1/03/10 Cut off wellhead, installed dry hole may be specified by the second of the second	thru plug. Set CIBP @ 10,000' w/35' cem 4' (4). balls. Recompletion unsuccessful. Prep to plug @ 9200'. Pumped 100' plug from 7550-7450'. WOC hrs. Tagged @ 4090'. botted 30 sx plug 50' inside & 50' outside. 221'. Perforated @ 60'. Circulated cemen arker, cleaned location. WELL IS PLUGO Rig Release Date: Rig Release Date: TITLE Regulatory Compliance E-mail address: _abarton@yatespetroleu.	ent. Perforated Lower Yeso 7544-48' (8), o plug & abandon. C 3 hrs. Tagged @ 7352'. WOC 3 hrs. Tagged @ 1860'. Perforated @ t to surface. GED & ABANDONED. Pipiroved for plugging of well bore only. Inhility under bond is retained pending receipt for 103 (Subsequent Report of Well Plugging) Inch may be found at OCD Web Page under orins; in it weimned state.nm. us/ocd. e. and belief. PHONE: (575) 748-1471 PNISOR
13. Describe proposed or completed operat of starting any proposed work). SEE R proposed completion or recompletion. 12/15/09 Dumped 50' of cement on top of flow 7557-70' (26), 7580-84' (8) & 7592-9 12/16/09 Acidized w/2750 gal 15% NEFE & 90 12/22/09 Circulated hole w/mud. Spotted 25 sx 12/23/09 thru 12/27/09 Tagged plug @ 9002'. 12/28/09 Spotted 25 sx plug @ 6300'. WOC 3 12/29/09 Perforated squeeze holes @ 2000'. Sp 483'. Spotted 25 sx plug. Tagged @ 1/03/10 Cut off wellhead, installed dry hole may be supported by the struck of the struck o	thru plug. Set CIBP @ 10,000' w/35' cem 4' (4). balls. Recompletion unsuccessful. Prep to plug @ 9200'. Pumped 100' plug from 7550-7450'. WOC hrs. Tagged @ 4090'. botted 30 sx plug 50' inside & 50' outside. 221'. Perforated @ 60'. Circulated cemen arker, cleaned location. WELL IS PLUGO Rig Release Date: Rig Release Date: TITLE Regulatory Compliance E-mail address: abarton@yatespetroleu.	ent. Perforated Lower Yeso 7544-48' (8), o plug & abandon. C3 hrs. Tagged @ 7352'. WOC 3 hrs. Tagged @ 1860'. Perforated @ t to surface. GED & ABANDONED. pproved for plugging of well bore only. fiability under bond is retained pending receipt in C103 (Subsequent Report of Well Plugging) frich may be found at OCD Web Page under forms; will wiemerd state.nm. us/ocd. e and belief. e Technician DATE 1/05/10

kai dan kawasi ninggalah mininggalah mininggalah menggi meneralah meneralah sebagai pada salah penggalah kadi