• • • • • • • • • • • • • • • • • • •					
Submit 3 Copies To Appropriate District I Submit 3 Copies To Appropriate District I 1625 N. French Dr., Hobbs, NM 87240 District II 1301 W. Grand Ave., Artesia, NM 87240 1220 South St. Francis Dr.			Form C-103 May 27, 2004 WELL API NO. 30-025-36331		
1301 W. Grand Ave., Artesia, NVT82 DSOUTE CONSERVATION DIVISION District III 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505		5. Indicate Type of STATE	of Lease		
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505			6. State Oil & Ga	s Lease No.	
SUNDRY NOTICES AND REPORTS ON (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEE DIFFERENT RESERVOID. USE "APPLICATION FOR PERMIT" (FORM PROPOSALS.)	EPEN (OR PLUG BACK TO A	7. Lease Name or Bertie Whitmir	Unit Agreement Name: e	
1. Type of Well: Oil Well X Gas Well Other			8. Well Number		
2. Name of Operator			9. OGRID Numbe	r	
OXY USA Inc. 3. Address of Operator			16 10. Pool name or	696	
P.O. Box 50250 Midland, TX 79710-0250			Monument Tubb	wildcat	
4. Well Location					
Unit Letter <u>B</u> : <u>660</u> feet from the	nor	<u>"th </u>	1650 feet fro	m the <u>east</u> line	
		Range 37E		County Lea 🗸	
11. Elevation (Show who		<i>DR, RKB, RT, GR, et</i> 19' GR	c.)		
Pit or Below-grade Tank Application or Closure					
Pit type Depth to Groundwater Distance from neare					
Pit Liner Thickness: mil Below-Grade Tank: Vo	olume_	bbls; Constructio	on Material		
12. Check Appropriate Box to Ind	icate	Nature of Notice	Report or Othe	r Data	
NOTICE OF INTENTION TO:	icate	· · · · · · · · · · · · · · · · · · ·	SEQUENT REI		
PERFORM REMEDIAL WORK D PLUG AND ABANDON [
TEMPORARILY ABANDON 🗌 CHANGE PLANS [COMMENCE DRILLI	NG OPNS. 🔲	PLUG AND	
PULL OR ALTER CASING MULTIPLE [COMPLETION		CASING TEST AND CEMENT JOB		ABANDONIVIENT	
OTHER:		OTHER:			
13. Describe proposed or completed operations. (Clearly state of starting any proposed work). SEE RULE 1103. For Ma or recompletion.					
See	Attac	hment		Ň	
I hereby certify that the information above is true and complete to grade tank has been/will be constructed or closed according to NMOCD gui	o the	best of my knowledge s, a general permit [and belief. I further	certify that any pit or below- ernative OCD-approved plan	
SIGNATURE	_ TITI	L <u>E Sr. Regulat</u>	tory Analyst	DATE 11810	
Type or print name David Stewart	E-n	nail address:	david_stewart@ox Teler	y.com bhone No. 432-685-5717	

E-mail addres	s:	david_	stew

		1
For State Use_Only		1 .
APPROVED BY	Tamp ll.	Sul
Conditions of Approval,	if any:	

DISTRICT 1 SUPERVISON JATE	Ŋ	1 3 2010	-
----------------------------	---	----------	---

Bertie Whitmire #1

Date Remarks

- 9/23/09 MIRU Westex 525. POOH w/rods & pump. ND WH NU BOP. POOH w/Tbg. Found scale build up on last 40 jts of Tbg. SWI & SDN. Will TIH w/bit & scraper tesing Tbg in AM.
- 9/24/09 PU 3-7/8" RB & 4.50" casing scraper. RU Tbg tester & TIH tetsting Tbg to 5,000# below slips. Found a hole 35 Jts above SN. LD 2 bent Jts. RD tester. POOH w/Tbg. LD bit & scraper. PU TIH w/4.50" RBP & packer. Left tools swinging @ 6,400'. SWI & SDN.
- 9/25/09 Tested packer to 1000 psi. Held. RIH w/ Packer & Plug on 204 jts 2 3/8" Tbg; Set Plug @ 6400'. Isolate csg leak
 @ 4346 to 4410'. PI Rate @ .4 bpm, @ 1200psi. Swab 40 bbls in 2 hrs, SFL Surface, EFL 1700' There is fluid entry
- 9/28/09 POH w/ 174 jts 2 3/8"Tbg & Pkr. MIRU Schlumberger ran CBL & CIL. SDON
- 9/29/09 POH w/ RBP & Tbg, RIH w/ CIBP set @ 6350 w/ 20' of cement on top.POH w/ Tbg, RIH w/Pkr set @ 4300. Did PI Rate 0.25 BPM @ 1500 psi. SDON. .
- 9/30/09 POH w/ 150 jts 2 3/8" Tbg & Pkr. RIH w Retainer on 150 jts 2 3/8" Tbg set @ 4314'
 PI Rate @ 2 bpm @ 850 psi, pump 20 bbl cement @400 psi, @ 48 bbl pressure started to climb. @ 50 bbl shut down. Max pressure jump to 2700 psi and held @ 900 psi. Wash up, rev out. Below retainer is 125 sks, 101 sks to pit, 74 sks in truck.
- 10/2/09 RIH w/ bit, BS, 6 DC On 2 3/8" to top of retainer. SD. RU Rev unit Drill out
- 10/5/09 Tag retainer @ 4313 drill to 4388 thru the retainer into cement. The Cement was balling up SDON.
- 10/6/09 Circulate cutting out of hole. RIH w/ 2 3/8" tbg. @ 6348'. Swab down to 1800' waited 1 hr & 45 min; tag FL @ 900 to 6 runs
- 10/7/09 Isolated casing leak to 4474-4491. Could not get a PI@1500psi. POH w/ Pkr and Plug. SDON NDP RIH w/ RBP and set @ 4610. Dump 1 sk of sand. Set Pkr @ 4430.
- 10/8/09 Pump 500 gal 15% HCL w/ rate .5 bpm @ 1000 psi flush w/ 25 bbls FW 2 bpm @ 700 psi. POH w/ Pkr & Plug. RIH w/ Retainer to 4442' left swinging. SDON.
- 10/9/09 RU Halliburton, Pump 20 bbls FW to clear retainer. Set CR @ 4,442'. Load backside to 500#. Establish Injedtion rate thru retainer 2 BPM @ 500#. Pump 1,000 gals Flo-Chec. M&P 150 Sx. Premium Pluss w/5#/sk Microbond + 0.3% Halad 322. Squeeze well to 3,100# w/aprox 10 Bbls cement in formation. Sting out of CR & reverse circulate hole clean. RD Halliburton. POOH w/ WS to 2000' x cal. TOC - 4442' x displaced 0 bbls
- 10/12/09 POOH w/Tbg. TIH w/3-7/8" RB & 6 3-1/8" DC's on 2-3/8" Tbg. Tag @ 4,441'. Drill out CICR @ 4,442' & soft cement to 4,473'. CHC.
- 10/13/09 PU power swivel. Establish reverse circulation and drill cement from 4,473' to 4,534'. Fell out of cement. RIH to 4,565'. CHC. RU & swab & swab Fluid level down to 3,000'. SWI & SDN. Will tag fluid in AM and check for fluid entry.
- 10/14/09 Tag Fluid @ 2400' gain 600' overnight, 9 bbls. Swab back down to 3000' waited 1 hrtag fluid @ 2950' 50' about 1 bmhr. swab FL to 3000 ' waited 2 hrs tag FL @ 2900', same rate. POH w/ bit, bs, dc. on 2 3/8. RIH to isolate casing leak.
- 10/15/09 POH w/ Pkr & Plug & tbg. rih W/ bit bs, dc on 2 3/8Tbg. Drill out CIBP @ 6350 to 6600, CHC. SDON.
- 10/16/09 POH w/ Bit, DC, & Tbg Tag @ 6393. Pump 500 gal 15 % HCL & 40 bbls Flush. 8 Runs, SFL 2400, EFL 3000, 38 bbls fluid recovery. POH w/ 204 jts 2 3/8" Tbg , 6 DC, BS, Bit
- 10/19/09 POH w/ 204 jts 2 3/8" Tbg , 6 DC, BS, Bit. RIH w/ BHA & 2 3/8" Tbg found no holes. Set TAC @ 6283 w/ 20,000#. RIH w/ Pump & rods. Loaded w/ 7 bbls pressure up to 500 psi held; 5 strokes to pressure up to 500 psi
- 10/20/09 Check pump action was good and Clean location. RDPU

~

OXY USA Inc. Bertie Whitmire #11 API No. 30-025-36331



2-3/8" tbg & TAC @ 6283'

PB-7453'