



# NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

**BILL RICHARDSON**

Governor

**Joanna Prukop**

Cabinet Secretary

**Mark E. Fesmire, P.E.**

Director

**Oil Conservation Division**

*Field Inspection Program*

*"Preserving the Integrity of Our Environment"*

20-Jan-10

**BURGUNDY OIL & GAS OF N M INC**

401 W TEXAS STE 1003

MIDLAND TX 79701

## LETTER OF VIOLATION - Inspection

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.


Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

### INSPECTION DETAIL SECTION

EUNICE MONUMENT UNIT No.038				D-29-20S-37E	30-025-06279-00-00	
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
01/14/2010	Routine/Periodic	Mark Whitaker	Yes	No	4/19/2010	iMAW1001444901
Violations						
Absent Well Identification Signs (Rule 103)						
Comments on Inspection:		Wrong operator on well sign. Well sing does not comply with current rule (19.15.16.8). NEED TO REPLACE WELL SIGN. 1st notice. MW				

EUNICE MONUMENT UNIT No.039				C-29-20S-37E	30-025-20899-00-00	
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
01/14/2010	Routine/Periodic	Mark Whitaker	Yes	No	4/19/2010	iMAW1001444601
Violations						
Absent Well Identification Signs (Rule 103)						
Comments on Inspection:		No pumping Unit. Rods stacked out in tbg. Production reported in October 2009. No well sign (Rule 19.15.16.8). NEED TO INSTALL WELL SIGN. 1st notice. MW				

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well. Such a hearing may result in imposition of CIVIL PENALTIES for your violation of OCD rules.




Sincerely,

COMPLIANCE OFFICER

Hobbs OCD District Office

**Note:** Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data  
\*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.

EMNRD  
OIL CONSERVATION DIVISION  
1625 N FRENCH DRIVE  
HOBBS NM 88240



HASLER

017H15554612

\$0.440

01/20/2010

Mailed From 88240

US POSTAGE

BURGUNDY OIL & GAS OF NM INC  
401 W TEXAS STE 1003  
MIDLAND, TX 79701