Office District I Energy, Minerals and Natural Resources	Form C-103 October 13, 2009 WELL API NO.
District III 1301 Rio Brazos Rd., Aztec, NMSR419 3 2010  1625 N French Dr., Hobbs, NM 88240  District III 1000 Rio Brazos Rd., Aztec, NMSR419 3 2010  1625 N French Dr., Hobbs, NM 88240  District III 1000 Rio Brazos Rd., Aztec, NMSR419 3 2010  Santa Fe. NM 87505	30-025-39053 ✓  5. Indicate Type of Lease  STATE
1220 S. St. Francis Dr., Santa DBSOCD 87505	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name Cattleman 4 State
PROPOSALS.) 1. Type of Well: Oil Well   ☐ Gas Well ☐ Other	8. Well Number 3
2. Name of Operator Chesapeake Operating, Inc.	9. OGRID Number
3. Address of Operator P.O. Box 18496 Oklahoma City, OK 73154-0496	10. Pool name or Wildcat Osudo; Strawn Wolfcamp
4. Well Location	03440, 544411 <b>10 0</b> (4) 26(1)(1)
Unit Letter C: 660' feet from the North line and 1720' feet from the West line	
Section 4 Township 21 S Range 35 E	NMPM County Lea ✓
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3630' GR	
12. Check Appropriate Box to Indicate Nature of Notice,	Report or Other Data
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK  TEMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRILL  PULL OR ALTER CASING   MULTIPLE COMPL   CASING/CEMENT  DOWNHOLE COMMINGLE	LING OPNS. P AND A
OTHER: OTHER. Plug Bac	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Con	
proposed completion or recompletion.	ipletions: Attach wellbore diagram of
proposed completion or recompletion.  Please find work performed in the plug back to the Wolfcamp from 12/21/09 through 1/8 12/21/09: MIRU Service unit. Unhang well. Unseat pump & TOOH w/production rods &	3/2010.
proposed completion or recompletion.  Please find work performed in the plug back to the Wolfcamp from 12/21/09 through 1/8 12/21/09: MIRU Service unit. Unhang well. Unseat pump & TOOH w/production rods & 12/22/09: NDWH, NUBOP. Release TAC & TOOH w/tbg. SWI SD. 12/23/09: MI WL service. TIH w/GR & JB to 10550'. PU CIBP & TIH to 10225' & place bbl of 2% KCL & test to 1000 psi, no leak off. SWI SD.	2/2010. Expump. Se 35' cmt on top of CIBP. Load hole w/145
proposed completion or recompletion.  Please find work performed in the plug back to the Wolfcamp from 12/21/09 through 1/8 12/21/09: MIRU Service unit. Unhang well. Unseat pump & TOOH w/production rods & 12/22/09: NDWH, NUBOP. Release TAC & TOOH w/tbg. SWI SD. 12/23/09: MI WL service. TIH w/GR & JB to 10550'. PU CIBP & TIH to 10225' & place bbl of 2% KCL & test to 1000 psi, no leak off. SWI SD. 12/28/09: MIRU WL. PU lubricator & test to 3000 psi. No leak off. TIH & perf Wolfca	2/2010. Expump. Se 35' cmt on top of CIBP. Load hole w/145
proposed completion or recompletion.  Please find work performed in the plug back to the Wolfcamp from 12/21/09 through 1/8 12/21/09: MIRU Service unit. Unhang well. Unseat pump & TOOH w/production rods & 12/22/09: NDWH, NUBOP. Release TAC & TOOH w/tbg. SWI SD. 12/23/09: MI WL service. TIH w/GR & JB to 10550'. PU CIBP & TIH to 10225' & place bbl of 2% KCL & test to 1000 psi, no leak off. SWI SD.	3/2010. 2 pump. 2 35' cmt on top of CIBP. Load hole w/145 mp from 10143'-10260' (OA) w/ 2 spf. Total
proposed completion or recompletion.  Please find work performed in the plug back to the Wolfcamp from 12/21/09 through 1/8 12/21/09: MIRU Service unit. Unhang well. Unseat pump & TOOH w/production rods & 12/22/09: NDWH, NUBOP. Release TAC & TOOH w/tbg. SWI SD. 12/23/09: MI WL service. TIH w/GR & JB to 10550'. PU CIBP & TIH to 10225' & place bbl of 2% KCL & test to 1000 psi, no leak off. SWI SD. 12/28/09: MIRU WL. PU lubricator & test to 3000 psi. No leak off. TIH & perf Wolfca 78 holes. PU pkr & assembly & TIH w/tbg to 10040'. SWI SD. 12/29/09: MIRU Acid service. Acidize Wolfcamp perfs 10143'-10260' (OA) w/ 4000 ga Spot 500 gals @ 10267'. Set pkr. Load & test annulus to 500 psi. No leak off. (Cont. pg. 2)	3/2010. 2 pump. 2 35' cmt on top of CIBP. Load hole w/145 mp from 10143'-10260' (OA) w/ 2 spf. Total
Please find work performed in the plug back to the Wolfcamp from 12/21/09 through 1/3 12/21/09: MIRU Service unit. Unhang well. Unseat pump & TOOH w/production rods & 12/22/09: NDWH, NUBOP. Release TAC & TOOH w/tbg. SWI SD. 12/23/09: MI WL service. TIH w/GR & JB to 10550'. PU CIBP & TIH to 10225' & plac bbl of 2% KCL & test to 1000 psi, no leak off. SWI SD. 12/28/09: MIRU WL. PU lubricator & test to 3000 psi. No leak off. TIH & perf Wolfca 78 holes. PU pkr & assembly & TIH w/tbg to 10040'. SWI SD. 12/29/09: MIRU Acid service. Acidize Wolfcamp perfs 10143'-10260' (OA) w/ 4000 ga Spot 500 gals @ 10267'. Set pkr. Load & test annulus to 500 psi. No leak off. (Cont. pg. 2)  Spud Date:  Rig Release Date:	3/2010.  the assistant on top of CIBP. Load hole w/145  mp from 10143'-10260' (OA) w/ 2 spf. Total  lls 15% NeFe HCL, dropping 150 ball sealers.
Please find work performed in the plug back to the Wolfcamp from 12/21/09 through 1/8 12/21/09: MIRU Service unit. Unhang well. Unseat pump & TOOH w/production rods & 12/22/09: NDWH, NUBOP. Release TAC & TOOH w/tbg, SWI SD. 12/23/09: MI WL service. TIH w/GR & JB to 10550'. PU CIBP & TIH to 10225' & place bbl of 2% KCL & test to 1000 psi, no leak off. SWI SD. 12/28/09: MIRU WL. PU lubricator & test to 3000 psi. No leak off. TIH & perf Wolfca 78 holes. PU pkr & assembly & TIH w/tbg to 10040'. SWI SD. 12/29/09: MIRU Acid service. Acidize Wolfcamp perfs 10143'-10260' (OA) w/ 4000 ga Spot 500 gals @ 10267'. Set pkr. Load & test annulus to 500 psi. No leak off. (Cont. pg. 2)  Spud Date:  Rig Release Date:	B/2010.  Expump.  See 35' cmt on top of CIBP. Load hole w/145  mp from 10143'-10260' (OA) w/ 2 spf. Total  Is 15% NeFe HCL, dropping 150 ball sealers.  Expected and belief.
Please find work performed in the plug back to the Wolfcamp from 12/21/09 through 1/8 12/21/09: MIRU Service unit. Unhang well. Unseat pump & TOOH w/production rods & 12/22/09: NDWH, NUBOP. Release TAC & TOOH w/tbg. SWI SD. 12/23/09: MI WL service. TIH w/GR & JB to 10550'. PU CIBP & TIH to 10225' & place bbl of 2% KCL & test to 1000 psi, no leak off. SWI SD. 12/28/09: MIRU WL. PU lubricator & test to 3000 psi. No leak off. TIH & perf Wolfca 78 holes. PU pkr & assembly & TIH w/tbg to 10040'. SWI SD. 12/29/09: MIRU Acid service. Acidize Wolfcamp perfs 10143'-10260' (OA) w/ 4000 ga Spot 500 gals @ 10267'. Set pkr. Load & test annulus to 500 psi. No leak off. (Cont. pg. 2)  Spud Date:  Rig Release Date:  Rig Release Date:  TITLE Senior Regulatory Compl.	B/2010.  Expump.  De 35' cmt on top of CIBP. Load hole w/145  mp from 10143'-10260' (OA) w/ 2 spf. Total  Ils 15% NeFe HCL, dropping 150 ball sealers.  Expure and belief.  DATE 01/12/2010
Please find work performed in the plug back to the Wolfcamp from 12/21/09 through 1/8  12/21/09: MIRU Service unit. Unhang well. Unseat pump & TOOH w/production rods & 12/22/09: NDWH, NUBOP. Release TAC & TOOH w/tbg. SWI SD.  12/23/09: MI WL service. TIH w/GR & JB to 10550'. PU CIBP & TIH to 10225' & place blood of 2% KCL & test to 1000 psi, no leak off. SWI SD.  12/28/09: MIRU WL. PU lubricator & test to 3000 psi. No leak off. TIH & perf Wolfca 78 holes. PU pkr & assembly & TIH w/tbg to 10040'. SWI SD.  12/29/09: MIRU Acid service. Acidize Wolfcamp perfs 10143'-10260' (OA) w/ 4000 ga Spot 500 gals @ 10267'. Set pkr. Load & test annulus to 500 psi. No leak off. (Cont. pg. 2)  Spud Date:  Rig Release Date:  Rig Release Date:  TITLE Senior Regulatory Compl.  Type or print name Bran Arrant  E-mail address: bryan.arrant@chl For State Use Only	28/2010. 26 pump. 26 and belief.  27 pump. 28 pump. 29 and belief.  20 pump. 20 pump. 20 pump. 21 pump. 22 pump. 23 pump. 24 pump. 25 pump. 26 and hole w/145 26 pump. 26 and hole w/145 27 pump. 28 pump. 29 pump. 20 pump
Please find work performed in the plug back to the Wolfcamp from 12/21/09 through 1/8  12/21/09: MIRU Service unit. Unhang well. Unseat pump & TOOH w/production rods & 12/22/09: NDWH, NUBOP. Release TAC & TOOH w/tbg. SWI SD. 12/23/09: MI WL service. TIH w/GR & JB to 10550'. PU CIBP & TIH to 10225' & place bbl of 2% KCL & test to 1000 psi, no leak off. SWI SD. 12/28/09: MIRU WL. PU lubricator & test to 3000 psi. No leak off. TIH & perf Wolfca 78 holes. PU pkr & assembly & TIH w/tbg to 10040'. SWI SD. 12/29/09: MIRU Acid service. Acidize Wolfcamp perfs 10143'-10260' (OA) w/ 4000 ga Spot 500 gals @ 10267'. Set pkr. Load & test annulus to 500 psi. No leak off. (Cont. pg. 2)  Spud Date:  Rig Release Date:  Rig Release Date:  TITLE Senior Regulatory Compl.  E-mail address: bryan.arrant@chl	28/2010. 26 pump. 26 and belief.  27 pump. 28 pump. 29 and belief.  20 pump. 20 pump. 20 pump. 21 pump. 22 pump. 23 pump. 24 pump. 25 pump. 26 and hole w/145 26 pump. 26 and hole w/145 27 pump. 28 pump. 29 pump. 20 pump

Cattleman 4 State # 3
Unit C Sec. 4, T-21-S R-35-E
Lea Co., NM
(API # 30-025-39053)
Plug back to Wolfcamp continued

12/30/2009 through 01/08/2010: Test well. Turn over to production.