Submit I Copy To Appropriate District Office	Energy, Minerals and Natural Resources		Form C-103	
District I			October 13, 2009 WELL API NO.	
1625 N. French Dr., Hobbs, NM 8824RECEIVED			0-025-26741	
1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION District III 1000 Pic Property Actor NM 87410 JAN 2 U 2.01220 South St. Francis Dr.		5. Indicate Type of	Lease	
District IV 1220 S. St. Francis Dr. Santa Fe, NM 87505		STATE 6. State Oil & Gas I	FEE X	
1220 S St. Francis Dr., Santa Fe, NM 87505	3000B		or state on a vas t	souse 110.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-191) FOR SUCH PROPOSALS.)			7 Lease Name or Unit Agreement Name J A Akens	
1. Type of Well: Oil Well X Gas Well Other			8. Well Number 11	
2. Name of Operator Chesapeake Operating, Inc.			9. OGRID Number 147179	
3. Address of Operator p.O. Box 18496 Oklahoma City, OK 73154-0496			10. Pool name or Wildcat	
4. Well Location			Oil Center; Blinebry	
Unit Letter R: 1980' feet from the South line and 2164' feet from the East line				
Section 3		ange 36E	NMPM (CountyLea
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3551' GR				
Total A 1/1/1 191/1			1 22000 1.0	40 - 18 (2010) - 10 - 10 - 10 - 10 - 10 - 10 - 10
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK				LTERING CASING
TEMPORARILY ABANDON			AND A	
DOWNHOLE COMMINGLE	JETH EE GOWN E	CASING/CLIVILINI	JOB	
OTHER:		OTHER		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.				
Please find the work performed in the plug and abandonment of this well from 1/11/10 through 1/14/10.				
1/11/10: MIRU PU. NDWH & NU BOP. POOH w/tbg. Found rods parted. Started stripping tbg out. SD. 1/12/10: Finish stripping out tbg & rods. SISD.				
1/13/10: PU RIH & circ hole clean w/brine & plugging mud. Pump 25 sxs cmt from 5792'-5545'. WOC. RIH to tag plug @ 5605'.				
POOH & pump 25 sxs 3954'-3707'. PU & WOC. SISD. 1/14/10: RIH to tag plug @ 3760'. Pump 25 sxs cmt 2615'-2368'. WOC. Tag plug @ 2571'. Pump 35 sxs cmt 1401'-1055', WOC,				
Tag plug @ 1054'. Pump 45 sxs cmt 404' to surface. RDMO. Turn well over to production for final clean up. Well P&A'd on 1/14/10.				
		Approved for pluggin	g of well bore only. Is retained pending receipt	
		of C-103 (Subsequent	t Report of Well Plugging) at OCD Web Page under	
		Forms, www.emnrd.st	••	
Spud Date:	Rig Release Da	ate:		
	<u></u>			J
I hereby certify that the information abov	e is true and complete to the be	est of my knowledge	and belief.	
	·			
SIGNATURE (My Army) TITLE Senior Regulatory Compl. Sp. DATE 11/15/2010				
Type or print name Bryan Arrant	E-mail address	s: bryan.arrant@chk	com PHON	NE: (405)935-3782
For State Use Only				
APPROVED BY: Larry 1	TITLE DIST	RIOT 1 SUPER	MSOF DATE	JAN 2 0 2010
Conditions of Approval (if any):	4 1			