

New Mexico Oil Conservation Division, District I  
1625 N. French  
Hobbs, NM 88240

Form 3160-5  
(August 2007)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

JAN 19 2010

HOBBSD

FORM APPROVED  
OMB No 1004-0137  
Expires July 31, 2010

**SUNDRY NOTICES AND REPORTS ON WELLS**  
**Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.**

5. Lease Serial No.

State

6. If Indian, Allottee or Tribe Name

**SUBMIT IN TRIPLICATE - Other instructions on page 2.**

1. Type of Well

☒ Oil Well

☐ Gas Well

☐ Other

2. Name of Operator

KEVIN O. BUTLER & ASSOCIATES

8. Well Name and No.

SOUTH CAPROCK QUEEN 11-30

9. API Well No.

3000500657

3a. Address

550 WEST TEXAS SUITE 660 MIDLAND, TX 79701

3b. Phone No. (include area code)

432-682-1178

10. Field and Pool or Exploratory Area

CAPROCK QUEEN

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

NESW 30 15S 31E NMP CHAVEZ NM

11. Country or Parish, State

NEW MEXICO

Chavez

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION:

TYPE OF ACTION

☒ Notice of Intent

☐ Subsequent Report

☐ Final Abandonment Notice

☐ Acidize

☐ Alter Casing

☐ Casing Repair

☐ Change Plans

☐ Convert to Injection

☐ Deepen

☐ Fracture Treat

☐ New Construction

☐ Plug and Abandon

☐ Plug Back

☒ Production (Start/Resume)

☐ Reclamation

☐ Recomplete

☐ Temporarily Abandon

☐ Water Disposal

☐ Water Shut-Off

☐ Well Integrity

☐ Other

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

For the purpose of these reports MIT test shall consist of PKR within 100' of top perforations & testing to 500# without a chart recorder for 15min. No OCD personnel present

SCRQ#11-30 API 30-005-00657 Oct. 08

MORU WSU RIH 4 3/4" 3 cone BTT bit to PBTD. RIH PKR to 100' perf & fail MIT test. Isolate whole & communication to surface. RU WL & back off csg inside surface pipe. RIH screw back into csg & land leaving 30pnts on. RBIH PKR & pass MIT test. Treat 1,200gal 12%HCL. Swab back spent acid & POOH PKR RIH TAC on production BHA & place well on PC pump. RDMO Steel reverse pit & closed system used on job.

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)

Title

President

Signature

Date

10-12-09

ACCEPTED FOR RECORD THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

/S/ DAVID R. GLASS

PETROLEUM ENGINEER

JAN 21 2010

Conditions of approval if any are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title

Date

Office

ROSWELL FIELD OFFICE

Title 18 U.S.C. Section 1001 and 1212 make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)