

Submit 3 Copies To Appropriate District Office
 District I
 1625 N. French Dr., Hobbs, NM 87240
 District II
 1301 W. Grand Ave., Artesia, NM 88210
 District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy, Minerals and Natural Resources
OIL CONSERVATION DIVISION
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

Form C- 03

June 19, 2008

WELL API NO. 30-025-29677	
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>	
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name South Hobbs (GSA) Unit	
8. Well Number 210	
9. OGRID Number 157984	
10. Pool name or Wildcat Hobbs: Grayburg-San Andres	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input checked="" type="checkbox"/>	
2. Name of Operator Occidental Permian Limited Partnership	
3. Address of Operator P.O. Box 4294, Houston, TX 77210-4294	
4. Well Location Unit Letter <u>D</u> : <u>721</u> feet from the <u>North</u> line and <u>569</u> feet from the <u>West</u> line Section <u>34</u> Township <u>18-S</u> Range <u>38-E</u> NMPM County <u>Lea</u>	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3635.9' GR	

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
 TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
 PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
 DOWNHOLE COMMINGLE ☐

OTHER: Temporarily Abandon Well

☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
 COMMENCE DRILLING OPNS. ☐ P AND A ☐
 CASING/CEMENT JOB ☐

OTHER:

☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

See Attached

Condition of Approval: Notify OCD Hobbs
 office 24 hours prior to running MIT Test & Chart

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mark Stephens TITLE Regulatory Compliance Analyst DATE 1/25/10
Mark_Stephens@oxy.com
 Type or print name Mark Stephens E-mail address: Mark_Stephens@oxy.com PHONE (713) 366-5158

For State Use Only

APPROVED BY [Signature] TITLE DISTRICT 1 SUPERVISOR DATE JAN 25 2010
 Conditions of Approval (if any):

Page 2 (C-103 Attachment)

South Hobbs (GSA) Unit No. 210
API No. 30-025-29677

Temporarily abandon well as follows:

- 1) MI x RU. ND WH x NU BOP.
- 2) POOH with production tubing and ESP equipment.
- 3) RIH with 6-1/4" bit x scraper on workstring. Clean out well to 4190' x circulate clean.
- 4) RU SWS x set 7" CIBP at 4182' with wireline.
- 5) Pressure test casing and squeezed perfs (4126' - 4180') to 500 psi.
- 6) RIH with 7" CIBP x set at 4000' x cap with ~~25~~ 35' cement. Tag to confirm.
- 7) Pressure test casing (notify OCD in advance of MIT).
- 8) ND BOP x install TxA wellhead.
- 9) RD x MO x clean location.

*Dump BAE/ 35'
CMT.*