	N	I.M. CII C	ons. Divisio	n		
	1	625 N. Fr	ench Dr.			
Form 3160-5 (September 2001)	UNITED STATES HOBDS, NM 88240 DEPARTMENT OF THE INTERIOR			FORM APPROVED OMB No. 1004-0135 Expires January 31, 2004		
BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS			5. Lease Serial No. 058699Y			
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.				6. If Indian, Allottee or Tribe Name		
SUBMIT IN T	RIPLICATE - Other instructi	ons on revers	se side	7. If Unit or CA/Agreement, Name and/or No.		
Oil Well Gas Well Other Name of Operator				8. Well Name and No. MCA Unit #188		
ConocoPhillips Co.				9. API Well No.		
a. Address 4001 Penbrook.	Odessa, TX 79762	b. Phone No. (inclu	ude arca code)	30–025–00709		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				10. Field and Pool, or Exploratory Area Maljamar G-SA		
1980' FSL & 1980' FWL SEC. 26, T-175, R-32E			11. County or Parish, State			
560. 20, 1-1/5,	K-32E			Lea, NM		
12. CHECK A	APPROPRIATE BOX(ES) TO IN	DICATE NAT	URE OF NOTICE, F	REPORT, OR OTHER DATA		
TYPE OF SUBMISSION		Т	YPE OF ACTION			
Notice of Intent		Осереп	Production (Sta			
		Fracture Treat	Reclamation	Well Integrity.		
Subsequent Report		New Construction Plug and Abandon	Recomplete Temporarily Al	U Other		
Final Abandonment Notice		Plug Back	Water Disposal			
SEE ATTACHED RE	PORT & WELLBORE DIAG	RAM		\$517181920212223		
			cabinty under	to plugging of the well backeoco r bond is retained Gatil ration is completed.		
 Thereby certify that the foregoin Name (Printed/Typed) 	ing is true and correct	J Title J	lames F. Newma Triple N Servi	an, P.E. ices, Inc. (432)-687-1994		
Signature			/13/04			
			TATE OFFICE USE			
	DAVID R. GLASS	Ti		Date		
ich would chung the applicant to		c subject lease O	ffice	· · · · · · · · · · · · · · · · · · ·		
ile 18 U.S.C. Section 1001 and T ites any false. fictitiou DAAradul PETROLEU structions on renerse	inte 43 U.S.C. Section 1212, make it a cri sut datements or representations as to any MENCINEER	me for any person l y matter within its ju	knowingly and willfully t arisdiction.	o make to any department or agency of the United		
	GWW					

1

 c_{-}

.

-

Daily Activity Report

ConocoPhillips MCA Unit #188 API #30-025-00709 Lea County, New Mexico

A.,

12/23/03 MIRU Triple rig #25 and plugging equipment. SDFN.

12/24/03 Notified BLM, Andy Cortez. RU Triple rig #25 and plugging equipment. Removed horse's head and laid down 49 ¾" to rod part. SD for Christmas.

12/29/03 Contacted BLM, Andrea. ND wellhead, NU BOP & enviro-vat. POOH w/ $24\frac{1}{2}$ jts (752') 2-3/8" production tubing, parted. Called out fishing tools. RIH w/ $3\frac{3}{4}$ " overshot on 2-3/8" workstring, tagged top of fish @ 1,304'. Made several attempts to catch fish, POOH w/ fishing tool and 6' piece of tubing. RIH w/ overshot, caught fish, POOH, recovered remaining joint plus 42 $\frac{1}{2}$ jts tubing, total recovery to date 2,081'. SDFN.

12/30/03 BLM Andy Cortez on location. RIH w/ kilo socket (Smith Services), caught rods at 1,830'. POOH w/ fishing tool, no rods. RIH w/ kilo socket, caught rods, POOH w/ tool and 34 ¾" rods. RIH w/ overshot, extensions, and workstring. Dressed off top of fish w/ tongs, unable to catch fish. POOH w/ overshot. Dressed overshot for collar. RIH, unable to catch fish. Top of fish at 2,640'. SDFN. Contacted BLM, Gary Gourley, instructed to continue fishing. Set up swivel for Wednesday.

12/31/03 RIH w/ Kutrite shoe, PU swivel, washed over top of tubing fish 2,640 – 2,645'. Circulated hole clean and ND stripper, POOH w/ shoe. SD for New Year's Day.

01/02/04 BLM Andy Cortez on location. RIH w/ Kutrite shoe, PU swivel, washed over top of tubing fish @ 2,645' for 2½ hrs. Circulated hole clean and ND stripper, POOH w/ shoe. RIH w/ overshot and latched onto fish. PU, pulled off, unable to catch fish. SD for weekend due to wind.

01/05/04 Contacted BLM, Armando Lopez, for procedure. POOH w/ fishing tools. RIH w/ tubing-set CICR to 2,608'. RU cementer, set CICR, established rate of 1 BPM @ 2,200 psi and squeezed 100 sx C cmt below CICR, final rate 1 BPM @ 2,200 psi, ISIP 2,050 psi. Stung out of retainer, dumped 10 sx C cmt on CICR 2,608 – 2,456', circulated hole w/ mud. POOH w/ tbg. Contacted BLM, Andy Cortez. RIH w/ wireline, perforated casing @ 2,290', POOH w/ wireline. RIH w/ packer. Attempted to set packer, split collar, POOH. RIH w/ tbg, screwed into fish, POOH w/ packer and replaced collar. RIH w/ packer to 1,863'. Set packer, established rate of 1 BPM @ 1,800 psi and squeezed 25 sx C cmt 2,290 – 2,190', ISIP 1,500 psi. SI well, SDFN.

01/06/04 Released packer, POOH. RU wireline and perforated casing @ 1,200', POOH w/ wireline. RIH w/ AD-1 packer to 845'. Loaded hole w/ mud, set packer, established circulation, and squeezed 50 sx C cmt 1,200 – 1,100', ISIP 950 psi. WOC 2 hrs and released packer, POOH. WOC 2 hrs and RIH w/ wireline, tagged cmt @ 1,040', PUH and perforated casing @ 60', POOH w/ wireline. ND enviro-vat & BOP, NU wellhead. Squeezed 45 sx C cmt 60' to surface. RDMO.

01/13/04 Cut off wellhead, capped well, installed marker. Cut off anchors and leveled cellar.

