P	VA'd. OK TO	RELEAS	E	
Submit 3 Copies To Appropriate District State of New I	Mexico Muss, 2,	4/2010	Form C-10	03
Office Energy, Minerals and Na	atural Resources	-	October 25, 20	07
District I 1625 N French Dr , Hobbs, NM 8726 CENTED VATION DIVISION District II		WELL API NO	O. 025-26561	
District II OIL CONSERVATION DIVISION District III JAN 19 ZUJU 1220 South St. Francis Dr. 1000 Rio Brazos Rd. Aziec, NM 87410		5. Indicate Type of Lease		\exists
District III UMN 1 9 2010 1220 South St. Francis Dr. 1000 Rio Brazos Rd, Aztec, NM 87410 Santa Fe, NM 87505		STATE FEE XX		
1000 Rio Brazos Rd, Aztec, NM 87410 District IV 1220 S St. Francis Dr, Santa Fe, NM 87505		6. State Oil & Gas Lease No.		
				_
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name: West Lovington Strawn Unit		
1. Type of Well: XX Oil Well Gas Well / Other		8. Well Number		
2. Name of Operator		9. OGRID Number		
Energen Resources Corporation		162928		
3. Address of Operator		10. Pool name or Wildcat		
3300 N."A" St., Bldg 4, Ste. 100, Midland, TX 79705 4. Well Location		Lovington, Strawn, West		
Unit Letter P: 660 feet from the Sou	ith line and 660	feet from the	Eastline_/	
Section 32 / Township 15S Range	35E NMPM	County	Lea	
11. Elevation (Show whether	er DR, RKB, RT, GR, etc 3956	c.)		*
12. Check Appropriate Box to Indicate Nature of Notic		Data		
NOTICE OF INTENTION TO:	l SUB	SEQUENT F	REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING				
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A				
PULL OR ALTER CASING MULTIPLE COMPL	CASING/CEMENT JO	ов 🗌		
OTHER:		dy for OCD insp	pection after P&A	
OTHER: All pits have been remediated in compliance with OCD rules				
All pits have been remediated in compliance with OCD rules Rat hole and cellar have been filled and leveled. Cathodic pro	and the terms of the Ope	rator's pit permi properly abando	t and closure plan.	
All pits have been remediated in compliance with OCD rules	and the terms of the Ope	rator's pit permi properly abando	t and closure plan.	
All pits have been remediated in compliance with OCD rules Rat hole and cellar have been filled and leveled. Cathodic pro	and the terms of the Ope otection holes have been ound level has been set in CR, API NUMBER, QU GE. All INFORMATIO	rator's pit permi properly abandon concrete. It sho	t and closure plan. oned. ows the RTER LOCATION OR	
All pits have been remediated in compliance with OCD rules Rat hole and cellar have been filled and leveled. Cathodic pro A steel marker at least 4" in diameter and at least 4' above gro OPERATOR NAME, LEASE NAME, WELL NUMBE UNIT LETTER, SECTION, TOWNSHIP, AND RANG	and the terms of the Ope otection holes have been ound level has been set in CR, API NUMBER, QU GE. All INFORMATIO SURFACE.	prator's pit permi properly abandon concrete. It sho ARTER/QUAR	t and closure plan. oned. ows the RTER LOCATION OR WELDED OR	
All pits have been remediated in compliance with OCD rules Rat hole and cellar have been filled and leveled. Cathodic pro A steel marker at least 4" in diameter and at least 4' above gro OPERATOR NAME, LEASE NAME, WELL NUMBE UNIT LETTER, SECTION, TOWNSHIP, AND RANG PERMANENTLY STAMPED ON THE MARKER'S S	and the terms of the Ope otection holes have been ound level has been set in CR, API NUMBER, QU GE. All INFORMATIO SURFACE.	prator's pit permi properly abandon concrete. It sho ARTER/QUAR	t and closure plan. oned. ows the RTER LOCATION OR WELDED OR	nd
All pits have been remediated in compliance with OCD rules Rat hole and cellar have been filled and leveled. Cathodic pro A steel marker at least 4" in diameter and at least 4' above gro OPERATOR NAME, LEASE NAME, WELL NUMBE UNIT LETTER, SECTION, TOWNSHIP, AND RANG PERMANENTLY STAMPED ON THE MARKER'S S The location has been leveled as nearly as possible to original other production equipment. Anchors, dead men, tie downs and risers have been cut off at the state of	and the terms of the Operator	prator's pit permi properly abandon concrete. It shows ARTER/QUAR IN HAS BEEN been cleared of and level.	t and closure plan. oned. ows the RTER LOCATION OR WELDED OR all junk, trash, flow lines an	nd
All pits have been remediated in compliance with OCD rules Rat hole and cellar have been filled and leveled. Cathodic pro A steel marker at least 4" in diameter and at least 4' above gro OPERATOR NAME, LEASE NAME, WELL NUMBE UNIT LETTER, SECTION, TOWNSHIP, AND RANG PERMANENTLY STAMPED ON THE MARKER'S S XX The location has been leveled as nearly as possible to original other production equipment. XX Anchors, dead men, tie downs and risers have been cut off at a standard sta	and the terms of the Operate of the	prator's pit permi properly abandon concrete. It shows ARTER/QUAR IN HAS BEEN been cleared of and level.	t and closure plan. oned. ows the RTER LOCATION OR WELDED OR all junk, trash, flow lines an	
All pits have been remediated in compliance with OCD rules Rat hole and cellar have been filled and leveled. Cathodic pro A steel marker at least 4" in diameter and at least 4' above gro OPERATOR NAME, LEASE NAME, WELL NUMBE UNIT LETTER, SECTION, TOWNSHIP, AND RANG PERMANENTLY STAMPED ON THE MARKER'S S XX The location has been leveled as nearly as possible to original other production equipment. XX Anchors, dead men, tie downs and risers have been cut off at the complex of the c	and the terms of the Operate of the	prator's pit permi properly abandon concrete. It shows ARTER/QUAR IN HAS BEEN been cleared of and level.	t and closure plan. oned. ows the RTER LOCATION OR WELDED OR all junk, trash, flow lines an	
All pits have been remediated in compliance with OCD rules Rat hole and cellar have been filled and leveled. Cathodic pro A steel marker at least 4" in diameter and at least 4' above gro OPERATOR NAME, LEASE NAME, WELL NUMBE UNIT LETTER, SECTION, TOWNSHIP, AND RANG PERMANENTLY STAMPED ON THE MARKER'S S XX The location has been leveled as nearly as possible to original other production equipment. XX Anchors, dead men, tie downs and risers have been cut off at S If this is a one-well lease or last remaining well on lease, the book of the Operator's pit permit and closure ple from lease and well location.	and the terms of the Operotection holes have been bund level has been set in CR, API NUMBER, QUE. All INFORMATION BURFACE. Il ground contour and has least two feet below group battery and pit location(s lan. All flow lines, products)	prator's pit permi properly abandon concrete. It shows that the property are also been cleared of and level. The property abandon concrete is properly abandon been remarked by the property are also been remarked	t and closure plan. oned. ows the RTER LOCATION OR WELDED OR all junk, trash, flow lines an ediated in compliance with at and junk have been remove	ed
All pits have been remediated in compliance with OCD rules Rat hole and cellar have been filled and leveled. Cathodic pro A steel marker at least 4" in diameter and at least 4' above gro OPERATOR NAME, LEASE NAME, WELL NUMBE UNIT LETTER, SECTION, TOWNSHIP, AND RANG PERMANENTLY STAMPED ON THE MARKER'S S XX The location has been leveled as nearly as possible to original other production equipment. XX Anchors, dead men, tie downs and risers have been cut off at the complex of the c	and the terms of the Operotection holes have been bund level has been set in CR, API NUMBER, QUE. All INFORMATION BURFACE. Il ground contour and has least two feet below group battery and pit location(s lan. All flow lines, products)	prator's pit permi properly abandon concrete. It shows that the property are also been cleared of and level. The property abandon concrete is properly abandon been remarked by the property are also been remarked	t and closure plan. oned. ows the RTER LOCATION OR WELDED OR all junk, trash, flow lines an ediated in compliance with at and junk have been remove	ed
All pits have been remediated in compliance with OCD rules Rat hole and cellar have been filled and leveled. Cathodic pro A steel marker at least 4" in diameter and at least 4' above gro OPERATOR NAME, LEASE NAME, WELL NUMBE UNIT LETTER, SECTION, TOWNSHIP, AND RANG PERMANENTLY STAMPED ON THE MARKER'S S XX The location has been leveled as nearly as possible to original other production equipment. XX Anchors, dead men, tie downs and risers have been cut off at IX If this is a one-well lease or last remaining well on lease, the BOCD rules and the terms of the Operator's pit permit and closure ple from lease and well location. XX All metal bolts and other materials have been removed. Portal	and the terms of the Operate of the	prator's pit permi properly abandon concrete. It shows that the property are also been cleared of and level. The property abandon concrete is properly abandon been remarked by the property are also been remarked	t and closure plan. oned. ows the RTER LOCATION OR WELDED OR all junk, trash, flow lines an ediated in compliance with at and junk have been remove	ed
All pits have been remediated in compliance with OCD rules Rat hole and cellar have been filled and leveled. Cathodic pro A steel marker at least 4" in diameter and at least 4' above gro OPERATOR NAME, LEASE NAME, WELL NUMBE UNIT LETTER, SECTION, TOWNSHIP, AND RANG PERMANENTLY STAMPED ON THE MARKER'S S The location has been leveled as nearly as possible to original other production equipment. Anchors, dead men, tie downs and risers have been cut off at If this is a one-well lease or last remaining well on lease, the BOCD rules and the terms of the Operator's pit permit and closure ple from lease and well location. All metal bolts and other materials have been removed. Portato be removed.) All other environmental concerns have been addressed as per Pipelines and flow lines have been abandoned in accordance well.	and the terms of the Operate of the	prator's pit permi properly abandon concrete. It shows a concrete. It shows a concrete in the	t and closure plan. oned. ows the RTER LOCATION OR WELDED OR fall junk, trash, flow lines an ediated in compliance with and junk have been remove insite concrete bases do not he	ed nave
All pits have been remediated in compliance with OCD rules Rat hole and cellar have been filled and leveled. Cathodic pro A steel marker at least 4" in diameter and at least 4' above gro OPERATOR NAME, LEASE NAME, WELL NUMBE UNIT LETTER, SECTION, TOWNSHIP, AND RANG PERMANENTLY STAMPED ON THE MARKER'S S XX The location has been leveled as nearly as possible to original other production equipment. XX Anchors, dead men, tie downs and risers have been cut off at a second of the operator's pit permit and closure ple from lease and the terms of the Operator's pit permit and closure ple from lease and well location. XX All metal bolts and other materials have been removed. Portato be removed.) XX All other environmental concerns have been addressed as per	and the terms of the Operate of the	prator's pit permi properly abandon concrete. It shows a concrete. It shows a concrete in the	t and closure plan. oned. ows the RTER LOCATION OR WELDED OR fall junk, trash, flow lines an ediated in compliance with and junk have been remove insite concrete bases do not he	ed nave
All pits have been remediated in compliance with OCD rules Rat hole and cellar have been filled and leveled. Cathodic pro A steel marker at least 4" in diameter and at least 4' above gro OPERATOR NAME, LEASE NAME, WELL NUMBE UNIT LETTER, SECTION, TOWNSHIP, AND RANG PERMANENTLY STAMPED ON THE MARKER'S S The location has been leveled as nearly as possible to original other production equipment. Anchors, dead men, tie downs and risers have been cut off at If this is a one-well lease or last remaining well on lease, the BOCD rules and the terms of the Operator's pit permit and closure ple from lease and well location. All metal bolts and other materials have been removed. Portato be removed.) All other environmental concerns have been addressed as per Pipelines and flow lines have been abandoned in accordance well.	and the terms of the Operate of the	been cleared of have been remuction equipmen oved. (Poured of NMAC. All fluedule an inspection	t and closure plan. oned. ows the RTER LOCATION OR WELDED OR fall junk, trash, flow lines an ediated in compliance with at and junk have been remove unsite concrete bases do not have unids have been removed from	ed nave
All pits have been remediated in compliance with OCD rules Rat hole and cellar have been filled and leveled. Cathodic pro A steel marker at least 4" in diameter and at least 4' above gro OPERATOR NAME, LEASE NAME, WELL NUMBE UNIT LETTER, SECTION, TOWNSHIP, AND RANG PERMANENTLY STAMPED ON THE MARKER'S S The location has been leveled as nearly as possible to original other production equipment. Anchors, dead men, tie downs and risers have been cut off at I if this is a one-well lease or last remaining well on lease, the B OCD rules and the terms of the Operator's pit permit and closure pl from lease and well location. All metal bolts and other materials have been removed. Portato be removed.) All other environmental concerns have been addressed as per Pipelines and flow lines have been abandoned in accordance vonon-retrieved flow lines and pipelines. When all work has been completed, return this form to the appropri inspection has to be made to a P&A location because it does not me	and the terms of the Operate of the	prator's pit permi properly abandon concrete. It shows a concrete in the concr	t and closure plan. oned. ows the RTER LOCATION OR WELDED OR fall junk, trash, flow lines an ediated in compliance with at and junk have been remove unsite concrete bases do not have unids have been removed from	ed nave n
All pits have been remediated in compliance with OCD rules Rat hole and cellar have been filled and leveled. Cathodic pro A steel marker at least 4" in diameter and at least 4' above gro OPERATOR NAME, LEASE NAME, WELL NUMBE UNIT LETTER, SECTION, TOWNSHIP, AND RANG PERMANENTLY STAMPED ON THE MARKER'S S XX The location has been leveled as nearly as possible to original other production equipment. XX Anchors, dead men, tie downs and risers have been cut off at IX If this is a one-well lease or last remaining well on lease, the book of the Operator's pit permit and closure ple from lease and well location. XX All metal bolts and other materials have been removed. Portato be removed.) XX All other environmental concerns have been addressed as per IX Pipelines and flow lines have been abandoned in accordance of non-retrieved flow lines and pipelines. When all work has been completed, return this form to the appropri inspection has to be made to a P&A location because it does not metal to be provided to the complete of the operatory. The location has to be made to a P&A location because it does not metal to be made to a P&A location because it does not metal to be provided to the complete of the operatory. The location has to be made to a P&A location because it does not metal to be made to a P&A location because it does not metal to be provided to the provided to	and the terms of the Operate of the	prator's pit permi properly abandon concrete. It shows a concrete in the concr	t and closure plan. oned. ows the RTER LOCATION OR WELDED OR all junk, trash, flow lines an ediated in compliance with at and junk have been remove uids have been removed from ion. If more than one essessed.	ed nave n
All pits have been remediated in compliance with OCD rules Rat hole and cellar have been filled and leveled. Cathodic pro A steel marker at least 4" in diameter and at least 4' above gro OPERATOR NAME, LEASE NAME, WELL NUMBE UNIT LETTER, SECTION, TOWNSHIP, AND RANG PERMANENTLY STAMPED ON THE MARKER'S S The location has been leveled as nearly as possible to original other production equipment. Anchors, dead men, tie downs and risers have been cut off at state of the operator's pit permit and closure ple from lease and the terms of the Operator's pit permit and closure ple from lease and well location. All metal bolts and other materials have been removed. Portate to be removed.) All other environmental concerns have been addressed as per Pipelines and flow lines have been abandoned in accordance on non-retrieved flow lines and pipelines. When all work has been completed, return this form to the appropri inspection has to be made to a P&A location because it does not me SIGNATURE Tracie Jenerry TYPE OR PRINT NAME E-For State Use (Poly)	and the terms of the Operate of the	prator's pit permi properly abandon concrete. It shows a concrete. It shows a concrete are a	t and closure plan. oned. ows the RTER LOCATION OR WELDED OR fall junk, trash, flow lines an ediated in compliance with at and junk have been remove unsite concrete bases do not have been removed from ion. If more than one ssessed. DATE	ed nave n
All pits have been remediated in compliance with OCD rules Rat hole and cellar have been filled and leveled. Cathodic pro A steel marker at least 4" in diameter and at least 4' above gro OPERATOR NAME, LEASE NAME, WELL NUMBE UNIT LETTER, SECTION, TOWNSHIP, AND RANG PERMANENTLY STAMPED ON THE MARKER'S S The location has been leveled as nearly as possible to original other production equipment. Anchors, dead men, tie downs and risers have been cut off at state of the operator's pit permit and closure ple from lease and the terms of the Operator's pit permit and closure ple from lease and well location. All metal bolts and other materials have been removed. Portate to be removed.) All other environmental concerns have been addressed as per Pipelines and flow lines have been abandoned in accordance on non-retrieved flow lines and pipelines. When all work has been completed, return this form to the appropri inspection has to be made to a P&A location because it does not me SIGNATURE Tracie Jenerry TYPE OR PRINT NAME E-For State Use (Poly)	and the terms of the Operate of the	been cleared of land level. have been remulation equipment oved. (Poured of NMAC. All fluedule an inspection enalty may be as my Analyst	t and closure plan. oned. ows the RTER LOCATION OR WELDED OR fall junk, trash, flow lines an ediated in compliance with at and junk have been remove unsite concrete bases do not have been removed from ion. If more than one ssessed. DATE	ed nave n