Form 3160-5 (August 2007)

# OCD-HORBCEIVED

#### **UNITED STATES** DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FEB 0 8 2010

FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010

### SUNDRY NOTICES AND REPORTS ON WELLS

SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.  SUBMIT IN TRIPLICATE – Other instructions on page 2.					6. If Indian, Allottee or Tribe Name  7. If Unit of CA/Agreement, Name and/or No.		
Oil Well Gas W	<i></i>			8. Well Name and No. Howe TG Federal #2			
2 Name of Operator Seely Oil Company					9. API Well No. 30-025-29038		
3a. Address 815 W 10th St Ft Worth, TX 76102	3b Phone No. (include area code) 817-332-1377			10. Field and Pool or Exploratory Area EK Bone Springs			
4. Location of Wely (Footage, Sec., T.,R.,M., or Survey Description) 810 FSL & 1830 FWL N-Sec 30- T18S-R34E				11. Country or Parish, State :ea County, New Mexico			
12. CHEC	K THE APPROPRIATE BO	X(ES) TO INDI	CATE NATUR	E OF NOTIC	E, REPORT OR OTHE	R DATA	
TYPE OF SUBMISSION			TY	PE OF ACTI	ON		
✓ Notice of Intent	Acidize Alter Casing	Deepe	ire Treat	=	duction (Start/Resume) Water Shut-Off		
Subsequent Report	Casing Repair Change Plans	=	New Construction Plug and Abandon		nplete orarily Abandon	Other	
Final Abandonment Notice	Convert to Injection		_		· Disposal		
following completion of the involve testing has been completed. Final determined that the site is ready for Seely Oil Company proposes to pluset CIBP @ 8275' w/ 35' cmt on top Perforate from 4692' - 4698' w/ 2 sp Acidize w/ 750 gallons NeFe. Fracture stimulate w/ 20,000 gallon Put well on production.	Abandonment Notices must be a final inspection.)  g back the well as follows.  b.  f (13 holes).  s gelled Kcl & 30,000 lbs s	and.		ts, including  Ď FOŘ	APP		
14. I hereby certify that the foregoing is true and correct. Name (Printed/Type David L. Henderson			Title Executive Vice President				
Signature Want L. Klandorson			Date 12/16/2009				
Early To the Control of the Control	THIS SPACE	FOR FEDE	RAL OR ST	ATE OFF	ICE USE		
Approved by  FEE  Title  Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify							)
that the applicant holds legal or equitable tentitle the applicant to conduct operations	itle to those rights in the subject				17		

Title 18 U.S C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false,

(Instructions on page 2)

fictitious or fraudulent statements or representations as to any matter within its jurisdiction

#### Howe TG Federal #2 30-025-29038 Seely Oil company February 5, 2010 Conditions of Approval

## IN FUTURE, BEFORE / AFTER DIAGRAMS NEED TO BE SUBMITTED.

- 1. Surface disturbance beyond the existing pad must have prior approval.
- 2. Closed loop system required.
- 3. Operator to have H2S monitoring equipment on location as H2S has been reported from the Delaware formation.
- 4. 3M Bop to be NU and tested prior to RIH.
- 5. Contact BLM 575-393-36112 a minimum of 4 hours prior to setting CIBP above the Bone Spring perfs.
- 6. Set CIBP @ 9,445' and bail 35' of cement (50' above the Bone Spring perfs)
- 7. Set CIBP @ \$,275' and bail 35' of cement (50' above the Bone Spring perfs)
- 8. Set 180' plug from 7,448' 7,628' (top of the Bone Spring)
- 9. Set 150' plug from 5384' 5534' (top of the Delaware)
- 10. Subsequent sundry and completion report required.
- 11. Submit final wellbore diagrams when work is complete.

MAK 020510