

Submit 3 Copies To Appropriate District
Office
District I
1625 N French Dr, Hobbs, NM 87410
District II
1301 W Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd, Aztec, NM 87410
District IV
1220 S. St. Francis Dr, Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
June 19, 2008

RECEIVED

OIL CONSERVATION DIVISION

FEB 16 2010 1220 South St. Francis Dr.

Santa Fe, NM 87505

HOBBSSOCD

WELL API NO. 30-025-29677
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name: South Hobbs (GSA) Unit
8. Well Number 210
9. OGRID Number 157984
10. Pool name or Wildcat Hobbs: Grayburg-San Andres
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3635.9' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/> Tx/d <input checked="" type="checkbox"/>	2. Name of Operator Occidental Permian Limited Partnership
3. Address of Operator P.O. Box 4294, Houston, TX 77210-4294	4. Well Location Unit Letter D : 721 feet from the North line and 569 feet from the West line Section 34 Township 18-S Range 38-E NMPM County Lea
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3635.9' GR	

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: Temporarily Abandon Well ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

See Attached

This Approval of Temporary
Abandonment Expires 2-1-2012
CIBP Set OVER 100' ABOVE TOP PERFS

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mark Stephens TITLE Regulatory Compliance Analyst DATE 2/9/10
Type or print name Mark Stephens E-mail address: Mark_Stephens@oxy.com PHONE (713) 366-5158


For State Use Only

APPROVED BY [Signature] TITLE OC FIELD REPRESENTATIVE / STAFF MANAGER DATE 2-17-10
Conditions of Approval (if any):

South Hobbs (GSA) Unit No. 210
API No. 30-025-29677

1/27/10 - 2/1/10: Temporarily abandon well as follows -

MI x RU. ND WH x NU BOP. POOH w/ESP equipment x 127 jts. 2-7/8" production tubing. RU Gray Wireline x run gauge ring to 4210'. POOH w/gauge ring x RIH with 7" CIBP x set at 4182'. Test squeezed perfs (4126' - 4180') - pump 175 bbls BW at 4 BPM x no pressure. Kill well with 170 bbls 10# brine. RIH with 7" CIBP x set at 4000'. Circulate 170 bbls packer fluid x test to 600 psi. Dump bail 6 sx. cement on top of CIBP x tag cement at 3948'. ND BOP x NU cap flange. Pressure test casing to 600 psi (test witnessed by the NMOCD's John Harrison, 2/1/10). RD x MO x clean location.



GRAPHIC CONTROLS CORPORATION
BUFFALO, NEW YORK

TEST DATE
2/1/10
BR 2221