Form 3160-5 (August 2007)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT DEC 28 21111

received

OMB No. 1004-0137 Expires: July 31, 2010

5. Lease Serial No. LC-064605A

6 If Indian, Allottee or Tribe Name

FORM APPROVED

## SUNDRY NOTICES AND REPORTS ON WHOSE SUCCED Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

7 If Unit of CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other instructions on page 2. 1. Type of Well Well Name and No. Oil Well Gas Well Other Federal A #2 2. Name of Operator Apache Corporation 9. API Well No 30-025-07239 3a Address 10. Field and Pool or Exploratory Area 3b. Phone No. (include area code) Bronco; Wolfcamp (7600) Tulsa, OK 74136 918,491,4968 4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description)
Unit B, Sec 14, t13S, R38E 11. Country or Parish, State Lea County, NM 660' FNL & 1274' FEL 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Acidize Water Shut-Off Deepen Production (Start/Resume) ✓ Notice of Intent Alter Casing Fracture Treat Reclamation Well Integrity New Construction Casing Repair Recomplete Other Subsequent Report Change Plans Plug and Abandon Temporarily Abandon Final Abandonment Notice Convert to Injection Plug Back Water Disposal 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones.

the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

Apache proposes to recomplete this well to the Wolfcamp via the following procedure:

- 1. RIH w/wireline and tag tip of cmt rtnr @ 9900'. Verify 35' of cmt on top of rtnr.
- 2. Shoot perfs selected by engineer.
- 3. RIH w/pkr and set @ +/-9390'. Acidize w/4k gals.
- 4. Swab load.
- 5. Assuming well swabs productive, POH w/pkr and tubing.
- 6. RIH w/prod tubing, pump and rods. RTP.

## SEE ATTACHED FOR CONDITIONS OF APPROVAL

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) Amber Cooke	Title Engineering Tech
Signature (MWW COOL)	Date 11/25/2009
THIS SPACE FOR FEDERAL OR STATE OFFICE USE	
Approved by PETRO	DLEUM ENGINEER APPROVED Title Date FEB 2 2 2010
Conditions of approval, if any, argattached Approval of this notice does not warrant or c that the applicant holds legal or equitable title to those rights in the subject lease which we entitle the applicant to conduct operations thereon.	ortify ould Office DEC 2 3 2009
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any perfectitious or fraudulent statements or representations as to any matter within its jurisdiction	The state of the s
(Instructions on page 2)	L CARLSBAD FIELD OFFICE

Apache Corporation NMLC-064605-A – Federal A #2 API: 30-025-07239 Lea County, New Mexico

RE: Plug back and Recomplete NOI – Conditions of Approval

There is to be no surface disturbance beyond the existing pad. A closed loop system is to be used. H2S monitoring and protection equipment is to be on site.

Closed loop system required.

H2S safety and monitoring equipment to be on location. H2S has been reported from this well.

Contact BLM (575-393-3612) a minimum 24 hours prior to work starting.

Submit subsequent report and completion report once work is completed.

DHW 120909