

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103

Revised March 25, 1999

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		<b>WELL API NO.</b> 30-025-04903
<b>1. Type of Well:</b> Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		<b>5. Indicate Type of Lease</b> STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
<b>2. Name of Operator</b> Chevron USA Inc		<b>6. State Oil &amp; Gas Lease No.</b> B-1732
<b>3. Address of Operator</b> 15 Smith Rd, Midland, TX, 79705		<b>7. Lease Name or Unit Agreement Name:</b> W.A. Ramsay NCT-A
<b>4. Well Location</b> Unit Letter <u>K</u> : <u>1980</u> feet from the <u>South</u> line and <u>1980</u> feet from the <u>West</u> line Section <u>34</u> Township <u>21-S</u> Range <u>36-E</u> NMPM <u>Lea</u> County		<b>8. Well No.</b> 34
<b>10. Elevation (Show whether DR, RKB, RT, GR, etc.)</b>		<b>9. Pool name or Wildcat</b> Eumont-Yates-7 Rvrs-Queen

## 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

## NOTICE OF INTENTION TO:


PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐TEMPORARILY ABANDON ☐ CHANGE PLANS ☐PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐OTHER: ☐

## SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒CASING TEST AND CEMENT JOB ☐OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

1. Set 5 1/2" CIBP at 3700, spot 25sx, plug from 3700-3500 (Queen) Tag at 3481.
2. Displace hole w/MLF 9.5# Brine w/25# gel P/BBL.
3. Spot 25sx, plug from 3200-3000 (B-Salt, Yates).
4. Spot 25sx, plug from 1600-1400 (T-Salt) Tag at 1386.
5. Perf 4 holes at 440, Circ cmt from 440-Surf w/150sx 5 1/2 x 8 5/8 csg (8 5/8 Shoe Surf) Tag at Surf.
6. Install dry hole marker 1-14-04.



Approved as to plugging of the Well Bore.  
Liability under bond is retained until  
surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jimmy Bagley TITLE Manager/Sunset DATE 1/14/04Type or print name Jimmy Bagley Telephone No. (432) 561-8600

(This space for State use)

APPROVED BY Hay W. Wink TITLED REPRESENTATIVE II/STAFF MANAGER  
 Conditions of approval, if any: OK DATE JAN 28 2004