

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
811 South First, Artesia, NM 87210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

WELL API NO. 30-025-20249
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-270
7. Lease Name or Unit Agreement Name: Vacuum Glorieta West Unit
8. Well No. 46
9. Pool name or Wildcat Vacuum Glorieta

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other	2. Name of Operator Chevron U.S.A. Inc.
3. Address of Operator 15 Smith Road - Midland, Texas 79705	4. Well Location Unit Letter N : 990 feet from the South line and 1650 feet from the West line Section 25 Township 17S Range 34E NMPM County Lea
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 4005' - GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Retrieve Open Hole Packer & TA Well ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

01-13-04 MIRU.
01-14-04 TOH w/120 jts 2-3/8" prod tbg.
01-15-04 Continue TOH w/60 jts prod tbg; lay down sub pump. Move out prod tbg; move in 59 jts 2-7/8" tbg & 190 jts 2-7/8" work string. PU retrieving tool head & 2-7/8" tbg & work string to 5705'.
01-16-04 Tag in window @ 5799'; could not work head thru window. TOH. TIH w/retrieving head & bent sub; went thru window. TIH to 7475'. TOH w/20 jts 5 stands. TOH w/retrieving head.
01-19-04 TOH w/tbg & OH packer. TIH w/5-1/2" csg scrapper to 5715'. TOH w/same. TIH w/5-1/2" CIBP w/WS. Set CIBP @ 5715'. Displaced hole w/FW. Pretest CIBP to 500# for 15 min (good).
01-20-04 Circ pkr fluid. TOH w/WS. Chart & test to 500 psi (good). Rig down. FINAL REPORT.

Well is Temporarily Abandoned.

This Approval of Temporary
Abandonment Expires 1/28/09

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Laura Skinner TITLE Regulatory Specialist

DATE 01-26-04

Type or print name Laura Skinner

(This space for State use)

APPROVED BY Gay W. Wink

Conditions of approval, if any:

FIELD REPRESENTATIVE II/STAFF MANAGER

DATE JAN 28 2004

