

Submit 3 Copies To Appropriate District Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Avenue, Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103  
Revised March 25, 1999

WELL API NO.  
30-025-30488

5. Indicate Type of Lease  
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.  
LG-4087

7. Lease Name or Unit Agreement Name:  
  
East Corbin Delaware Unit

8. Well No.  
11

9. Pool name or Wildcat  
West Corbin - Delaware

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
Oil Well ☐ Gas Well ☐ Other Injection Well

2. Name of Operator  
EOG Resources, Inc

3. Address of Operator  
P.O. Box 2267, Midland, TX, 79702

4. Well Location

Unit Letter L : 1980 feet from the North line and 660 feet from the West line

Section 16 Township 18-S Range 33-E NMPM Lea County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒


CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

1. Circ hole w/mud laden fluid, spot 75sx from 5550-4950, WOC Tag at 5015.
2. Cut and pull 5 1/2" csg at 3000.
3. Spot 75sx across 5 1/2" csg stub and 8 5/8 shoe from 3050-2850, WOC Tag at 2928, re-spot 50sx from 2928-2750, WOC Tag at 2763.
4. Spot 35sx from 1475-1375.
5. Spot 35sx from 400-300.
6. Circ 20sx from 60-Surf.
7. Install dry hole marker, clean location. 1-13-04

Approved as to plugging of the Well Bore  
Liability under bond is retained until  
surface restoration is completed.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE Manager/Sunset DATE 1/13/04

Type or print name Jimmy Bagley Telephone No. (432) 561-8600  
(This space for State use)

APPROVED BY [Signature] TITLE OC FIELD REPRESENTATIVE II/STAFF MANAGER DATE JAN 28 2004  
Conditions of approval, if any: