Form 3160-5 (February 2005)

Conditions of approval, if any:

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

RECEIVED OCD-HORBS MAR 0 1 2010

OM EXPIR

FORM APROVED
OMB NO. 1004-0135
EXPIRES: March 31, 200

BUREAU OF LAND MANAGEMENT
SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an

HOBBSOCD

EXPIRES.	March 51,	2007
Lease Serial No.		
N	M-63020	

abandoned well. Use Form 3160-3 (APD) for such proposals	o. It maian, Anottee of This Name	
SUBMIT IN TRIPLICATE	7. Unit or CA Agreement Name and No.	
1a. Type of Well Oil Well Gas Well Other	8 Well Name and No.	
2. Name of Operator DEVON ENERGY PRODUCTION COMPANY, LP	Bilbrey 28A Federal 1 9. API Well No.	
3 Address and Telephone No.	30-025-30664	
20 North Broadway, Oklahoma City, OK 73102-8260 405-552-8198	10. Field and Pool, or Exploratory	
Location of Well (Report location clearly and in accordance with Federal requirements)*	Bilbrey Morrow (Gas)	
1980' FSL & 1980' FWL Unit K Sec 28 T21S R32E	11. County or Parish State	
	Lea NM	
12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA		
TYPE OS SUBMISSION TYPE OF ACTION		
	n (Start/Resume) Water Shut-Off	
Alter Casing Fracture Treat Reclamation		
Change Plans Plug and Abandon Temporal	rily Abandon	
Final Abandonment Notice Convert to Injection Plug Back Water Dis	sposal	
Bond No. on file with BLM/BIA Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirement, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection) Devon Energy Production Company, LP respectfully requests approval to plug back the Morrow and Agrecomplete the Delaware formation per the following procedure. Bibrey Jorth MIRU. ND wellhead. NU BOP. TOOH with tubing. RU wireline and RIH with 4 1/2" CIBP and set at +/- 13,870'. Dump bail 35' of cement on plug. RIH with 7" CIBP and set at +/- 12,060'. Dump bail 35' of cement on plug. RD wireline. RU and perforate Delaware from 8,571' - 8,611'; 2 spf - 0.43 EHD holes. RIH with treating packer and set at ~ 8,433'. Acidize with 2,000 gals 7.5% HCI. Evaluate and Frac per recommendation. Flow well back. Unset packer and POOH with packer and tubing. RIH with tubing; SN at ~ 8,700'. ND BOP and NU wellhead. RIH with rods and pump. RDMO. Hang well on production.		
SEE ATTACHED FOR CONDITIONS OF APPROVAL 14. Thereby certify that the foregoing is true and correct Name Norvella Adams Title Sr. Staff Engineering Technician (This space for Federal or State Office use)	Date APPROVIDED	
Approved by Title	Date FFR 2 5 2010	

within its jurisdiction.

*See Instruction on Reverse Side

MAR U 3 2010

BUREAU OF LAND MANAGEMENT

CARLSBAD FIELD OFFICE

Bilbrey 28A Federal 1 30-025-30664 Devon Energy Production Co. February 18, 2010 Conditions of Approval

At final abandonment or when the well is sold the operator is to drill out the 7" CIBP and address plugs across the top of the Morrow, Wolfcamp and Bone Spring Formations, and also a plug across the 7" casing shoe and the liner stub.

- 1. The 7" CIBP is to be set above the liner stub.
- 2. Surface disturbance beyond the existing pad must have prior approval.
- 3. Closed loop system required.
- 4. A minimum of a 5M BOP is required and must be tested prior to performing operations. All blowout preventer (BOP) and related equipment (BOPE) shall comply with well control requirements as described in Onshore Oil and Gas Order No. 2 and API RP 53 Sec. 17.
- 5. Operator to have H2S monitoring equipment on location as H2S has been reported from wells in the area.
- 6. Subsequent sundry and completion report required.

CRW 021810