

Office
District I

1625 N French Dr, Hobbs, NM 88240

District II

1301 W Grand Ave, Artesia, NM 88210

District III

1000 Rio Brazos Rd, Aztec, NM 87410

District IV

1220 S St Francis Dr, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural ResourcesForm C-103
October 13, 2009

RECEIVED

OIL CONSERVATION DIVISION

MAR 11 2010

HOBBSD

220 South St. Francis Dr.

Santa Fe, NM 87505

WELL API NO.
30-025-28434

5. Indicate Type of Lease

STATE ☒ FEE ☐ ☒6. State Oil & Gas Lease No.
E-6002

7. Lease Name or Unit Agreement Name

B LEE STATE

8. Well Number 007

9. OGRID Number

155615

10. Pool name or Wildcat

SCHARB, BONESPRING Queen

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)1. Type of Well: Oil Well ☒ Gas Well ☒ Other ☐

2. Name of Operator

NADEL AND GUSSMAN PERMIAN, LLC

3. Address of Operator

601 N. MARIENFELD, STE. 508 MIDLAND, TX 79701

4. Well Location

Unit Letter H: 1980 feet from the NORTH line and 660 feet from the EAST line

Section 5 Township 19S Range 35E NMPM County LEA

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

The Oil Conservation Division **Must be notified 24 hours prior** to the beginning of plugging operations.

- 1.) TAG CIBP-CIRCULATE PLUGGING MUD
- 2.) SPOT 25 SXS CLASS C CEMENT @ 4050'-TAG
- 3.) SPOT 25 SXS CLASS C CEMENT @ 3417'
- 4.) PERF-SPOT 35 SXS CLASS C CEMENT @ 1907'-TAG
- 5.) PERF @ 500'-PUMP 25 SXS CLASS C CEMENT-TAG
- 6.) PERF @ 60'-CIRCULATE 25 SXS CLASS C CEMENT TO SURFACE
- 7.) CUT OFF ANCHORS-INSTALL P&A MARKER

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE

AGENT

DATE 3-10-2010

Type or print name

JERRI JENNINGS

E-mail address:

PHONE:

For State Use Only

APPROVED BY:

TITLE

STAFF MEMBER

DATE


3-15-10

Conditions of Approval (if any):

NADEL AND GUSSMAN PERMIAN

B LEE STATE No. 7
1980' FNL, 800' FEL, Unit H, Sec 5, 19S, 35E, Lea County, NM
API # 30-025-28434

Elev: 3893.5 GL, 3906.5 KB



1) TAG CIBP - Circ Plug
Mud

2) Spot 25sx @
4050' CTAG

3) Spot 25sx @
3417'

4) Perf @ Spot 35sx
@ 1907' CTAG

5) Perf @ 500'
Pump 25sx CTAG

6) Perf @ 60'
Circ 25sx To
Surface

7) Cut off
anchors,
install A+A
marker