

Submit 3 Copies To Appropriate District
Office
District I
1625 N French Dr, Hobbs, NM 87240
District II
1301 W Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd, Aztec, NM 87401
District IV
1220 S St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
June 19, 2008

RECEIVED

OIL CONSERVATION DIVISION

1220 South St. Francis Dr.
Santa Fe, NM 87505

MAR 12 2010

HOBSOCD

WELL API NO. 30-025-27828
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. LG-1145
7. Lease Name or Unit Agreement Name: Comanche State Unit (38021)
8. Well Number 4
9. OGRID Number 7377
10. Pool name or Wildcat North Legg (Delaware)
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3840.4' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other Dry Hole	7. Lease Name or Unit Agreement Name: Comanche State Unit (38021)
2. Name of Operator EOG Resources, Inc.	8. Well Number 4
3. Address of Operator P.O. Box 2267 Midland, TX 79702	9. OGRID Number 7377
4. Well Location Unit Letter H : 1980 feet from the North line and 660 feet from the East line Section 9 Township 21S Range 33E NMPM County Lea	10. Pool name or Wildcat North Legg (Delaware)
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3840.4' GR	

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. Set CIBP @ +/- 8620' and cap w/ 35' of cement.
2. Cut and pull 5-1/2" casing @ +/- 5950'.
3. Spot 40 sx cement plug at 5-1/2" casing stub. Tag.
4. Spot 60 sx cement plug from 5530' to 5671'. Tag.
5. Spot 40 sx cement plug from 3760' to 3860'. Tag.
6. Spot 40 sx cement plug from 2520' to 2620'. Tag.
7. Pump 195 sx cement plug from 601' to surface.
8. Cut off wellhead and weld on dry hole marker.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Stan Wagner TITLE Regulatory Analyst DATE 3/9/10

Type or print name Stan Wagner E-mail address: _____ PHONE 432-686-3689

For State Use Only

APPROVED BY [Signature] TITLE STAFF MGR DATE 3-15-10


Conditions of Approval (if any):

THE OIL CONSERVATION DIVISION MUST
BE NOTIFIED 24 HOURS PRIOR TO THE
BEGINNING OF PLUGGING OPERATIONS



Comanche State Unit No. 4

1,980' FNL & 660' FEL
Sec. 9, T21S, R33E
Lea County, New Mexico
API 30-025-27828





Comanche State Unit No. 4

1,980' FNL & 660' FEL

Sec. 9, T21S, R33E

Lea County, New Mexico

API 30-025-27828

Proposed P&A

