

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103

Revised March 25, 1999

WELL API NO. 30-025-36272

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name:
FORT 21

8. Well No.

1

9. Pool name or Wildcat
WILDCAT

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

PECOS PRODUCTION COMPANY

3. Address of Operator

400 W. ILLINOIS, SUITE 1070, MIDLAND, TEXAS 79701

4. Well Location

Unit Letter G : 2310 feet from the NORTH line and 1978 feet from the EAST line

Section 21 Township 14S Range 34E NMPM LEA County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)
4124' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐TEMPORARILY ABANDON ☐ CHANGE PLANS ☐PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒CASING TEST AND CEMENT JOB ☐OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- 1.) RIG UP P & A EQUIPMENT; DIG AND LINE WORK PIT; NIPPLE UP BOP.
- 2.) SET CIBP AT 13450'; CIRCULATE HOLE WITH 9.5# MUD; SPOT 25 SACKS ON CIBP. 12/16/2003
- 3.) SPOT 30 SACKS OF CEMENT FROM 12700' TO 12800'. 12/16/2003
- 4.) SPOT 30 SACKS OF CEMENT FROM 9900' TO 10000'. 12/16/2003
- 5.) SPOT 30 SACKS OF CEMENT FROM 6900' TO 7000'. 12/16/2003
- 6.) SPOT 30 SACKS OF CEMENT FROM 4450' TO 4550'; TAG TOC AT 4404'. 12/17/2003
- 7.) CUT AND PULL 5 1/2" CASING FROM 1950'; SPOT 40 SACK PLUG 50' IN CASING STUB; TAG AT 1792'. 12/19/2003
- 8.) SPOT 40 SACKS OF CEMENT AT 455'; TAG AT 335'. 12/19/2003
- 9.) CUT OFF WELLHEAD; SPOT 10 SACK SURFACE PLUG; INSTALL P & A MARKER. 12/19/2003

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE

DATE

Type or print name

(This space for State use)

PETROLEUM ENGINEER

Telephone No.

APPROVED BY

TITLE

DATE

Conditions of approval, if any:

Approved as to plugging of the Well Bore.
Liability under bond is retained until
surface restoration is completed.

