RECEIVED

MAR 3 0 2010

Conditions of Approval (if any):

P/A'd. OK TO RELEASE.
MSB 4/1/2010
(See inspection 12/17/2009)

Submit One Copy To Appropriate District HOBBSOCD Office Form C-103 State of New Mexico March 18, 2009 Energy, Minerals and Natural Resources District I WELL API NO. 1625 N. French Dr., Hobbs, NM 88240 30-025-39445 OIL CONSERVATION DIVISION District II 5. Indicate Type of Lease 1301 W Grand Ave, Artesia, NM 88210 1220 South St. Francis Dr. FEE District III STATE | 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 6. State Oil & Gas Lease No. District IV 1220 S. St Francis Dr., Santa Fe, NM 87505 7. Lease Name or Unit Agreement Name SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A Berry DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH 8. Well Number #1 1. Type of Well: Oil Well Gas Well Other 9. OGRID Number 2. Name of Operator 113315 Texland Petroleum-Hobbs, LLC 10. Pool name or Wildcat 3. Address of Operator Wildcat, Bone Spring 777 Main Street, Suite 3200, Fort Worth, Texas 76102 4 Well Location Unit Letter \underline{I} : 2310 feet from the South line and 840 feet from the East line Township 17S Range 39E NMPM Lea County NM 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data SUBSEQUENT REPORT OF: NOTICE OF INTENTION TO: ALTERING CASING | REMEDIAL WORK PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ COMMENCE DRILLING OPNS. P AND A CHANGE PLANS TEMPORARILY ABANDON CASING/CEMENT JOB PULL OR ALTER CASING MULTIPLE COMPL □ Location is ready for OCD inspection after P&A OTHER: All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.) All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from nonretrieved flow lines and pipelines. When all work has been completed, return this form to the appropriate District office to schedule an inspection. TITLE Regulatory Analyst DATE 3/30/2010 SIGNATURE TYPE OR PRINT NAME Vickie Smith _____EMAIL: ___vsmith@texpetro.com_____ PHONE: __575-397-7450_ 1 TITLE Compliance Of