Submit 1 Copy To Appropriate District Office District I State of New Mexico District I Energy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 88240 OIL CONSERVATION DIVISION District II 001 CONSERVATION DIVISION 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION District II 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 8440 2 6 (101) 1220 South St. Francis Dr. Sistrict IV 1220 South St. Francis Dr. 1200 S. St. Francis Dr., Santa Fel OBBSOLOW Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other Injection 2. Name of Operator ConocoPhillips Company 3. Address of Operator PO. 3. Address of Operator PO. Box 51810 Midland, Tx 79710 4. Well Location	Form C-103 October 13, 2009 WELL API NO. 30-025-20516 5. Indicate Type of Lease STATE FEE 6. State Oil & Gas Lease No. B-2229 7. Lease Name or Unit Agreement Name Philmex 8. Well Number # 9 9. OGRID Number 217817 10. Pool name or Wildcat Maljamar; Grayburg/San Andres	
	1980 feet from the East line NMPM Lea County	
RKB 4133 • 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBS PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRIL PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT DOWNHOLE COMMINGLE COMMINGLE	LING OPNS. P AND A	
OTHER: OTHER: Workover & MIT		
 Workover 2/24/2010-3/17/2010: MIRU. Well shut in. Appeared to have casing issue in the RIH w/tubing, pkr, & plug to 4849. Set plug at 4732. Moved pkr/plug up hole at intermediat follows: 4651'lost minimal pressure 4586' lost minimal pressure 4488' lost minimal pressure 4424' good test 2486' good test 1526' good test 1526' good test 10' good test POOT and SWION. RIH w/plug and tbg to 500' and set plug. Pump ½' casing. Pressure up to 500 psi. Ran downt o 500' and cleaned out sand. Tested to 500 ps at 500' and 4441'. Set pkr at 4443.58. Tested well to 500 psi for 30 miutes. Good test. Pump RDMO. Ran MIT on 3/15/2010. Good test. Chart attached. Test witnessed by representation. 	the intervals in an attempt to isolate the leak as beed 20 sxs cmt with 3% calcium in & out of 5 bit for 30 minutes. Good test. Retrieved plugs beed 1000 gls acid. Flushed w/25 bbls of water.	
Spud Date: Rig Release Date:		
I hereby certify that the information above is true and complete to the best of my knowledge SIGNATURE TITLE_Sr. Regulatory Spectrum Type or print name Donna Williams E-mail address: Donna.J.Will For State Use Only TITLE_ST. Regulatory Spectrum Donna.J.Will APPROVED BY: Time Time TITLE_ST. Regulatory Spectrum Conditions of Approval (if any): TITLE_ST. Regulatory Spectrum Donna.J.Will	ecialist DATE 3/24/2010	

~____/

1

Gonzales, Elidio L, EMNRD

From:	Jones, William V., EMNRD
Sent:	Thursday, April 01, 2010 4:59 PM
То:	Hill, Larry, EMNRD; Gonzales, Elidio L, EMNRD
Cc:	Ezeanyim, Richard, EMNRD; Kautz, Paul, EMNRD; Williams, Donna J; Brooks, David K.,
	EMNRD
Subject:	Packer Setting on Philmex #9 30-025-20516

Hello Again:

Researched this issue this afternoon and confirmed what Donna said.

What I found is the SWD-126 in 1972 approved disposal into the San Andres 4960 to 5090 and the well was near or in the Vacuum (GSA) area. It had some upper San Andres perfs that were squeezed but later broke down – so was likely disposing/injecting into a producing oil interval (my assumption).

Phillips requested (on 7/5/88) formal approval for the well to be reclassified as an injection well and included in the Philmex Waterflood project – and clearly stated the upper perfs would be part of the waterflood. One fact to keep in mind is the Philmex Waterflood Project in the Maljamar (GSA) Pool is approved for both the Grayburg and the San Andres with injection as high as 4236.

On 8/6/91, the OCD finally replied to this request, granting the move and stated "the physical characteristics including the perforated interval remain the same". (By that time the upper perfs had been open for several years.)

The Vacuum(GSA) and the Maljamar (GSA) apparently had some overlap so wells were moved and perfs were added....

Donna Williams states this well may now have the packer set at 4443 feet with top perfs at 4542 feet. This top injection depth is still below the top of the Philmex Waterflood.

I did not do a detailed stick diagram showing perf depths in this area – but from what I see this well may be contributing to oil recovery as part of a waterflood. The language in the permission letter was unfortunate and confusing without looking over the application and the well.

One thing I did see is the PBTD on this well (cased) may be at 5800 feet which is down in the Glorieta. The well should have originally been plugged back to within a closer distance below the bottom of the injection interval. It would be prudent to someday verify this plug still is in place. We are being careful about operators obeying written orders and careful about the packer setting depths – but may not be too careful about depths below the permitted intervals.

Anyway - I think this situation is OK. You folks may have found additional facts and have other concerns.

Conoco could take the lead and clean up items like this by re-certifying old waterfloods to the modern UIC standards at an examiner hearing. This preparation would prompt its engineers into closely examining the tubulars and the reservoir.

Happy Easter.

