Submit 3 Copies To Appropriate District State of New Me Office District District District State of New Me	
District 1 <u>District 1</u> 1625 N. French Dr., Hobbary & 88240 and market and Natu	
District II District II 1625 N. French Dr., Hobbsen N488240 District II 1301 W. Grand Ave., Artesia, NM 88210 District III 1301 W. Grand Ave., Artesia, NM 88210 District III 1220 South St. Fran	DIVISION 30-025-03151 V 5. Indicate Type of Lease
1000 Die Deres Bel Aster MARAIA I CUIU 1220 South St. 114	STATE X FEE
1220 S. St. Francis Dr., Santa DBBSUCD	505 6. State Oil & Gas Lease No. South Vacuum Unit 35
87505 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLU DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FO	JG BACK TO A State C Hh Vacuum
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other SWD	8. Well Number 28WD 352
2. Name of Operator Paladin Energy Corp. /	9. OGRID Number 164070
3. Address of Operator	10. Pool name or Wildcat SWD
10290 Monroe Dr., Ste. 301, Dallas, Texas 75229	Vacuum Devonian, South 296101
4. Well Location	
Unit Letter I : <u>1980</u> feet from the <u>South</u> line and <u>660</u> feet from the <u>East</u> line $$ Section 35 Township 18S Range 35E NMPM Lea County	
Section 35 Township 18S Range 35E NMPM Lea County 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 11. Elevation (Show whethet C, Sh	
3862' GR	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
PERFORM REMEDIAL WORK [] PLUG AND ABANDON [] TEMPORARILY ABANDON [] CHANGE PLANS []	REMEDIAL WORK I ALTERING CASING COMMENCE DRILLING OPNS. P AND A I
PULL OR ALTER CASING MULTIPLE COMPL	
OTHER: OTHER: Convert to SWD Image: Convert to SWD 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of	
starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.	
Step 1 MIRU on location. N/D wellhead, N/U BOP's, POOH with 2-3/8" tubing and 7" packer & 2-7/8" tubing and 5" packer. WIH with 2-7/8" work string and set cast iron bridge plug at 13,540', dump bailed 50' of cement (top of cement at 13,490'). Isolated Mckee perforations - 13,640-821'. WBIH and set second CIBP at 12,040', dump bailed 45' of cement (top of cement at 11,995').	
Step 2 R/U electric line and WIH with 3-1/8" perforating guns. Perforated Devonian formation from 11,630-11,840' 2SPF. POOH w/ e- line. WIH with work string & acidizing packer. Rigged up acid pump truck, pumped 6000 gal. 15% NEFE Acid.	
Step 3 Rigged up swab unit and swabbed back acid. Pulled tubing and packer. Picked up 3-1/2" plastic coated tubing and 7" plastic coated packer (injection string). Ran in hole and set Packer at 11,580'. N/D BOPS, N/U wellhead. Tested annulus to 600 psi for 30 minutes. Tested OK.	
Step 4 Installed surface tanks and vessels and began injection in accordance with <u>Administrative Order SWD-1188</u> .	
Spud Date: 2/9/2010 Rig Release Date:	ate: 2/25/2010
Non · Well PDD=2809601	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
SIGNATURE Dan Plan - TITLE V. P. Exploration & Production DATE 3/24/2010	
Type or print name <u>David Plaisance</u> E-mail address: <u>dplaisance@paladinenergy.com</u> PHONE: <u>214-654-0132</u>	
APPROVED BY: TITLE STAFF MOR DATE 4-1-10	
APPROVED BY TITLE STAFF MGT DATE 4-1-10 Conditions of Approval (if any). 2A Vacuum Machee South (GAS)	
- mriveralm	

