

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised May 08, 2003

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-11668
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name B.M. Justis "A"
8. Well Number 002
9. OGRID Number 002175
10. Pool name or Wildcat Jalmat Tansill Yates 7 Rivers

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☒ Gas Well ☐ Other

2. Name of Operator
Bettis, Boyle & Stovall

3. Address of Operator
P.O. Box 1240, Graham, TX 76450

4. Well Location

Unit Letter H : 1980 feet from the North line and 660 feet from the East line
Section 20 Township 25S Range 37E NMPM Lea County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3056 GR

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- 1) Notify OCD 24 hrs. prior to beginning P&A operations.
- 2) MIRU pulling unit.
- 3) Tag plug in hole @ 2800' & set 25 sx of cement on top of plug.
- 4) Set 25 sx plug @ base of salt - 2580'
- 5) Set 25 sx plug @ top of salt - 1223'
- 6) Casing shoe @ 300', perf @ 350' & bring cement 50' on the outside & inside of the casing & tag cement @ 250'.
- 7) Set 10 sx plug from 60' to surface.
- 8) Cut off well casing 4' below ground level & weld on plate.
- 9) Clean up location.

Estimated date to plug & abandon is April 21, 2004.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kim Ligon TITLE Regulatory Analyst DATE 1/27/04

Type or print name Kim Ligon

Telephone No. 940-549-0780

(This space for State use)

APPROVED BY [Signature] FIELD REPRESENTATIVE II/STAFF MANAGER DATE 30 2004

Conditions of approval, if any:

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.



(3 STRING CSNG)

SECT 20 TWN 255 WELL # 002
FROM 1980 N 660 RNG 37E
TD: 3030 FORMATION @ TD _____
PBTD: 2800 FORMATION @ PBTD _____

8 5/8"
@1255
TOC *mm*

2800'
 7"
 2890-3030 @ 2890
 TOC

TD 3030

	SIZE	SET @	TOC	TOC DETERMINED BY	
SURFACE	12 1/4	300	mm	mm	
INTMED 1	8 5/8	1255	mm	mm	
INTMED 2					
PROD	7	2890		(75 24)	
	SIZE	TOP	BOT	TOC	DETERMINED BY
LINER 1	5 1/2	2860	3030		
LINER 2					
	CUT & PULL @			TOP - BOTTOM	
INTMED 1			PERFS	-	
INTMED 2			OPENHOLE	2890 - 3030	
PROD					

RUSTLER (ANHYD)	975	*
YATES		
QUEEN		
GRAYBURG		
SAN ANDRES		
CAPTIAN REEF		*
DELAWARE		
BELL CANYON		
CHERRY CANYON		
BRUSHY CANYON		
BONE SPRING		
GLORIETA		
BLINEBRY		
TUBB		
DRINKARD		
ABO		
WC		
PENN		
STRAWN		
ATOKA		
MORROW		
BOSS		
DEVORIAN		

[illegible]