

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised June 10, 2003

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-24582
5. Indicate Type of Lease STATE ☐ FEE ☐
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☐ Gas Well ☐ Other

7. Lease Name or Unit Agreement Name

Nancy

8. Well Number

1

2. Name of Operator

C.W. Trainer

9. OGRID Number

3. Address of Operator

P.O. Box 754 Midland TX 79702

10. Pool name or Wildcat

Tres Papalotes

4. Well Location

Unit Letter **F** : **2144** feet from the **North** line and **1874** feet from the **West** line

Section **5**

Township **15 S** Range **34 E** NMPM **Lea County**

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPERATIONS ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Approved as to plugging of the Well Bore
Liability under bond is retained until
surface restoration is completed.

Jan 20, 2004
1. Ran 2 7/8" tbg in hole to 742.06
2. Spotted 65 sack cement plug from 742' to 642'
3. Pulled 4 jts tbg. & circulated hole w. 9.5 # mud
4. PWH w tbg to 435' & spotted 50 sack cement plug. waited 3 hours & tagged top of cement @ 350'
5. Spotted 10 sack cement plug at surface.
6. Set dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

John Gould Jr

TITLE

Consultant

DATE **Jan 22 2004**

Type or print name

John Gould Jr

E-mail address:

Telephone No. **432 687 2004**

(This space for State use)

APPROVED BY

Larry W. Wink

TITLE

OC FIELD REPRESENTATIVE II/STAFF MANAGER

Conditions of approval, if any:

JAN 30 2004

PLUGGING & ABANDONMENT WORKSHEET (3 STRING CSNG)
 OPERATOR C. W. Trainer
 LEASENAME Nancy

 WELL # 1
 SECT 5 TWN 15 S RNG 34 E
 FROM 2086 N/S L 2086 E/W L
 TD: 10500 FORMATION @ TD
 PBDT: 10497 FORMATION @ PBDT

	SIZE	SET @	TOC	TOC DETERMINED BY	
SURFACE	13 3/8	350	Surf	Visual	
INTMED 1	9 5/8	4491	3500	est	
INTMED 2					
PROD	5 1/2	10700	9000	est	
	SIZE	TOP	BOT	TOC	DETERMINED BY
LINER 1					
LINER 2					
	CUT & PULL @			TOP - BOTTOM	
INTMED 1	420'	9 5/8	PERFS	-	
INTMED 2			OPENHOLE	-	
PROD	4550	5 1/2			

*** REQUIRED PLUGS DISTRICT ***

RUTLER (ARRIVE)	
YATES	
QUEEN	
GRAYBRO	
SAN ANDREW	
CAPTAIN REEF	
DELAWARE	
BELL CANYON	
CHERRY CANYON	
BERRY CANYON	
BONE SPRING	
OLDMETH	
BLISSLEY	
TUBS	
DEWEARD	
ARG	
WC	
PERIN	
STRAWN	
AYOEA	
MACROW	
SCIS	
CHICKMAN	

PLUG	TYPE	SACKS	DEPTH
PLUG	PLUG	CMNT	
EXAMPLES			
PLUG #1	OH	25 SXS	9850'
PLUG #2	SHOE	50 SXS	8700'-8800'
PLUG #3	CIBP/35'		3300'
PLUG #4	CIBP	25 SXS	3300'
PLUG #5	STUB	50 SXS	4600'-4700'
PLUG #6	RETNR BOX	300 SXS	400
PLUG #7	SURF	10 SXS	0-10'
PLUG #8			
PLUG #9			
PLUG #10			
PLUG #11			
PLUG #12			
PLUG #13			
PLUG #14			
PLUG #15			
PLUG #16			
PLUG #17			
PLUG #18			
PLUG #19			
PLUG #20			
PLUG #21			
PLUG #22			
PLUG #23			
PLUG #24			
PLUG #25			
PLUG #26			
PLUG #27			
PLUG #28			
PLUG #29			
PLUG #30			

