OCD Hobbs

Lorm 3160-5 (April 2004)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

r, three man and	FORM APPROVED OMB No. 1004-0137 Expires March 31, 200
------------------	---

Other

	ı	EXPRICS	Maiche
5	Lease Senal	No	
	NM1826	4	

Do not use this form for abandoned well. Use Form	proposals to drill or to re-enter an π 3160-3 (APD) for such proposals.	6 If Indian, Aflottee or Tube Name	
abandoned well. Use Form 3160 - 3 (APD) for such proposals. SUBMIT IN TRIPLICATE- Other instructions on reverse side. 1 Type of Well Gas Well Other 2 Name of Operator Finley Resouces, Inc. 3a Address PO Box 2200, Fort Worth, TX 76113 3b Phone No (include area code) 817-336-1924		7 H Unit or CA/Agreement Name and/or No	
1 Type of Well Oil Well 11 Gas Well 13	8 Well Name and No Federal D 12 9 API Well No		
2 Name of Operator Finley Resouces, Inc.			
3a Address PO Roy 2200 Fort Worth, TX 76113		30-025-25737 ✓ 10 Field and Pool or Exploratory Area	
4 Location of Well (Footage, Sec., T., R., M. or Survey Description) 990' FNL & 330' FEL of Section 27 - 20S - 36E		Eumont(Yates, Queen) 11 Counity or Parish State Lea	
12. CHECK APPROPRIATE	BOX(ES) TO INDICATE NATURE OF NOTICE		
TYPE OF SUBMISSION	TYPE OF ACTION		
✓ Notice of Intent		(Start/Resume) Water Shut-Off Well Integrity	

Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof if the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

New Construction

Plug and Abandon

☐ Plug Back

- 1. Set CIBP @ 3120'-Put 25sx plug at top of BP.
- 2. 2. Set 35sx plug from 1600' to 1500'-Tag @ 1500'
- 3. Set 25sx plug from 440'-340'-Tag at 340'.
- 4. Perf and squeeze. Circulate @ 338' (csg shoe) with 100' left in csg.

Casing Repair

Change Plans

_ Convert to Injection

5. Spot 60' plug to surface.

__ Subsequent Report

Final Abandonment Notice

6. Verify cement in all annulus and seal well.

SEE ATTACHED FOR CONDITIONS OF APPROVAL

Recomplete

Water Disposal

Temporarily Abandon

RECEIVED

MAR 0 3 2010 HOBBSUCD

RECLAMATION PROCEDURE ATTACHED

14 Thereby certify that the foregoing is true and correct Name (Printed/Typed)	ŀ		
Bob Howell	Title Western	District Manager	
Signature Bob Lowell	Date	02/09/2010	
THIS SPACE FOR FEE	DERAL OR STATI	E OFFICE UPPROVED	
Approved by Dull Land	G422/01 title	Date	
Conditions of approval, if any are attached. Approval of this notice does certify that the applicant holds legal or equitable title to those rights in the which would entitle the applicant to conduct operations thereon.	not warrant or subject lease Office	MAR 2 2010 s/ Dustin Winkler	21.
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crim States any lalse fictitious or fraudulent statements or representations as to	ne for any person knowingly any matter within its jurisd	ind BUREAU OF LAND MANAGEME	igency of the Uni
(Instructions on page 7)		CHINCODAD FIELD OFFICE	