UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an 2 8 2010 abandoned well. Use form 3160-3 (APD) for such proposals. HOBBES OCD						
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an 2 8 2010 abandoned well. Use form 3160-3 (APD) for such proposals						
Do not use this form for proposals to drill or to re-enter an 2 8 2010 abandoned well. Use form 3160-3 (APD) for such proposals						
abandoned well. Use form 31b0-3 (APD) for such proposals.						
	nd/or No.					
SUBMIT IN TRIPLICATE - Other instructions on reverse side.						
1. Type of Well 8. Well Name and No. ANGLEY DEEP 1						
	9. API Well No					
CHESAPEAKE OPERATING, INC. / E-Mail: linda.good@chk.com 30-025-25699	30-025-25699					
3a. Address3b. Phone No. (include area code)10. Field and Pool, or ExploratoryP.O. BOX 18496Ph: 405-935-4275LANGLIE						
OKLAHOMA CITY, OK 73154-0496	Strawn					
4 Location of Well (Footage, Sec., T., R, M., or Survey Description) 11. County or Parish, and State						
Sec 28 T22S R36E NENW 990FNL 2310FWL / LEA COUNTY, NM /	LEA COUNTY, NM					
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	<u></u>					
TYPE OF SUBMISSION TYPE OF ACTION `						
Notice of Intent						
Subsequent Report Casing Repair New Construction Recomplete	itegrity					
□ Final Abandonment Notice □ Change Plans □ Plug and Abandon ☑ Temporarily Abandon □ Convert to Injection □ Plug Back □ Water Disposal						
13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration	n thereof					
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers a Attach the Bond under which the work will be performed or provide the Bond No on file with BLM/BIA. Required subsequent reports shall be filed within a following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed only after all requirements, including reclamation, have been completed, and the operation determined that the site is ready for final inspection.)	nd zones 0 days led once					
ATTENTION: DUNCAN WHITLOCK Duncan, can we get a quick approval?						
From 11/3/2008 until 12/30/2008 Chesapeake spent \$1,000,000 trying to recover a lost ESP and tubing. At the end of the fishing operation, the top of the tubing is estimated to be at 12,150' and the top of the electric cable is at 11,100'. See Sundry Notice dated 9/24/2008.						
Chesapeake, respectfully, requesting that the well be TA'd with a SHRP while the wellbore is evaluated for any remaining potential.						
Procedure:						
1. ND WH/NU BOP. SEE ATTACHED FOR						
CONDITIONS OF APPROVAL SEE ATTACHED E-mail From Fin	~					
14. Thereby certify that the foregoing is true and correct	nell					
Electronic Submission #84753 verified by the BLM Well Information System For CHESAPEAKE OPERATING, INC., sent to the Hobbs						
Name (Printed/Typed) LINDA GOOD Title SR. REGULATORY COMPLIANCE SPEC	<u></u>					
Signature (Electronic Submission) Date 04/14/2010						
THIS SPACE FOR FEDERAL OR STATE OFFICE USE						
Approved By Shi W Liter G G Jaaling Title LIET	la la					
Approved By 9, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1,						
which would entitle the applicant holds legal or equitable title to those rights in the subject lease of the subje						
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the	United					
States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.						

** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED **

.

١

Additional data for EC transaction #84753 that would not fit on the form

32. Additional remarks, continued

* 2. Rig up wireline co. RIH w/gauge ring and junk basked to 11,075'. Set 7" CIBP @ 10,075' and dump 35' of cement on top of the GBP.
3. Pressure test casing to 500 psi with chart recorder.
4. ND BOP/NU WH.

Wellbore Schematic Attached.

(CHK PN 891473)

-2

* Squeeze cement Below CICR to perts + Place 10st. ON Top Asper ATTACHER COA'S





BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.

् **१**

~

a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging.

b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes with a 10% allowable leakoff.

c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.

d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.

e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.

3. Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned.

Wells that successfully pass the casing integrity test may be approved for Temporary Abandonment (TA) status provided that the operator:

- 1. **Submits a subsequent Sundry Notice** (Form 3160-5) requesting TA approval <u>with well bore</u> <u>diagram</u> with all perforations and CIBP's and Cement retainers and tops of cement on each.
- 2. Describes the temporary abandonment procedure.
- 3. Attaches a clear copy or the original of the pressure test chart.
- 4. Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

Langley Deep Well #1. Well may be approved to be TA/SI for a period of 90 days until July 15, 2010 after successful MIT and subsequent report with well bore diagram is submitted. This will be the last and only TA/SI approval. Well must be P&A or plans to return to beneficial use submitted by July 15, 2010. RIH to 11,075' set 7" cement retainer, squeeze cement below retainer to perfs. at 12,386'-12,525', pull out of retainer place 10 sacks cement on top. Pressure test casing as per requirements. Contact BLM to witness placement of retainer, cement and MIT test.



Linda Good <linda.good@chk.com> 04/21/2010 05:55 AM To "Duncan Whitlock (duncan_whitlock@nm.blm.gov)" <duncan_whitlock@nm.blm.gov> cc Jeff Finnell <jeff.finnell@chk.com>

bcc

Subject FW: Langley Deep 1 - Plug back procedure

Hi Duncan,

Please see Jeff's email below with the changes you requested for the Sundry Notice dated 4/14/2010.

Thank you,

	-	 	
Linda Good			
Sr. Regulatory Compliance Specialist		 	
Southern Division - Permian North			
Chesapeake Energy Corporation			
Bldg. 11, #451			
Office: (405) 935-4275			
Fax: (405) 849-4275			
E-mail: linda.good@chk.com			

From: Jeff Finnell Sent: Tuesday, April 20, 2010 5:10 PM To: Linda Good Subject: Langley Deep 1 - Plug back procedure

Linda,

Please pass this procedure on to the BLM:

1. MIRU workover rig. ND WH/NU BOP.

2. POH w/ 16 jts of tubing left in well for kill string.

3. RIH w/ 7" cement retainer on 2 7/8" tubing. Set retainer at 11,075' just above fish. Shear off of retainer, sting back into it and establish injection rate.

4. RU cement co. Pump 250 sxs cement into retainer to fill up casing from retainer to bottom perf. Pull out of retainer and spot 10 sxs of cement on top of retainer. POH w/ tubing.

5. Run MIT test on well with chart recorder.

6. ND BOP/NU WH. Rig down workover rig. TA well.

Jeff Finnell, P.E. Sr. Asset Manager Chesapeake Energy Corporation New Phone: 405-935-4347 New e-mail: jeff.finnell@chk.com