

Submit 3 Copies To Appropriate District Office  
**District I**  
1625 N. French Dr., Hobbs, NM 87240  
**District II**  
811 South First, Artesia, NM 87210  
**District III**  
1000 Rio Brazos Rd., Aztec, NM 87410  
**District IV**  
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
2040 South Pacheco  
Santa Fe, NM 87505

Form C-103  
Revised March 25, 1999


<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-36226
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/> Disposal		5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
2. Name of Operator Xeric Oil & Gas Corporation		6. State Oil & Gas Lease No.
3. Address of Operator P. O. Box 352 Midland, TX 79702		7. Lease Name or Unit Agreement Name: Howse
4. Well Location Unit Letter <u>L</u> : 1980 feet from the <u>South</u> line and 330 feet from the <u>West</u> line Section <u>17</u> Township <u>20S</u> Range <u>39E</u> NMPM Lea County		8. Well No. <u>1</u>
10. Elevation (Show whether DR, RKB, RT, GR, etc.) GR 3537		9. Pool name or Wildcat <u>SWD Howse</u> , San Andres

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
<b>NOTICE OF INTENTION TO:</b> PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/> OTHER: <input type="checkbox"/>	<b>SUBSEQUENT REPORT OF:</b> REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER: <u>FRAC</u> <input checked="" type="checkbox"/>

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1/27/04 POOH W/PKR & TBG. RIH W/MODEL R PKR + TBG & SET @ 4865'. ACID FRAC W/5000 GALS 20% XLINK ACID. SWION TO LET GEL BREAK & ACID SPEND.

1/28/04 BLEED OFF PRESSURE. RELEASE MODEL R PKR & POH W/TBG; RIH W/PLAS<sup>5</sup>IC COATED A<sup>5</sup> 1 PKR + 134 JTS TBG TO A SETTING DEPTH OF 4285'. FLANGE UP WELLHEAD. RD PULLING UNIT & RETURN TO SWD INJECTION.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Angie Crawford TITLE Production Analyst DATE 1/29/04  
Type or print name Angie Crawford Telephone No. 432-683-3171  
(This space for State use)

APPROVED BY Chris Williams TITLE OC DISTRICT SUPERVISOR/GENERAL MANAGER DATE FEB 2 2004  
Conditions of approval, if any: