Form 3160-5 February 2005)

Approved by Conditions of approval, if any

UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APROVED OMB NO. 1004-0135 EXPIRES: March 31, 2007

BUREAU	JOF LAND MANAGEMENT		, ay		Iviation 61, 2007
SUNDRY NOTICES AND REPORTS ON WELLS HOBBSOCD				5. Lease Serial No.	
Do not use this form for proposals to drill or to re-enter an				NMNM-98189 6. If Indian, Allottee or Tribe Name	
abandoned well. Use	e Form 3160-3 (APD) for such	proposals		o. If indian, Anottee or i	Tibe Ivanic
SL	JBMIT IN TRIPLICATE		1	- 11 17 - 01 1	-t Name and No
		<u></u>		7. Unit or CA Agreeme	at Name and No.
ia. Type of Well 🔃 Oil Well 🔲 Ga	s Well 🔲 Other			8 Well Name and No.	
				- 1	
2. Name of Operator				Nana 30 Fed 3	
DEVON ENERGY PRODUCTION COMPANY, LP					05 20500
3. Address and Telephone No.				30-025-39580	
20 North Broadway, Oklahoma City, OK 73102-8260 405-552-8198				10. Field and Pool, or Exploratory	
Location of Well (Report location clearly and in accordance with Federal requirements)*				######################################	
2040 FSL 1980 FWL				11. County or Parish	
K 30 18S 32E				Lea	NM NM
12. CHECK	K APPROPRIATE BOX(s) TO	INDICATE NATURE OF N	IOTICE, REPOR	T, OR OTHER DATA	
TYPE OS SUBMISSION		TYF	PE OF ACTION		
	Acidize	Deepen	Production	n (Start/Resume)	Water Shut-Off
Notice of Intent	Alter Casing	Fracture Treat	Reclamation		Well Integrity
✓ Subsequent Report	Casing Repair	New Construction	Recomplet		Other Completion
Final Abandonment Notice	Change Plans	Plug and Abandon		ily Abandon	Report
13 Describe Proposed or Completed (Convert to Injection	Plug Back	Water Dis		
subsequent reports shall be filed within 3 new interval, a Form 3160-4 shall be filed eclamation, have been completed, and to 2/25/2010 MIRU. NU BOP and test to 1 casing again to 1500 psi - held. POOH v 3/01/2010 RIH with bit and scraper and 3/02/2010 MIRU wireline. RIH and perform 3/3/2010 RU and frac lower bone spring RIH and set composite plut at 8255'. Test	d once testing has been complete operator has determined the solution of the operator has determined the solution of the operator has determined the solution of the operator	at the site is ready for final 1500 psi for 30 minutes - hollars. OOH with tubing, bit and signee phasing. POOH with	notices snail be inspection) neld. Drilled out craper. ND BOF wireline.	cement and DV tool. Co and NU frac valve.	Circulate hole clean. Test
Springs from 8104'-8178' with 3,017# 10' 3/5/2010 ND frac valve and NU BOP. 3/6/2010 Circulate 2% KCI, cleaned out 3/9/2010 RIH with production tubing and 3/11/2010 RIH with rods and pump. Hu 3/12/2010 RDMO. Turned well over to p	0 Mesh White, 75,953# 20/40 \ and drilled out composite plug. d set at 8456'. ND BOP and N ng well on production.	White and 18,979# Siber F . Circulate hole and POOF	200 16/30. RD		
14. Thereby certify that the foregoing is Signed This space for Federal or State Office u	Name Title	Senior Staff Engineerin	g Technician	Date	4/5/2010
Approved by	Title	PETPOLEUM ENVA		Date MAY	0 4 2019

The 10 C Section 1001, makes it a crime for any person knowingly and willouly within its jurisdiction

*See Instruction on Reverse Side

