

Submit 1 Copy To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
October 13, 2009

OIL CONSERVATION DIVISION

RECEIVED

220 South St. Francis Dr.
Santa Fe, NM 87505

MAY 12 2010

WELL API NO. 30-025-10899
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No. 16706
7. Lease Name or Unit Agreement Name R. W. COWDEN "A" WN
8. Well Number 001
9. OGRID Number 142624
10. Pool name or Wildcat JALMAT TANSILL YATES 7 RIVERS

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☒ Other ☐

2. Name of Operator
ROCA PRODUCTION, INC.

3. Address of Operator
P.O. BOX 10139 MIDLAND, TX 79702

4. Well Location

Unit Letter _____ P: 330' feet from the SOUTH line and 330 feet from the EAST line
Section 30 Township 23S Range 37E NMPM County LEA

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3323' GR

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. SET CIBP @ 2780' W/35' CMT ON TOP
2. RIH - TAG CIBP @ 3225' - CAP W/35' CMT. - CIRC. MLF
3. RIH - SPOT 100' CMT @ 3024 - 2924 WOC - TAG
4. CUT 7" CSG @ 2820' PULL CSG -
5. RIH TO 2870 SPOT 50 SX CMT - (STUB - 9 5/8 CSG SHOE) WOC - TAG
6. RIH PERF @ 1325' - SQ 50 SX CMT - WOC - TAG
7. RIH PERF @ 400' - SQ 50 SX CMT - WOC - TAG
8. RIH PERF @ 275' - SQ 50 SX CMT - WOC - TAG
9. RIH PERF @ 60' - SQ 50 SX CMT - WOC - TAG
- 6.) INSTALL P&A MARKER-CLEAN UP LOCATION AS PER REGULATED

The Oil Conservation Division **Must be notified**
24 hours prior to the beginning of plugging operations

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mark Hoskins TITLE _____ AGENT _____ DATE MAY 10, 2010

Type or print name MARK HOSKINS E-mail address: mark@mayomarrs.net PHONE: 432-586-2844

For State Use Only

APPROVED BY: [Signature] TITLE STAFF ASST DATE 5-13-10

Conditions of Approval (if any):

R W Cowden "A" WN # 1

Spud 1937
 Western Gas Company
 330' FSL + 330' FEL
 Sec 30 T23S R37E
 Lea Co. New Mexico
 API # 30-025-10899

