## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE **OIL CONSERVATION DIVISION** 1 220 South St. Francis Dr. WELL API NO. DISTRICT I 1625 N French Dr , Hobbs, NM 88240 30-025-07569 Santa Fe, NM 87505 5. Indicate Type of Lease DISTRICT II STATE STATE FEE 1301 W. Grand Ave, Artesia, NM 88210 6 State Oil & Gas Lease No. DISTRICT III 1000 Rio Brazos Rd, Aztec, NM 87410 7. Lease Name or Unit Agreement Name SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A South Hobbs(G/SA) Unit DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.) 8 Well No. 1. Type of Well: Oil Well X Gas Well 9. OGRID No. 2 Name of Operator 157984 Occidental Permian Ltd. 10 Pool name or Wildcat Hobbs (G/SA) 3. Address of Operator HCR 1 Box 90 Denver City, TX 79323 4. Well Location Unit Letter L 1980 Feet From The Feet From The Line South 560 West NMPM Section 18-S Range County 11. Elevation (Show whether DF, RKB, RT GR, etc.) 3635' KB Pit or Below-grade Tank Application or Closure Distance from nearest fresh water well

Distance from nearest surface water Pit Type Depth of Ground Water Pit Liner Thickness Below-Grade Tank: Volume bbls; Construction Material 12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG & ABANDONMENT PULL OR ALTER CASING CASING TEST AND CEMENT JOB Multiple Completion OTHER: OTHER: Temporarily Abandon Well/TA Status request 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103, For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 1. RUPU & RU. 2. RU wireline & perforate tubing @3700'. RD wireline. 3. ND wellhead/NU BOP. 4. POOH and lay down ESP equipment. 5. RIH w/bit to 4169'. POOH w/bit. 6. RIH w/CIBP set @4000'. Cap w/40 feet of cement. Tag TOC @3960'. 7. ND BOP/NU TA wellhead. 8. Test casing to 560 PSI and chart for the NMOCD. Mark Whittaker w/NMOCD on location for test. 9. RDPU & RU. Clean location. Well it temporarily abandoned. This Approval of Temporary RUPU 04/12/2010 RDPU 04/15/2010 Abandonment Expires \_\_\_ I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or or an (attached) alternative OCD-approved closed according to NMOCD guidelines , a general permit plan **SIGNATURE** ገ ያወን TITLE Administrative Associate DATE 05/12/2010 TYPE OR PRINT NAME TELEPHONE NO Johnson E-mail address: mendy johnson@oxy.com Mend 806-592-6280 For State Use Only START NOR TITLE APPROVED BY CONDITIONS OF APPROVAL IF

