

Submit 1 Copy To Appropriate District
Office

State of New Mexico
Energy, Minerals and Natural Resources

Form C-10
October 13, 2009

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Ave., Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

RECEIVED
CONSERVATION DIVISION

MAY 17 2010
1220 South St. Francis Dr.
Santa Fe, NM 87505

HOBBSD

WELL API NO.

30-025-26893

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

L-1080

7. Lease Name or Unit Agreement Name
Sawyer 4 State

8. Well Number 002

9. OGRID Number

266091

10. Pool name or Wildcat
Sawyer-W [SA]

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☐ Other SWD

2. Name of Operator

VPR Operating LLC

3. Address of Operator

1406 Camp Craft Suite 106, Austin, Texas 78746

4. Well Location

Unit Letter A : 660 feet from the North line and 660 feet from the

East line

4 Section

10S

Township

37E

Range

NMPM

County Le

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING C/SING
COMMENCE DRILLING OPNS. ☐ P AND A
CASING/CEMENT JOB ☐

OTHER:

OTHER:

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of
proposed completion or recompletion.

VPR Operating LLC plugged and abandoned this well 05/11/10 with the following procedure:

- 1] Set CIBP @ 4850'. Cap w/ 35' cement.
- 2] Circulate hole with mud.
- 3] Spot 25 sx Class C @ 3250'.
- 4] Spot 25 sx Class C @ 2370'.
- 5] Spot 25 sx Class C 597'- 350'.
- 6] WOC.
- 7] Tag plug @ 180'.
- 8] Spot 25 sx Class C plug @ surface.

9] Cut off casing head.

10] Install NMOCD approved dry hole marker.

11] Clean and level location, removing
and tubing.

Approved for plugging of well bore only.
Liability under bond is retained pending receipt
of C-103 (Subsequent Report of Well Plugging)
which may be found at OCD Web Page under
Forms, www.emnrd.state.nm.us/oed.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE

Agent

DATE

Type or print name M.Y. Merchant

e-mail address:

mymench@penrocoil.com

PHONE: 575-492-1236

For State Use Only

APPROVED BY:

TITLE

DATE

Conditions of Approval (if any):