## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE RECEIVED CONSERVATION DIVISION	Revised 5-27-2004
DISTRICT I 1220 South St. Francis Dr	WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 MAY 1 4 ZUIU Santa Fe, NM 87505	30-025-28944 <b>/</b> 5 Indicate Type of Lease <b>/</b>
DISTRICT II  1301 W. Grand Ave, Artesia, NM 88210 HOBBSOCD	STATE FEE X
DISTRICT III	6. State Oil & Gas Lease No.
1000 Rio Brazos Rd, Aztec, NM 87410	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	North Hobbs (G/SA) Unit
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)	Section 32
1. Type of Well:	8. Well No. 223
Oil Well Gas Well Other Injector  2. Name of Operator	9. OGRID No. 157984
Occidental Permian Ltd.	). Odkib No. 13/984
3. Address of Operator	10. Pool name or Wildcat Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX 79323	
4. Well Location	
Unit Letter E : 2630 Feet From The North 1420 Feet	From The West Line
Section 32 Township 18-S Range 38-E	, NMPM Lea County
11. Elevation (Show whether DF, RKB, RT GR, etc.)	
3634' GL	
Pit or Below-grade Tank Application or Closure	
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water	
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material	
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPN	NS PLUG & ABANDONMENT
PULL OR ALTER CASING	T JOB
OTHER. Repair Casing Leak/Perforate/Acid Treat X OTHER:	
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any	
proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.	
1. Kill well. POOH w/injection equipment.	
<ol> <li>Clean out to PBTD.</li> <li>Perforate hole at 2 JSPF.</li> </ol>	
4. Acid treat well w/2310 gal of 15% NEFE acid.	
5. Perform scale squeeze.	
6 RIH w/injection equipment.	
<ul><li>7. Test casing and chart for the NMOCD.</li><li>8. Return well to injection.</li></ul>	
o. recent them to injection	
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be	
constructed or	
closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan	
SIGNATURE TITLE Administrative Associate DATE 05/12/2010	
TYPE OR PRINT NAME Mendy A. Johnson E-mail address: mendy johnson@oxy.com	TELEPHONE NO. 806-592-6280
For State Use Only	300-392-0200
APPROVED BY TITLE	
CONDITIONS OF APPROVAL IF ANY	F MAR DATE 5-17-10