
Submit 3 Copies To Appropriate District Office	State of New Mexico		Form C-103
	Energy, Minerals and Natural Resources		June 19, 2008
1625 N French Dr , Hobbs, NM SPACE CONTROL OF THE PROPERTY OF			WELL API NO. 30-025-22168
District I 1625 N French Dr , Hobbs, NM 8210 District II 1301 W Grand Ave , Artesia, NM 88210 District III District III 1301 W Grand Ave , Artesia, NM 88210 District III MAY 1.4 2015 1220 South St. Francis Dr			5. Indicate Type of Lease
1000 Pro Proved Pd. Acted NM 97410		1015 251.	STATE FEE
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505 87505			6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)			R.E. COLE NCT-A
1. Type of Well: Oil Well Gas Well Other			8. Well Number 9
2. Name of Operator			9. OGRID Number 4323
CHEVRON /			10. Pool name or Wildcat
3. Address of Operator 15 SMITH ROAD, MIDLAND, TEXAS 79705			BLINEBRY
4. Well Location			
Unit Letter N: 1075 feet from the SOUTH line and 2395 feet from the WEST line			
Section 16 Township 22-S Range 37-E NMPM County LEA			
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3400' GL			
		· · · · · · · · · · · · · · · · · · ·	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK			
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI			
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐ CASING/CEMENT JOB ☐ DOWNHOLE COMMINGLE ☐			
DOWNHOLE COMMINGLE	•		
OTHER:			DRARILY ABANDON WITH CHART
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date			
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion			
or recompletion. 3-04-10: MIRU.			
3-05-10: REL PKR.			
3-06-10: SET CIBP @ 6300. DUMP 35' CMT ON TOP. PU PKR & TBG TO 5371.			
3-07-10: SET PKR @ 5629. PMP PKR FLUID DN TBG. COULD NOT GET TEST ON CIBP @ 6300. COULD NOT REL PKR. PMP			
60 BBLS DN BS. REL PKR. <u>SET PKR @ 5360.</u> LOAD TEST BS TO 500#. OK.			
5-05-10; MIRU PULLING UNIT & PUMP TRUCK. TBG ON VAC. CSG-40 PSI. BLED CSG DN. PMP 10 BBLS DN CSG.			
STARTED TO LOAD UP. PRESS UP TO 300 PSI. TIGHTEN FLANGE TO WH. NOTIFY NMOCD WO WITNESS TEST. GOT			
VERBAL APPROVAL TO RUN CHART. RAN CHART & TESTED TO 520 PSI FOR 35 MINS. GOOD.			
(ORIGINAL CHART & COPY OF CHART ATTACHED).			
WELL IS TEMPORARILY ABANDONED.			
WELL IS TEMPORARILY ABANDONED. This Approval of Temporary 5-2011 Abandonment Expires			
	Abandonme	ill Exhiles ====	the state of the s
			,
Spud Date:	Rig Release Da	ate:	
			'
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE OF 13-2010 DATE 05-13-2010			
Type or print name DENISE PINKERTON E-mail address: <u>leakejd@chevron.com</u> PHONE: 432-687-7375			
For State Use Only			
APPROVED BY: Starphen TITLE STATE MATE DATE 5-18-10			
Conditions of Approval (if any):			



Well, RECole A #9 Reservoir Blinebry/Drinkard

