

Submit 1 Copy To Appropriate District
Office
District I
1625 N French Dr, Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88202
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr, Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
October 13, 2009

RECEIVED MAY 21 2010 HOBBSOCD		OIL CONSERVATION DIVISION 1220 South St. Francis Dr. Santa Fe, NM 87505
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS) 1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other <input type="checkbox"/>		WELL API NO. 30-025-21212
2. Name of Operator SOUTHWEST ROYALTIES, INC.		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
3. Address of Operator 6 DESTA DRIVE, STE 2100, MIDLAND, TEXAS 79705		6. State Oil & Gas Lease No. NM 058102
4. Well Location Unit Letter <u>F</u> : <u>1840</u> feet from the <u>N</u> line and <u>1840</u> feet from the <u>W</u> line Section <u>28</u> Township <u>9S</u> Range <u>33E</u> NMPM LEA County		7. Lease Name or Unit Agreement Name Flying M San Andres Unit
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4340' GL KB (10') 4350'		8. Well Number 25-2
		9. OGRID Number 21355
		10. Pool name or Wildcat Flying M San Andres 024620

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☒
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Plug and Abandon Well 5/4/10. Prepare to reclaim location.

- * All pits and rat holes will be remediated, filled or leveled.
- * Steel marker over plugged well bore with permanent identification.
- * Location leveled and all junk, equipment and anchors removed.
- * All environmental concerns addressed by OCD guidelines.

File a FINAL ABANDONMENT REQUEST FOR FINAL INSPECTION.

Spud Date: 04/25/65

Rig Release Date: 05/07/65

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE Operations Assistant DATE 5/19/10

Type or print name _____ E-mail address: dhoward@claytonwilliams.com PHONE: 432/688-3267
For State Use Only

APPROVED BY: [Signature] TITLE STAFF MGR DATE 5-24-10
Conditions of Approval (if any): _____