Form 3160-5 (August 2007)

(Instructions on page 2)

UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No 1004-0137

Expires: July 31, 2010

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to be compared well. Her Form 2160 2 (1997) abandoned well. Use Form 3160-3 (APD) for such proposals.

5. Lease Serial No. NM -077090 6. If Indian, Allottee or Tribe Name

SUBMI	IT IN TRIPLICATE – Other instr	7. If Unit of CA/Agree	7. If Unit of CA/Agreement, Name and/or No.			
1. Type of Well	/		0 W-11 V 1 V			
Oil Well Gas Well Other			Falcon Federal No.	8. Well Name and No. Falcon Federal No. 1		
2 Name of Operator / OXY USA Inc.			9. API Well No. 30-025-32190	7		
3a. Address PO Box 4294 Houston, TX 77210	Phone No. (include area code)	10. Field and Pool or Exploratory Area				
713-		-366-5303				
4. Location of Well (Footage, Sec., T.,R.,M.,/or Survey Description) 1980 FSL & 660 FEL Sec 1 T24S R34E Unit "I"			· '	11. Country or Parish, State Lea County, NM		
	Y			-		
	CK THE APPROPRIATE BOX(ES			ER DATA		
TYPE OF SUBMISSION			TYPE OF ACTION			
Notice of Intent Subsequent Report	Acidize Alter Casing	☐ Deepen ✓ Fracture Treat	<u> </u>	Water Shut-Off		
	Casing Repair	New Construction	Reclamation Recomplete			
	Change Plans	Plug and Abandon	Temporarily Abandon	Other		
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal			
testing has been completed. Final determined that the site is ready for 1. MIRU POH w/tbg, rods and pum 2. Test tubing for leak, RIH with tbg, 3. Pump fluid off and test zone for a 4. Return to production.	r final inspection.) p. rods, pump.			completed and the operator has		
If current open interval is not product 1. MIRU POH w/ tbg, rods and pum 2. RIH w/ bit and clean out to PBTD 3. Install casing patch from approx 84. Perforate Brushy Canyon zone 865. Stimulate 6. CO to 9000' +/-7. RIH w/tbg, rods, pump and test	@ 9000' @ 9000'		ATTACHED FO	- -		
If recompletion in the Delaware is un			Shale component of the Bon	e Spring formation.		
14. I hereby certify that the foregoing is tr	ie and correct. Name (Printed/Types					
Elizabeth S. Bush-Ivie, P.E.		Title Regulatory Te	eam Leader			
Signature Schulle	& Bul-Die 1	Date 05/14/2010	APPR	OVED		
	THIS SPACE FOR	FEDERAL OR STATE	OFFICE USE			
Approved by		PET DUE TITLE	CHANCE H MAY	1 8 2010 MAY 2 4 2016		
Conditions of approval, if any, are attached, nat the applicant holds legal or equitable tit nutle the applicant to conduct operations the	le to those rights in the subject lease nereon.	arrant or certify which would Office	5 PETROLEU	W. INGRAM M ENGINEER		
Fitle 18 U.S.C. Section 1001 and Title 43 U	S C. Section 1212, make it a crime	for any person knowingly and will	fully to make to any department	or agency of the United States any false,		

Falcon Federal No. 1 30-025-32190 OXY USA Inc. May 18, 2010 Conditions of Approval

- 1. Surface disturbance beyond the existing pad must have prior approval.
- 2. Closed loop system required.
- 3. Operator to have H2S monitoring equipment on location as H2S has been reported.
- 4. A minimum of a 3M BOP is required and must be tested. All blowout preventer (BOP) and related equipment (BOPE) shall comply with well control requirements as described in Onshore Oil and Gas Order No. 2 and API RP 53 Sec. 17.
- 5. Prior to final plugging of well, operator shall clean-out to top of Wolfcamp and set a plug across the top of the Wolfcamp formation at 11631 feet. Plug to be Class H and must be 220' in length.

WWI 051810