Submit 1 Copy To Appropriate District Office <u>District 1</u>	State of New Me			Form C-103	
Energy, Minerals and Natural Resources 1625 N French Dr., Hobbs, NM 88240 District II 1301 W. Grand Ave., Artesia, NM 88210 Descript III 1301 W. Grand Ave., Artesia, NM 88210			WELL API NO.		
1301 W. Grand Ave., Artesia, NM 88270 CONSERVATION DIVISION			30-025-37918		
1000 Rio Brazos Rd Aziec NM 874 MAY 2.5 2010 220 South St. Francis Dr.			5. Indicate Type of Lease STATE FEE X		
District IV 1220 S St. Francis Dr., Santa Fe, NHOBBSOCD 87505			6. State Oil & Gas Lease No.		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name MONUMENT DISPOSAL (35738)		
1. Type of Well: Oil Well Gas Well Other SWD			8. Well Number #1		
2. Name of Operator MONUMNET DISPOSAL INC			9. OGRID Number 242044 /		
3. Address of Operator			10. Pool name or Wildcat		
1314 BRITTANY, HOBBS, NM 88240 4. Well Location			SWD; SAN ANDRES		
Unit Letter H:	2582 feet from the N	line and	900 6 6 4	T	
Section 35	Township 19S Range	line and ge 36E	809 feet from the NMPM LEA Co		
	11. Elevation (Show whether DR, K		NMPM LEA Co	ounty 🗸	
12 Charle As	proprieto Dou to Indiana N. a	CNI			
	ppropriate Box to Indicate Nat	ure of Notice,	Report or Other Data	a	
TEMPORARILY ABANDON	PLUG AND ABANDON ☐ FCHANGE PLANS ☐ C	SUBS REMEDIAL WORK COMMENCE DRIL CASING/CEMENT	LING OPNS. PAI	RT OF: ERING CASING [] ND A [X]	
OTHER:					
13. Describe proposed or complet	ed operations. (Clearly state all per). SEE RULE 19.15.7.14 NMAC.	OTHER. tinent details, and For Multiple Com	give pertinent dates, inc pletions: Attach wellbo	cluding estimated date re diagram of	
2. Test plug 1000 PSI PKR set at 4268			Note: All cement class C		
3. Discovered CSG leak 3952-4100					
4 RIH set cement retainer at 3922 squeeze with 160 sxs at 2200 PSI POOH					
5 RIH to 3922 circulate 160 BBL 9.5 gel brine					
6 Pump 25 sxs at 3922, pump 25 S	XS at 2860, pull up hole				
7. WOC 3 hours RIH tag cement at					
8 Pump 25 sxs at 2397, pump 25 s.	ks at 1150, pump 65 sxs at 419, circulate of	cement to surface, PC	OOH shut blind rams, pressu	re test to 500 PS1 for one hor	ur lost 50
PSI		ŕ	-, p		, 1001 00
9 Rig down BOP fill CSG to surfac	e with cement, cut well head off set dry ho	ole marker; clean loc	ation		
Spud Date:	Rig Release Date:	5-25-10			
I hereby certify that the information abo	ve is true and complete to the best o	f my knowledge a	nd belief.		
SIGNATURE M COLO	1	GR	DATE	5-25-10	
Type or print name Ken Marsh	E-mail address:		DLIONE.		
For State Use Only	7		rhune:	575-631-6979	
APPROVED BY: Conditions of Approval (if apy)	TITLE STA	AFF MG	DATE_S	-26-10	
	•				